Markup Summary

dsdlaforce (8)



Subject: Callout Page Label: 7 Lock: Locked Author: dsdlaforce

Construction Drawings modified to match report. C&G Stays as is

Contradicts the construction plans. Requirement is to tie the proposed sidewalk to the existing sidewalk. To do this the existing C&G will have to be removed/replace. Analysis will have to be conducted to determine the appropriate C&G configuration.



Subject: Callout Page Label: 10 Lock: Locked Author: dsdlaforce

The swale from the Bradley Rd. Storm discharge is exisitng; it will be modified as part of the grading so the word proposed was added

State in the narrative on how this is conveyed. Is it via an existing or proposed channel? Unresolved. Review 2: Identify if it's existing or proposed swale.

a pard (Winfardi Garkh Dourine Poud 44) was belt under Markon Mindas (Marko Wingstrowd by E Paro Carney on Markon Mindas (Marko Windstrom Mindas (Marko Windstrom Marko Windstrom Markon) (Marko Windstrom Markon) (Marko Windstrom Markon) (Marko Windstrom Markon) (Markon) (M

Subject: Callout Page Label: 12 Lock: Locked Author: dsdlaforce

The no. 1 was added back in.

The number "1" was deleted.



Subject: Cloud+ Page Label: 23 Lock: Locked Author: dsdlaforce

Extent of 100-year flooding is shown and remains in the Grinnell Boulevard r.o.w. Narrative revised to describe. Design carries flow.

Delineate the spread of the 100yr runoff. Unresolved.

Review 2: Show this on both sides for the full length along Grinnel Blvd. Depending on extent, additional drainage easements and/or improvements may be required.

Update the narrative for DP-K (pg 10) by elaborating on the findings/recommendations regarding this swale. Per ECM Section 3.3.4 the minimum freeboard shall be 0.5 foot. Based on the 100yr spread shown, the existing swale has insufficient capacity. Revise the design accordingly and update the DP 42a channel analysis accordingly.



Subject: Callout Page Label: 76 Lock: Locked Author: dsdlaforce

Revised to 1.2%

Review 2: The construction plans show a 1.2% slope. Revise to match.



Subject: Callout Page Label: 79 Lock: Locked Author: dsdlaforce

Calculations revised to reflect Manhole grate Review 2: This has been revised to a manhole grate. Update the inlet accordingly. The Type D grate has a greater opening than a manhole grate.



Subject: Callout Page Label: 80 Lock: Locked Author: dsdlaforce

Revised

Review 2: The construction plans show a 1% slope. Revise to match.



Subject: Callout Page Label: 81 Lock: Locked Author: dsdlaforce

Revised to reflect Manhole grate Review 2: This has been revised to a manhole grate. Update the inlet accordingly. The Type D grate has a greater opening than a manhole grate.