

RECEIVED

PLANNING DEPARTMENT

Job No 63790

January 17, 2003

Manitou Springs, CO 80829 1107 Manitou Avenue Jensen Realty

El Paso County, Colorado S-315, Crystal Park Subdivision Geologic Study Crystal Park Road

Gentlemen:

to be constructed on the above referenced site. the possible geologic concerns that may affect the performance of the proposed residential structure observation of the proposed building and septic field areas and provide our professional opinion on referenced address on January 15, 2003. The purpose of our site visit was to perform a visual At your request, personnel of RMG Engineers, Inc. have performed a site visit at the above

the soils underlying the site typically consist of a decomposed granite consisting of fine to coarse grained sand and gravel overlying granite bedrock of the Pikes Peak Granite Formation. Based upon our visual observations and a review of the geologic information provided for this area.

area consisted of decomposed granite and formational granite bedrock. was observed between the garage level and lowest (basement) level. Soils exposed in the excavated lowest level had been excavated to "rough" grade. An elevation difference of approximately 15 feet No significant drainage gullies were present in the proposed building area or septic system location. The house is to be placed on a steep slope. At the time of our site visit, the driveway, garage and Vegetation consists of dense scrub oak and a few scattered pine trees with moderate ground cover.

held to a minimum on this site revegetation/erosion mats placed as required. All excavation cuts and soil disturbance should be slopes be no steeper than a 3:1 (horizontal to vertical) in both the cut areas and any fill slopes. is also rapid and the potential for erosion can be high. It is our recommendation that long-term Erosion of the material can be high and some rip rap type of material may be required to prevent The permeability of the sand and gravel is generally considered high to very high. Surface runoff Revegetation of any disturbed areas should be performed as soon as possible with

S-315, Crystal Park Subdivision El Paso County, Colorado Crystal Park Road

additional reinforcing will likely be required to achieve the desired rigidity. The foundation must rest on native soil and should not rest on any uncontrolled fill material and it is important that the structure be designed with as much rigidity as possible. may be exerted on the structure due to its placement on the hillside. The slopes at this site are steep pressures and the structures should be designed as rigid as possible to resist additional pressures that considered moderate to high. The proposed structure should be designed to resist downslope creep is a concern at this site. The potential for downslope creep of the walkout trench at this site is Downslope creep, which is the accelerated movement of the surficial soils in the downslope direction Tie beams and

test performed by Colorato Edigineering. Care should be taken to terrace the absorption field in such a way as to prevent surface seepage of the effluent. Because of the 35% slope across the proposed septic field site, an engineered septic system will be required. It is anticipated that a shallow septic field will be placed at this site, due to the shallow percolation The septic system will be blaced on the moderate to steep lower portion at the north side of the lot. pit do

Based on our site observations, a rockfall hazard does not exist at this site

hesitate to call. I hope this provides the information you requested. 32060 STATE OF THE Should you have any questions, please do not

Cordially

Mark E. Clippinger

62060 mm.

MEC/slf

COLORADO GEOLOGICAL SURVEY

Division of Minerals and Geology

Denver, Colorado 80203 Phone: (303) 866-2611 FAX: (303) 866-2461 1313 Sherman Street, Room 715 Department of Natural Resources

April 14, 2003

NW17 T14S R67W

Bill Owens

Crystal Park Site 315

27 E. Vermijo

El Paso County Planning

Mr. Terry Rorick

Colorado Springs, CO 80903-2088

CGS Review No. EP-03-0045

Vicki Cowart State Geologist and Director

Ronald W. Cattany Division Director Greg E. Walcher Executive Director

Dear Mr. Rorick:

were included in the referral. Report prepared by Colorado Engineering & Geotechnical Group, Inc (November 2002) Geologic Study report prepared by RMG Engineers (January 2003) and a Percolation In response to your request I visited this site to review the plans for development. A

access drive. Future owners should be made aware that the costs associated with building on steep slopes can be substantial. be required in the foundation design. Additional retainage might be necessary for the by a geotechnical engineer for stability concerns. Tie-backs to the bedrock will probably envelope. The cuts for the building and the driveway should be designed and examined Slopes. The slopes at the site are steep, ranging up to 50 percent within the building

toundation walls. The house should be designed to resist increased lateral earth pressures. Features n include limited window and door space on the ground floor and increased width of Features might

reseeded as soon as possible. the downslope part of the site to prevent sediment loss. Disturbed areas should be The residuum of the Pike's Peak granite is very erodible. Silt fence should be installed at

including a swale or drain to capture water. design should consider a means to divert these flows, by crowning the driveway or could still produce nuisance flooding during periods of heavy precipitation. The site The only runoff that would affect the site will be what intersects the driveway, which hillside, and as such, runoff flows along the inside of the road rather than off the edge Drainage. Crystal Park Road lies above the site. The road is graded to slope into the

RECEIVED

APR 17 2003

percolation rate was 5.67 minutes per inch. subsurface soil to a depth of 19 ft was described as decomposed granite. The average sunlight to the leach field area. Bedrock was not encountered in the profile hole. The observation and the site map, there is no place that fits this criterion except by the road provided by Colorado Engineering states that slopes were 2 percent grade, but based on The area is in the trees and would have a northeast exposure, limiting the amount of percent, as scaled from the site map provided by Virginia Ownbey. The schematic ISDS. The topographic grade in the vicinity of the proposed leach field is about 35

the pit or field to prevent wastewater from exiting to the hillside. mostly at the entry point. carefully laid to achieve consistent flow throughout the field, rather than discharging design, based on the thick soil section. If a drain field is constructed, lines should be stability. Seepage pits, which are commonly used in Crystal Park, would be a possible can be graded and terraced, but this creates disturbance and possible concerns for slope acceptable performance when components are placed on an angle. The leach field site The chief limitation to ISDS is the slope of the site. It is more difficult to achieve Consideration should be given to lining the downslope part of

potential that the ISDS will release inadequately treated wastewater to the subsurface. that unless the native material is combined with a clay or graded sand mix, there is the health departments. The decomposed granite has little filtering capacity, which means The percolation rate is fast, although within prescribed limits set by the state and county

also necessary to achieve standards of performance, prevent inadequately treated minimize disturbance to the hillside. wastewater from discharging to the hillside or entering the groundwater system, and to engineering of the foundation to increase stability. Special design for the leach field is In summary, the chief concern at the site is the steep slopes, which will require

Please call me if there are any questions

Celia Gre

Geologis