

As a general comment, why was this the solution proposed? In our punchlist all we asked for was the gap at the top (in the horizontal plane) by covered up. The new plate/cover in the vertical plane (the yellow area below) was definitely not requested or necessary and will mess with the intended hydraulic functionality of the pond.

For future reference: this type of modification should have been sent to the County for review before the contractor was instructed to install it, to avoid misinterpretations of our punchlist items.

