

Materials Testing Forensic Civil/Planning

## PAVEMENT DESIGN REPORT

APPROVED Engineering Department

10/25/2022 7:42:57 AM
dsdnijkamp

EPC Planning & Community
Development Department

The Ridge at Lorson Ranch – Filing No. 3 El Paso County, Colorado

## PREPARED FOR:

Landhuis Company 212 N. Wahsatch Ave. Ste 301 Colorado Springs, CO

JOB NO. 186386-3

October 20, 2022

Respectfully Submitted,

Reviewed by,

RMG - Rocky Mountain Group

RMG - Rocky Mountain Group

Nathan Malefyt Staff Geologist

Tony Munger, P.E. Sr. Geotechnical Project Manager

SF Number 22-004

#### Note:

- Full depth asphalt paving is not allowed by El Paso County.

PCD File No. SF-22-007

## TABLE OF CONTENTS

GENERAL SITE AND PROJECT DESCTIPTION	3
Location	3
Existing Conditions	
Project Description	
FIELD INVESTIGATION AND SUBSURFACE CONDITIONS	3
Drilling	3
Subsurface Materials	
Groundwater	4
LABORATORY TESTING	4
Laboratory Testing	4
PAVEMENT DESIGN	
Street Classification – Urban Local	5
Pavement Thickness	5
Pavement Materials	6
Soil Mitigation	6
Subgrade Preparation	6
Surface Drainage	7
Subgrade Observations and Testing	7
CLOSING	7
FIGURES	
Site Vicinity Map	
Test Boring Location Plan/Pavement Recommendations	
Explanation of Test Boring Logs	3
Test Boring Logs	
Summary of Laboratory Test Results	11
Soil Classification Data	12-14
Denver Swell/Consolidation Test Results	15-17
Moisture-Density Relation Curve	18
California Bearing Ratio Test Results	19-20

### APPENDIX A

Design Chart for Flexible Pavements – Urban Local Roads

## GENERAL SITE AND PROJECT DESCRIPTION

#### Location

The Ridge at Lorson Ranch, Filing No. 3 is generally located in the southeastern portion of El Paso County, Colorado, east of the intersection of Fontaine Boulevard and Marksheffel Road. The location of the site is shown on the Site Vicinity Map, Figure 1.

### **Existing Conditions**

At the time of our field investigation, the proposed streets were close to grade and utility mains and services had been installed. Curb and gutter had not been installed.

#### **Project Description**

This Pavement Design Report was performed to determine the subsurface conditions present along the roadway alignments and to develop recommendations for the design and construction of the proposed flexible pavements.

The proposed streets included in this investigation are shown on Figures 2.1 and 2.2. The streets considered below are classified as Urban Local. The roads classified as Urban Local are Reagan Ridge Drive, Logans Ridge Drive, Rikers Ridge Lane, Cody Ridge Drive, Scrub Jay Trail, Broken Top Drive, Alpine Ridge Drive, and Walleye Drive.

# FIELD INVESTIGATION AND SUBSURFACE CONDITIONS

#### **Drilling**

The subsurface conditions on the site were investigated by drilling thirteen exploratory test borings. The approximate locations of the test borings are presented in the Test Boring Location Plan, Figure 2.1.

The test borings were advanced with a power-driven, continuous-flight auger drill rig to depths of about 5 to 10 feet below the existing ground surface. Samples were obtained in general accordance with ASTM D-1586 utilizing a 2-inch OD split-barrel sampler. Representative bulk samples of subsurface materials were obtained from each boring at a depth of approximately 0 to 2 feet below the existing ground surface. An Explanation of Test Boring Logs is presented in Figure 3. The Test Boring Logs are presented in Figures 4 through 10.

#### **Subsurface Materials**

The subsurface materials encountered in the test borings consisted of sandy clay fill, native sandy clay, and sandy claystone. Combined bulk samples of the material classified as CL according to the Unified Classification System. For pavement design purposes, the combined bulk soil samples classified as A-6 with a group index of 18, and A-7-6 with group indices ranging from 20 to 30 in accordance with the American Association of State Highway and Transportation Officials (AASHTO) classification system. This soil classification is considered "poor" as subgrade material.

#### Groundwater

Groundwater was not encountered in the test borings at the time of drilling. Groundwater is not expected to affect the construction of the pavements. Fluctuations in groundwater and subsurface moisture conditions may occur due to variations in precipitation and other factors not readily apparent at this time. Development of the property and adjacent properties may also affect groundwater levels.

### LABORATORY TESTING

#### **Laboratory Testing**

The moisture content for the recovered samples was obtained in the laboratory. Grain-size analysis, Atterberg Limits tests, and Denver Swell/Consolidation tests were performed on selected samples for purposes of classification and to develop pertinent engineering properties. A Summary of Laboratory Test Results is presented in Figure 11. Soil Classification Data are presented in Figures 12 through 14. Denver Swell/Consolidation Test Results are presented in Figure 15 through 17.

A combined bulk sample of A-7-6 soil (using materials with group indices ranging from 25 to 30) was tested to determine the optimum moisture-density relationship in accordance with ASTM D698 (Standard Proctor compaction test). California Bearing Ratio, CBR tests were performed at varying densities with moisture content near optimum. At 95% of the maximum Standard Proctor density, the CBR of the bulk sample was determined to be 1.6. The Moisture-Density Relation Curves are presented in Figure 18. The CBR Test Results are presented in Figures 19 and 20.

It's our understanding that the developer intends to install a composite roadway section consisting of Hot Mix Asphalt over Aggregate Base Course (ABC). The use of Cement-Treated Subgrade (CTS) was considered. However, based on information from personnel of El Paso County Planning & Community Development via electronic mail on September 19 and 20, 2022, our understanding is that the use of the on-site soils as a component of the CTS mixture has been deemed unsuitable for pavement construction. As such, a CTS option is not presented herein. If a CTS option is desired in the future, please contact personnel of RMG for more information.

## PAVEMENT DESIGN

The discussion presented below is based on the subsurface conditions encountered in the test borings, laboratory test results and the project characteristics previously described. If the subsurface conditions are different from those described in this report or the project characteristics change, RMG should be retained to review our recommendations and modify them, if necessary. The conclusions and recommendations presented in this report should be verified by RMG during construction.

The pavement design was performed using the El Paso County Engineering Criteria Manual, Appendix D. The pavement design parameters and design calculations are presented below.

#### Street Classification – Urban Local

1) Reagan Ridge Drive, Logans Ridge Drive, Rikers Ridge Lane, Cody Ridge Drive, Scrub Jay Trail, Broken Top Drive, Alpine Ridge Drive, and Walleye Drive

```
ESAL = 292,000 (Table D-2)
Serviceability Index = 2.0 (Table D-1)
```

2) Strength coefficients (Table D-3)

```
Asphalt (HMA): a_1 = 0.44
Aggregate Base Course (ABC): a_2 = 0.11
```

3) Subgrade

$$M_r = CBR \times 1500 = 1.6 \times 1500 = 2,400 \text{ psi}$$

- 4) Structural number (SN) = 3.73 (per 1993 AASHTO Empirical Equation for Flexible Pavements)
- 5) Composite asphalt/ABC section

```
Minimum HMA thickness = D_1 = 3 inches (Table D-2)
ABC thickness = D_2 = {SN - (D_1 x a_1)} / a_2 = {3.73 - (3 x 0.44)} / 0.11 = 22.0 inches
SN = (5.25 x 0.44) + (13 x 0.11) = 3.74 > 3.73 (Min. SN required)
Use HMA thickness = 5.25 inches over ABC thickness = 13.0 inches
```

#### **Pavement Thickness**

Based on the design calculations, the recommended pavement section is presented below and on Figure 2.2.

#### **Recommended Pavement Sections**

Reagan Ridge Drive, Logans Ridge Drive, Rikers Ridge Lane, Cody Ridge Drive, Scrub Jay Trail, Broken Top Drive, Alpine Ridge Drive, and Walleye Drive	5.25" HMA	13.0" ABC
---	--------------	--------------

#### **Pavement Materials**

Pavement materials should be selected, prepared, and placed in accordance with El Paso County specifications and the *Pikes Peak Region Asphalt Paving Specifications*. Tests should be performed in accordance with the applicable procedures presented in the specifications.

#### **Soil Mitigation**

The PDCM notes that mitigation measures may be required for expansive soils, shallow ground water, subgrade instability, etc. Based on the AASHTO classification of for the soils in the subdivision, the subgrade soils evaluated for this pavement design exhibited a swell of less than 2.0%. Groundwater or wet and unstable soils were not encountered in the borings. Therefore, special mitigation measures do not appear to be necessary for subgrade preparation.

#### **Subgrade Preparation**

All fill placed below pavements should be moisture conditioned and compacted in accordance with El Paso County *Standard Specifications Manual*. Prior to placement of the pavement section, the final subgrade should be scarified to a depth of 12 inches, adjusted to within 2 percent of the optimum moisture content and compacted to El Paso County specifications. The subgrade should then be proofrolled with a heavy, pneumatic tired vehicle. Areas which deform under wheel loads should be removed and replaced. Base course place atop prepared subgrade should be compacted to at least 95 percent of the maximum modified Proctor density (ASTM D1557).

#### **Sulfate Content**

Sulfate testing was performed on selected samples based on ASTM C1580. Test results showed up to 0.98% by weight, indicating the soils present Class II (severe) sulfate exposure. Based on these results, high sulfate resistant Type V cement or a Type V equivalent mixture according to ACI 201.2R-10 is suggested for concrete in contact with the subsurface materials. Cement type shall be designed and approved by a licensed Colorado Professional Engineer and Foundation Designer. Calcium chloride should not be used for the onsite soils. The concrete should not be placed on frozen ground. If placed during periods of cold temperatures, the concrete should be kept from freezing. This may require covering the concrete with insulated blankets and heating.

Concrete work should be completed in accordance with the latest applicable guidelines and standards published by ACI.

#### **Surface Drainage**

Surface drainage is important for the satisfactory performance of pavement. Wetting of the subgrade soils or base course will cause a loss of strength which can result in pavement distress. Surface drainage should provide for efficient removal of storm-water runoff. Water should not be allowed to pond on the pavement or at the edges of the pavement.

#### **Subgrade Observations and Testing**

The pavement thicknesses presented above assume pavement construction is completed in accordance with El Paso County specifications and the *Pikes Peak Region Asphalt Paving Specifications*. RMG should be present at the site during subgrade preparation, placement of fill, and construction of pavements to perform site observations and testing.

#### **CLOSING**

This report has been prepared for the exclusive purpose of providing geotechnical engineering information and recommendations for development described in this report. RMG should be retained to review the final construction documents prior to construction to verify our findings, conclusions and recommendations have been appropriately implemented.


This report has been prepared for the exclusive use by the **Landhuis Company** for application as an aid in the design and construction of the proposed development in accordance with generally accepted geotechnical engineering practices. The analyses and recommendations in this report are based in part upon data obtained from test borings, site observations and the information presented in referenced reports. The nature and extent of variations may not become evident until construction. If variations then become evident, RMG should be retained to review the recommendations presented in this report considering the varied condition, and either verify or modify them in writing.


Our professional services were performed using that degree of care and skill ordinarily exercised, under similar circumstances, by geotechnical engineers practicing in this or similar localities. RMG does not warrant the work of regulatory agencies or other third parties supplying information which may have been used during the preparation of this report. No warranty, express or implied is made by the preparation of this report. Third parties reviewing this report should draw their own conclusions regarding site conditions and specific construction techniques to be used on this project.


The scope of services for this project does not include, either specifically or by implication, environmental assessment of the site or identification of contaminated or hazardous materials or conditions. Development of recommendations for the mitigation of environmentally related conditions, including but not limited to biological or toxicological issues, are beyond the scope of

this report. If the Client desires investigation into the potential for such contamination or conditions, other studies should be undertaken.

If we can be of further assistance in discussing the contents of this report or analysis of the proposed development, from a geotechnical engineering point-of-view, please feel free to contact us.









Architecture Structural Geotechnical



Forensics
Civil / Planning

Materials Testing

#### **Engineers / Architects**

SOUTHERN COLORADO OFFICE
2910 AUSTIN BLUFFS PKWY, SUITE 100,
COLORADO SPRINGS, CO 80918
(719) 548-0600 ~ WWW.RMGENGINEERS.COM
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO


## SITE VICINITY MAP

THE RIDGE AT LORSON RANCH
PAVEMENT DESIGN
EL PASO COUNTY, COLORADO
LANDHUIS COMPANY

JOB No. 186386

FIG No. 1

DATE 10-20-2022




JOB No. 186386 THE RIDGE AT LORSON RANCH
PAVEMENT DESIGN
EL PASO COUNTY, COLORADO
LANDHUIS COMPANY

¥Z¥ ENGINEER: DRAWN BY: CHECKED BY: 10-20-2022

**TEST BORING** LAYOUT PLAN

SHEET No.

DENOTES APPROXIMATE LOCATION OF TEST BORINGS



THE RIDGE AT LORSON RANCH
PAVEMENT DESIGN
EL PASO COUNTY, COLORADO
LANDHUIS COMPANY

186386

ENGINEER: IM
DRAWN BY: NM
CHECKED BY: TM
ISSUED: IO-20-2022

PAVEMENT RECOMMENDATIONS

SHEET No.

## SOILS DESCRIPTION



**CLAYSTONE** 



FILL: CLAY, SANDY



SANDY CLAY

UNLESS NOTED OTHERWISE, ALL LABORATORY TESTS PRESENTED HEREIN WERE PERFORMED BY: RMG - ROCKY MOUNTAIN GROUP 2910 AUSTIN BLUFFS PARKWAY COLORADO SPRINGS, COLORADO

## SYMBOLS AND NOTES



STANDARD PENETRATION TEST - MADE BY DRIVING A SPLIT-BARREL SAMPLER INTO THE SOIL BY DROPPING A 140 LB. HAMMER 30", IN GENERAL ACCORDANCE WITH ASTM D-1586. NUMBER INDICATES NUMBER OF HAMMER BLOWS PER FOOT (UNLESS OTHERWISE INDICATED).

UNDISTURBED CALIFORNIA SAMPLE - MADE BY DRIVING A RING-LINED SAMPLER INTO THE SOIL BY DROPPING A 140 LB. HAMMER 30", IN GENERAL ACCORDANCE WITH ASTM



D-3550. NUMBER INDICATES NUMBER OF HAMMER BLOWS PER FOOT (UNLESS OTHERWISE INDICATED).

DEPTH AT WHICH BORING CAVED



BULK DISTURBED BULK SAMPLE

FREE WATER TABLE



**AUG** AUGER "CUTTINGS"

4.5

WATER CONTENT (%)

ROCKY MOUNTAIN GROUP

Architectural Structural Forensics




**EXPLANATION OF TEST BORING LOGS**  JOB No. 186386

FIGURE No. 3

Oct/20/2022 DATE

**Engineers / Architects** 

Colorado Sprinas: (Corporate Office)
2910 Austin Bluffs Partway
Colorado Springs, CO 99016
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO



Architectural Structural Forensics





Engineers / Architects

Colorado Sprinos: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spinos, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

TEST BORING LOG JOB No. 186386

FIGURE No. 4








Colorado Springs: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spings, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

**TEST BORING** LOG

JOB No. 186386

FIGURE No. 6






Colorado Sprinas: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spings, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

**TEST BORING LOG** 

FIGURE No. 7






Colorado Sprinos: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spinos, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

**TEST BORING LOG** 

FIGURE No. 8



Architectural Structural Forensics




**Engineers / Architects** 

Colorado Sprinos: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spinos, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

TEST BORING LOG JOB No. 186386

FIGURE No. 9





Colorado Springs: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spings, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

**TEST BORING LOG** 

FIGURE No. 10

Test Boring No.	Depth	Water Content (%)	Dry Density (pcf)	Liquid Limit	Plasticity Index	% Retained No.10 Sieve	% Retained No.40 Sieve	% Passing No. 200 Sieve	% Swell @ 100 psf	AASHTO Classification
40	2.0	12.5	101.7	41	26	1.9	3.8	81.2	- 0.1	A-7-6 (20)
40	4.0	13.6								
41	2.0	11.5		42	25	0.4	3.6	82.3		A-7-6 (20)
41	4.0	14.3								
42	2.0	14.6		46	31	1.5	4.0	82.9		A-7-6 (25)
42	4.0	14.1								
43	2.0	11.2	103.9	39	24	1.7	3.5	79.5	0.0	A-6 (18)
43	4.0	11.4								
43	9.0	9.3								
44	2.0	15.7		45	30	0.4	3.5	84.4		A-7-6 (25)
44	4.0	11.7								
45	2.0	16.3	95.7	43	29	1.5	4.4	79.4	0.0	A-7-6 (22)
45	4.0	16.2								
46	2.0	15.2		45	32	1.1	3.5	76.9		A-7-6 (23)
46	4.0	15.5								
47	2.0	10.4	104.7	43	30	1.6	3.5	81.2	- 0.1	A-7-6 (23)
47	4.0	9.4								
48	2.0	17.0	94.5	49	34	2.3	8.6	71.6	- 0.6	A-7-6 (23)
48	4.0	13.4								
49	2.0	13.8		47	32	0.8	3.7	80.7		A-7-6 (25)
49	4.0	13.1								
49	9.0	22.1								
50	2.0	16.6		49	34	2.8	4.5	82.5		A-7-6 (28)
50	4.0	16.5								
51	2.0	15.1	99.7	44	31	2.1	11.9	75.7	0.1	A-7-6 (22)
51	4.0	19.3								
52	2.0	18.8		54	36	1.6	5.7	80.9		A-7-6 (30)
52	4.0	12.2								

Architectural Structural Forensics




**Engineers / Architects** 

Geotechnical Materials Testing SUMMARY OF LABORATORY TEST RESULTS

JOB No. 186386 FIGURE No. 11 PAGE 1 OF 1 DATE Oct/20/2022

Colorado Sprinas: (Corporate Office)
2910 Austin Buffs Farkway
Colorado Springs, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO



	Test Boring	Depth (ft)		Classification			LL	PL	PI	
•	40	2.0		LEAN CLAY with SAND(CL)			41	15	26	
X	41	2.0		LEAN CLAY with SAND(CL)				42	17	25
<b>A</b>	42	2.0		LEAN CLAY with SAND(CL)			46	15	31	
*	43	2.0		LEAN CLAY with SAND(CL)			39	15	24	
$\odot$	44	2.0		LEAN CLAY with SAND(CL)			45	15	30	
	Toot Poring	Donth (ft)	%Craval	0/ 0	0/, Cil+	0/ Clay				

	Lest Boring	Depth (ft)	%Gravel	%Sand	%Silt	%Clay
•	40	2.0	0.9	17.9	81	.2
	41	2.0	0.0	17.7	82	2.3
	42	2.0	0.3	16.8	82	2.9
*	43	2.0	0.0	20.5	79	).5
•	44	2.0	0.2	15.4	84	.4

Architectural Structural Forensics

Geotechnical Materials Testing Civil, Planning SOIL CLASSIFICATION DATA


JOB No. 186386

FIGURE No. 12

DATE Oct/20/2022

Engineers / Architects

Colorado Sarings: (Corporate Office)
2910 Austin Bluffs Partway
Colorado Springs, CO 69916
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO



	Test Boring	Depth (ft)	Classification	LL	PL	PI
	45	2.0	LEAN CLAY with SAND(CL)	43	14	29
X	46	2.0	LEAN CLAY with SAND(CL)	45	13	32
<b>A</b>	47	2.0	LEAN CLAY with SAND(CL)	43	13	30
*	48	2.0	LEAN CLAY with SAND(CL)	49	15	34
•	49	2.0	LEAN CLAY with SAND(CL)		15	32
	Tast Davisson	D = = 41= (f4)	0/ Cravel 0/ C 1 0/ City 0/ Clave			

	l est Boring	Depth (ft)	%Gravel	%Sand	%Silt	%Clay
•	45	2.0	0.3	20.3	79	.4
	46	2.0	0.3	22.9	76	5.9
▲	47	2.0	0.7	18.1	81	.2
*	48	2.0	0.4	27.9	71	.6
$\odot$	49	2.0	0.1	19.2	80	.7

RMG

Architectural Structural Forensics

Geotechnical Materials Testing Civil, Planning SOIL CLASSIFICATION DATA


JOB No. 186386

FIGURE No. 13

DATE Oct/20/2022

Engineers / Architects

Colorado Sarings: (Corporate Office)
2910 Austin Bluffs Partway
Colorado Springs, CO 69916
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO



-	Test Boring De	epth (ft)	Classification	LL	PL	PI
•	50	2.0	LEAN CLAY with SAND(CL)	49	15	34
×	51	2.0	LEAN CLAY with SAND(CL)	44	13	31
▲	52	2.0	FAT CLAY with SAND(CH)	54	18	36

T	est Boring	Depth (ft)	%Gravel	%Sand	%Silt	%Clay
•	50	2.0	0.3	17.2	82.5	
×	51	2.0	1.4	22.9	75.7	
▲	52	2.0	0.1	19.0	80.9	

RMG

Geotechnical Materials Testing Civil, Planning SOIL CLASSIFICATION DATA

JOB No. 186386


FIGURE No. 14

DATE Oct/20/2022

Architectural Structural Forensics

Engineers / Architects

Colorado, Sprinas. (Comorate Office)
2910 Austin Bull's Fartwey
Colorado Springs. CO 69918
(719) 548-09018
SOUTHERN COLORADO, DERVIER METRO, NORTHERN COLORADO



Architectural Structural Forensics




Engineers / Architects

Colorado Springs: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spings, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

## SWELL/CONSOLIDATION TEST RESULTS

JOB No. 186386

FIGURE No. 15



Architectural Structural Forensics




**Engineers / Architects** 

Colorado Springs: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spings, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

## SWELL/CONSOLIDATION TEST RESULTS

JOB No. 186386

FIGURE No. 16





SWELL/CONSOLIDATION **TEST RESULTS** 


JOB No. 186386

FIGURE No. 17

Oct/20/2022 DATE

**Engineers / Architects** 

Colorado Springs: (Corporate Office)
2910 Austin Bluffs Parkway
Colorado Spings, CO 80918
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO





Geotechnical Materials Testing

#### Engineers / Architects

Colorado Sprinas: (Corporate Office)
2910 Austin Bluffs Partway
Colorado Springs, CO 99916
(719) 548-0600
SOUTHERN COLORADO, DENVER METRO, NORTHERN COLORADO

## MOISTURE-DENSITY RELATION CURVE

JOB No. 186386

FIGURE No. 18


#### **CALIFORNIA BEARING RATIO TEST RESULTS**

Project: The Ridge at Lorson Ranch
Job No.: 186386

AASHTO Classification" A-7 Sample Number: CBR

Sample Location: Combined Bulk Sample Soil Description: Sandy Clay

	10 blows/lift	25 blows/lift	56 blows/lift
Penetration			
(in)	Load (psi)	Load (psi)	Load (psi)
0.000	0.0	0.0	0.0
0.025	5.0	7.7	10.4
0.050	6.7	10.7	14.4
0.075	7.4	12.4	17.8
0.100	7.7	13.4	19.8
0.125	8.4	14.4	21.5
0.150	9.1	15.8	23.2
0.175	10.1	16.1	25.5
0.200	10.4	17.5	27.2
0.300	11.8	19.1	31.6
0.400	12.8	21.2	36.3
0.500	13.4	22.2	40.0



	Corrected	
	Penetration	Corrected Load
	(in)	(psi)
10 blows/lift	0.100	0.8
25 blows/lift	0.100	1.3
56 blows/lift	0.100	2.0




#### **CALIFORNIA BEARING RATIO TEST RESULTS**

Project: The Ridge at Lorson Ranch Job No.: 186386

AASHTO Classification" A-7 Sample Number: CBR

Sample Location: Combined Bulk Sample Soil Description: Sandy Clay

	10 blows/lift	25 blows/lift	56 blows/lift
Corrected California Bearing Ratio	0.8	1.3	2.0
Dry Density (pcf)	81.3	94.1	97.3
Percent Compaction	82	95	98
Percent Moisture After Soaking	40.5	38.6	34.2
Percent Expansion (+) / Compression (-)	3.3%	3.9%	3.7%
Surcharge Weight (lbs)	12.60	12.60	12.60



California Bearing Ratio	1.6
Dry Density (pcf)	99.5
Percent Compaction	95%
Target Dry Density	94.5
Compaction Test Method	ASTM D-698
Condition of sample	Soaked



