

August 9, 2019



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
COLORADO SPRINGS, CO 80907
PHONE (719) 531-5599
SF-26-018 (719) 531-5238

COLA, LLC
555 Middle Creek Pkwy., Ste. 380
Colorado Springs, CO 80921

Provide memo stating findings
in report are still valid or what
has changed since report is 7
years old.

Attn: Dan Romano

Re: Geologic Hazard Additional Borings
Springs at Waterview East (Trails at Aspen Ridge)
South Powers and Bradley Road
Colorado Springs, Colorado

Ref: Entech Engineering, Inc., Revised February 8, 2019. *Soils, Geology and Geologic Hazard, Springs at Waterview East, South Powers Boulevard and Bradley Road, El Paso County, Colorado.* Entech Job No. 170039.

Entech Engineering, Inc., April 10, 2019. *Geologic Hazard Addendum, Springs at Waterview East, South Powers Boulevard and Bradley Road, El Paso County Colorado.* Entech Job No. 170039.

Dear Mr. Romano

A Soils, Geology and Geologic Hazard Study was prepared by Entech Engineering, Inc., Revised Date February 8, 2019, for the above referenced site. This letter is in response to the Colorado Geological Survey (CGS) review letter dated July 19, 2019, CGS Unique No. EP-18-0011_5 which is attached to this letter.

CGS recommended additional investigation on the site in areas where significant cuts are proposed. Entech drilled four additional borings on August 7, 2019. Test Boring locations are shown on Figure 1. Test Boring Nos. 1 – 3 were drilled in areas of deep cuts, and Test Boring No. 4 was placed in an area of significant fill. Groundwater was not encountered during drilling or subsequent to drilling. The test borings were drilled to depths of 20 to 40 feet. Soils encountered in these borings consisted of predominantly sandy clay soils with underlying claystone and shale bedrock. The bedrock underlying the site is the Pierre Shale Formation of Cretaceous Age, which typically has a moderate to high expansion potential.

The new borings do not alter the conclusions in the previous reports. Based on the additional subsurface information, it is anticipated claystone or shale will be exposed in the majority of cuts proposed on the site. These soils have the potential for moderate to high expansion potential. Mitigation of the expansive soils will be required for the majority of the site. Specific recommendations for foundations and construction will be provided in the Subsurface Soil Investigations after additional site investigation is performed for the different phases of the development prior to construction.

COLA, LLC
Geologic Hazard Additional Borings
Springs at Waterview East (Trails at Aspen Ridge)
South Powers Boulevard and Bradley Road
El Paso County, Colorado

We trust this has provided you with the information you required. If you have any questions or need additional information, please do not hesitate to contact us.

Respectfully Submitted,

ENTECH ENGINEERING, INC.



Logan L. Langford, P.G.
Geologist

LLL/kah
Encl.


Entech Job No. 170039

AA Projects/2017/170039 geohaz additional borings


Reviewed by:



Joseph C. Goode, Jr., P.E.
President



FIGURES

[illegible]

ENTECH
ENGINEERING, INC.
505 ELKTON DRIVE
COLORADO SPRINGS, CO. 80907 (719) 531-5599

**SITE PLAN/TEST BORING LOCATION MAP
SPRINGS AT WATERVIEW EAST
S POWERS BOULEVARD AND BRADLEY ROAD
EL PASO COUNTY, CO.
FOR: COLA, LLC**

DRAWN
ILL
CHECKED
DATE
8/8/19
SCALE
AS SHOWN
JOB NO.
170039
FIGURE NO.
1

**APPENDIX A: Colorado Geological Survey Review Letter, dated
July 19, 2019, CGS Unique No. EP18-0011_5**

COLORADO GEOLOGICAL SURVEY

1801 Moly Road
Golden, Colorado 80401



July 19, 2019

Karen Berry
State Geologist

Nina Ruiz
El Paso County
Planning and Community Development
2880 International Circle
Colorado Springs, CO 80910

Location:
W½ Section 9,
T15S, R65W of the 6th P.M.
38.7562, -104.6777

**Subject: Trails at Aspen Ridge PUDSP191 (previously reviewed as Springs East at Waterview SP-17-010)
El Paso County, CO; CGS Unique No. EP-18-0011 5**

Dear Ms. Ruiz:

Colorado Geological Survey has reviewed the Trails at Aspen Ridge combined PUD/preliminary plan resubmittal. I understand the applicant currently proposes 605 SF residential lots (previously 516 lots) on 118 acres located southeast of S. Powers Blvd. and Bradley Road, east of Security-Widefield.

The available referral documents include:

- Trails at Aspen Ridge Letter of Intent (revised June 26, 2019),
- Geologic Hazard Addendum, Springs at Waterview East (Entech Engineering, Inc., April 10, 2019),
- Set of eight Trails at Aspen Ridge Grading and Erosion Control Plans (Matrix Design Group/Stantec, June 2019),
- and other documents.

CGS previously discussed concerns about insufficient subsurface information in the northeastern and southwestern areas of the site, where significant cuts are planned. **The additional borings described by Entech in their 4/10/2019 addendum are not located within the areas of concern.**

The additional borings described by Entech (two sets of two borings, both labeled TB-1 and TB-2) are located as follows:

Entech's Appendix B boring TB-1 is located near the Legacy Drive/Frontside Drive cul de sac where, according to sheet 4 of the June 2019 Grading & Erosion Control Plans, approximately 10-15 feet of fill is proposed. TB-2 is located northwest of the Legacy/Frontside cul de sac, in a commercial area outside of the Trails at Aspen Ridge development area, described on sheet 4 of the grading plans as "unplatted."

The locations of Entech's Appendix C borings are difficult to determine because of the poor quality of Figure 2, but appear to be located east of proposed Wagon Hammer Drive, outside of the currently proposed Trails at Aspen Ridge development area, within the existing Phase I (Not a Part)/Filing I Area To Remain identified on the PUD and grading plans.

Our previous comments therefore remain valid: Entech's borings in some areas of the Trails at Aspen Ridge PUD/preliminary plan do not extend to sufficient depths to provide meaningful information about soil and bedrock engineering properties and groundwater levels.


Nina Ruiz
July 19, 2019
Page 2 of 2

Additional investigation, sampling, testing and analysis are needed in proposed areas of cuts exceeding about 8 feet, based on the project grading plans, to characterize subsurface conditions, determine depth and extent of overexcavation, if overexcavation is planned to reduce the use of drilled pier foundations, and to determine basement feasibility where Entech's borings did not extend to sufficient depth below planned basement floor and foundation bearing depths.

Entech has previously stated that "Overexcavation depths of 4 to 6 feet are anticipated for the site." This means 4 to 6 feet below foundation bearing elevations. For a development of the proposed density, overexcavation should be performed over the entire area within a specific construction phase determined to require overexcavation, at the grading phase of development, before wet utilities are installed. In areas of expansive soils, significant cuts and/or shallow claystone bedrock, roads will require overexcavation as well.

Thank you for the opportunity to review and comment on this project. If you have questions or require additional review, please call me at (303) 384-2643, or e-mail carlson@mines.edu.

Sincerely,



Jill Carlson, C.E.G.
Engineering Geologist

APPENDIX B: Laboratory Test Results and Test Boring Logs

TEST BORING NO. 1
 DATE DRILLED 8/7/2019
 Job # 170039

TEST BORING NO. 2
 DATE DRILLED 8/7/2019
 CLIENT DAKOTA SPRINGS
 LOCATION TRAILS AT ASPEN RIDGE

REMARKS

DRY TO 30', 8/8/19

CLAY, VERY SANDY, LIGHT
 BROWN, VERY STIFF, MOIST

CLAYSTONE, SANDY, TAN,
 HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			36	7.5	2
5			50 11"	9.3	3
10			50 7"	8.7	3
15			50 6"	9.9	3
20			50 6"	9.1	3
25			50 3"	9.4	3
30			50 6"	9.4	3
35			50 3"	9.7	3

REMARKS

DRY TO 32', 8/8/19

SAND, CLAYEY, FINE TO COARSE
 GRAINED, TAN, MEDIUM DENSE,
 MOIST

WEATHERED TO FORMATIONAL
 CLAYSTONE, SANDY, GRAY
 BROWN, VERY STIFF TO HARD,
 MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			10	3.4	1
5			15	3.7	1
10			19	5.5	1
15			17	6.6	1
20			22	13.0	1
25			23	12.6	1
30			34	14.1	3
35			50 10"	15.6	3



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN:

DATE:

CHECKED:

DATE:

LL

8/9/19

JOB NO.
 170039

FIG NO.

B-1

TEST BORING NO. 3
 DATE DRILLED 8/7/2019
 Job # 170039

TEST BORING NO. 4
 DATE DRILLED 8/7/2019
 CLIENT DAKOTA SPRINGS
 LOCATION TRAILS AT ASPEN RIDGE

REMARKS

DRY TO 37', 8/8/19

CLAY, SANDY, TAN, FIRM TO
 STIFF, MOIST

WEATHERED CLAYSTONE, SANDY,
 TAN, VERY STIFF, MOIST

CLAYSTONE, SANDY, GRAY
 BROWN, HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			13	13.2	2
5			28	10.6	2
10			39	13.0	3
15			50 8"	14.4	3
20			50 7"	12.2	3
25			50 7"	10.7	3
30			50 6"	12.7	3
35			50 8"	12.7	3
40			50 4"	9.9	3

REMARKS

DRY TO 20', 8/8/19

CLAY, SANDY, TAN, FIRM,
 MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			13	5.2	2
5			14	8.1	2
10			13	3.6	2
15			13	5.4	2
20			10	14.8	2



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN

DATE

CHECKED

DATE

LLL

8/9/19

JOB NO.
 170039

FIG NO.
 13-2

April 10, 2019

Dakota Springs Engineering, Inc.
31 North Tejon Street, Suite 500
Colorado Springs, CO 80903



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
COLORADO SPRINGS, CO 80907
PHONE (719) 531-5599
FAX (719) 531-5238

Attn: Charles K. Cothorn

Re: Geologic Hazard Addendum
Springs at Waterview East
South Powers and Bradley Road
Colorado Springs, Colorado

Ref: Entech Engineering, Inc., Revised February 8, 2019. *Soils, Geology and Geologic Hazard, Springs at Waterview East, South Powers Boulevard and Bradley Road, El Paso County, Colorado*. Entech Job No. 170039

Dear Mr. Cothorn:

A Soils, Geology and Geologic Hazard Study was prepared by Entech Engineering, Inc., Revised Date February 8, 2019, for the above referenced site. This addendum is in response to the Colorado Geological Survey (CGS) review letter dated March 20, 2019, CGS Unique No. EP-18-0011_4 and is included in Appendix A.

CGS recommended additional investigation on the site in areas where significant cuts are proposed. Entech has recently drilled additional borings at the site. The Summary of Laboratory Test Results, Test Boring Location Maps and Test Boring Logs are included in Appendices B and C. Soils encountered in these borings consisted of predominantly clay soils with underlying claystone and shale. The bedrock underlying the site is the Pierre Shale Formation of Cretaceous Age, which typically has a moderate to high expansion potential.

Based on the additional subsurface information, it is anticipated claystone or clay soils will be exposed in the majority of cuts proposed on the site. These soils have the potential for moderate to high expansion potential. Mitigation of the expansive soils will be required for the majority of the site. Specific recommendations for foundations and construction will be provided in the Subsurface Soil Investigations after additional investigation is performed for the different phases of the development prior to construction.

We trust this has provided you with the information you required. If you have any questions or need additional information, please do not hesitate to contact us.

Respectfully Submitted,

ENTECH ENGINEERING, INC.


Logan L. Langford, P.G.
Geologist

LLL/kah

Encl.

Entech Job No. 170039

AA Projects/2017/170039 geohaz addendum

Reviewed by:


Joseph C. Goode, Jr.
President



**APPENDIX A: Colorado Geological Survey Review Letter, dated
March 20, 2019, CGS Unique No. EP18-0011_4**

COLORADO GEOLOGICAL SURVEY

1801 Moly Road
Golden, Colorado 80401



Karen Berry
State Geologist

March 20, 2019

Nina Ruiz
El Paso County
Planning and Community Development
2880 International Circle
Colorado Springs, CO 80910

Location:
W½ Section 9,
T15S, R65W of the 6th P.M.
38.7562, -104.6777

**Subject: Trails at Aspen Ridge PUDSP191 (previously reviewed as Springs East at Waterview SP-17-010)
El Paso County, CO; CGS Unique No. EP-18-0011 4**

Dear Ms. Ruiz:

Colorado Geological Survey has reviewed the Trails at Aspen Ridge combined PUD/preliminary plan referral. I understand the applicant currently proposes 516 SF residential lots on 118 acres located southeast of S. Powers Blvd. and Bradley Road, east of Security-Widefield.

The available referral documents include:

- Trails at Aspen Ridge Letter of Intent (February 13, 2019),
- Soil, Geology, and Geologic Hazard, Springs at Waterview East (Entech Engineering, Inc., revised February 8, 2019),
- Set of ten Trails at Aspen Ridge Grading and Erosion Control Plans (Matrix Design Group/Stantec, February 2019),
- and other documents.

CGS previously reviewed the Springs East at Waterview development, and two previous versions of Entech's Soil, Geology, and Geologic Hazard report (4/25/2017 and 2/21/2018). Entech's revised (2/8/2019) report contains an updated lot layout but is otherwise unchanged from the 2/21/2018 version.

Entech's ten borings were drilled to a depth of 20 feet. The Trails at Aspen Ridge Grading and Erosion Control Plans indicate that significant cuts and fills are planned. Cuts of approximately 15 feet are proposed in the area of Entech's borings TB-1 in the in the northeastern area of the site, and TB-5, in the southwestern area of the site, so Entech's borings extend only five feet below proposed grade in these areas, and do not extend to sufficient depths to provide meaningful information about soil and bedrock engineering properties and groundwater levels.

As noted in CGS's 11/28/2017 review letter, **additional investigation, sampling, testing and analysis are needed in proposed cut areas, based on the project grading plans**, to characterize subsurface conditions, determine depth and extent of overexcavation, if overexcavation is planned to reduce the use of drilled pier foundations, and to determine basement feasibility where Entech's borings did not extend to sufficient depth below planned basement floor and foundation bearing depths.


Entech states (page 7) "Overexcavation depths of 4 to 6 feet are anticipated for the site." This means 4 to 6 feet below foundation bearing elevations. For a development of the proposed density, overexcavation should

Nina Ruiz
March 20, 2019
Page 2 of 2

be performed over the entire area within a specific construction phase determined to require overexcavation, at the grading phase of development, before wet utilities are installed. In areas of expansive soils, significant cuts and/or shallow claystone bedrock, roads will require overexcavation as well.

Thank you for the opportunity to review and comment on this project. If you have questions or require additional review, please call me at (303) 384-2643, or e-mail carlson@mines.edu.

Sincerely,

A handwritten signature in black ink, appearing to read 'Jill Carlson', written over the word 'Sincerely,'.

Jill Carlson, C.E.G.
Engineering Geologist



**APPENDIX B: Laboratory Test Results and Test Boring Logs,
Entech Job No. 190161**

TABLE 1
SUMMARY OF LABORATORY TEST RESULTS

CLIENT COLA, LLC
PROJECT TRAILS AT ASPEN RIDGE
JOB NO. 190161

SOIL TYPE	TEST BORING NO.	DEPTH (FT)	WATER (%)	DRY DENSITY (PCF)	PASSING NO. 200 SIEVE (%)	LIQUID LIMIT (%)	PLASTIC INDEX (%)	SULFATE (WT %)	FHA SWELL (PSF)	SWELL/CONSOL (%)	UNIFIED CLASSIFICATION	SOIL DESCRIPTION
1	2	5			34.4						SM	SAND, SILTY
2	1	2-3			67.3	27	13				CL	CLAY, SANDY
2	1	10	33.1	103.3	90.0	44	26			0.3	CL	CLAY, SANDY
2	2	30			61.6						CL	CLAY, VERY SANDY
3	1	20	23.2	102.6	95.5	32	13			0.9	CL	CLAYSTONE, SANDY

FIGURE



⊕ TB-2- APPROXIMATE TEST BORING LOCATION AND NUMBER



ENTECH
ENGINEERING, INC.
505 ELKTON DRIVE
COLORADO SPRINGS, CO 80907 (719) 531-5399

VICINITY MAP/TEST BORING LOCATION PLAN
LEGACY DRIVE - BORROW SITE
EL PASO COUNTY, CO
FOR: COLA, LLC

DRAWN BY:
SCC

DATE DRAWN:
02/21/19

DESIGNED BY:
SCC

CHECKED:
SCC

JOB NO.:
190161
FIG. NO.:

1

APPENDIX A: Test Boring Logs

TEST BORING NO. 1
 DATE DRILLED 2/8/2019
 Job # 190161

TEST BORING NO. 2
 DATE DRILLED 2/8/2019
 CLIENT COLA, LLC
 LOCATION TRAILS AT ASPEN RIDGE

REMARKS

WATER @ 15', 2/8/19
 CLAY, SANDY, TAN TO RED
 BROWN, FIRM, MOIST

HIGHLY WEATHERED CLAYSTONE,
 GRAY BROWN, VERY STIFF,
 MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			14	7.3	2
5			8	14.0	2
10			12	21.3	2
15			11	11.1	2
20			34	19.6	3

REMARKS

DRY TO 30', 2/8/19
 SAND, SILTY, FINE GRAINED,
 LIGHT BROWN, LOOSE TO MEDIUM
 DENSE, MOIST

CLAYEY LENSES

CLAY, SANDY, RED BROWN,
 STIFF, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			15	7.2	1
5			10	6.1	1
10			9	3.1	1
15			17	3.0	1
20			13	4.5	1
25			29	10.9	1
30			16	15.5	2



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN

DATE

CHECKED: *h*

DATE: 2/21/19

JOB NO:
 190161

FIG NO:
 A- 1


**APPENDIX C: Laboratory Test Results and Test Boring Logs,
Entech Job No. 190162**

TABLE 1
SUMMARY OF LABORATORY TEST RESULTS

CLIENT COLA, LLC
PROJECT TRAILS AT ASPEN RIDGE
JOB NO. 190162

SOIL TYPE	TEST BORING NO.	DEPTH (FT)	WATER (%)	DRY DENSITY (PCF)	PASSING NO. 200 SIEVE (%)	LIQUID LIMIT (%)	PLASTIC INDEX (%)	SULFATE (WT %)	FHA SWELL (PSF)	SWELL/CONSOL (%)	UNIFIED CLASSIFICATION	SOIL DESCRIPTION
1	1	2-3	13.3	103.0	91.8	39	19	<0.01		1.5	CL	CLAY, SANDY
1	2	2-3			95.6				1420		CL	CLAY, SANDY
2	1	10	15.8	107.2	97.3			0.24		1.2	CL	CLAYSTONE, SANDY
2	2	15	15.8	113.9	97.9	56	36			3.1	CH	CLAYSTONE, SANDY
3	1	20			93.5			0.15			CL	SHALE

FIGURES



ENTECH
ENGINEERING, INC.

305 ELKTON DRIVE
COLORADO SPRINGS, CO 80907 (719) 531-3599

VICINITY MAP
TRAILS AT ASPEN RIDGE-BORROW SITE
EL PASO COUNTY, CO
FOR: COLA, LLC

DRAWN BY:
SCC


DATE DRAWN:
02/25/19

DESIGNED BY:
SCC

CHECKED:
SCC

JOB NO.:
190162
FIG. NO.:

1



 TB-2 - APPROXIMATE TEST BORING LOCATION AND NUMBER



ENTECH
ENGINEERING, INC.

585 ELAKTON DRIVE
COLORADO SPRINGS, CO. 80907 (719) 531-5599

TEST BORING LOCATION MAP
TRAILS AT ASPEN RIDGE-BORROW SITE
EL PASO COUNTY, CO
FOR: COLA, LLC

DRAWN BY:
SCC

DATE DRAWN:
02/25/19

DESIGNED BY:
SCC

CHECKED:
SCC

JOB NO.:
190162
FIG. NO.:

2

APPENDIX A: Test Boring Logs

TEST BORING NO. 1
 DATE DRILLED 2/11/2019
 Job # 190162

TEST BORING NO. 2
 DATE DRILLED 2/11/2019
 CLIENT COLA, LLC
 LOCATION TRAILS AT ASPEN RIDGE

REMARKS

DRY TO 20', 2/11/19

0.5' TOPSOIL, CLAY, SANDY,
 TAN, STIFF, MOIST

WEATHERED TO FORMATIONAL
 CLAYSTONE, SANDY, TAN,
 VERY STIFF TO HARD, MOIST

SHALE, GRAY BROWN, HARD,
 MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			24	10.1	1
5			45	11.3	2
10			50 9"	15.0	2
15			50 9"	13.1	2
20			50 2"	9.5	3

REMARKS

DRY TO 30', 2/11/19

0.5' TOPSOIL, CLAY, SANDY,
 TAN, STIFF, MOIST

WEATHERED TO FORMATIONAL
 CLAYSTONE, SANDY, GRAY
 BROWN, VERY STIFF TO HARD,
 MOIST

SHALE, GRAY BROWN, HARD,
 MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			20	13.5	1
5			28	15.2	1
10			47	16.3	2
15			40	17.6	2
20			47	17.0	2
25			50 7"	13.6	2
30			50 2"	9.6	3



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN:

DATE

CHECKED: *A*

DATE: *2/22/19*

JOB NO:
 190162

FIG NO:
 A- 1



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
COLORADO SPRINGS, CO 80907
PHONE (719) 531-5599
FAX (719) 531-5238

**SOIL, GEOLOGY, AND GEOLOGIC HAZARD
SPRINGS AT WATERVIEW EAST
SOUTH POWERS BOULEVARD AND BRADLEY ROAD
EL PASO COUNTY, COLORADO**

Prepared for

Dakota Springs Engineering, Inc.
31 North Tejon Street, Suite 500
Colorado Springs, Colorado 80903

Attn: Charles K. Cothorn

April 25, 2017
February 21, 2018
Revised February 8, 2019

Respectfully Submitted,

ENTECH ENGINEERING, INC.

Logan L. Langford, P.G.
Geologist

LLL/nc

Encl.

Entech Job No. 170039
AAprojects/2017/170039 countysoil/geo

Reviewed by:

Joseph C. Goode, Jr., P.E.
President



TABLE OF CONTENTS

1.0 SUMMARY	1
2.0 GENERAL SITE CONDITIONS AND PROJECT DESCRIPTION	2
3.0 SCOPE OF THE REPORT	2
4.0 FIELD INVESTIGATION	3
5.0 SOIL, GEOLOGY AND ENGINEERING GEOLOGY	3
5.1 General Geology	3
5.2 Soil Conservation Survey	4
5.3 Site Stratigraphy	4
5.4 Soil Conditions	5
5.5 Groundwater	6
6.0 ENGINEERING GEOLOGY – IDENTIFICATION AND MITIGATION OF GEOLOGIC HAZARDS	7
6.1 Relevance of Geologic Conditions to Land Use Planning	8
7.0 ECONOMIC MINERAL RESOURCES	9
8.0 EROSION CONTROL	10
9.0 DETENTION FACILITIES	11
10.0 CLOSURE	13
BIBLIOGRAPHY	14

TABLES

Table 1: Summary of Laboratory Test Results

FIGURES

Figure 1: Vicinity Map

Figure 2: USGS Map

Figure 3: Development Plan/Test Boring Location Map

Figure 4: Soil Survey Map

Figure 5: Elsmere Quadrangle Geology Map

Figure 6: Geology Map/Engineering Geology

Figure 7: Floodplain Map

Figure 8: Typical Perimeter Drain Details

APPENDIX A: Site Photographs

APPENDIX B: Test Boring Logs and Profile Hole Logs

APPENDIX C: Laboratory Test Results

APPENDIX D: Soil Survey Descriptions

1.0 SUMMARY

Project Location

The project lies in a portion of the W½ of Section 9, Township 15 South, Range 65 West of the 6th Principal Meridian in El Paso County, Colorado. The site is located approximately 2½ miles east of Security-Widefield, Colorado.

Project Description

Total acreage involved in the project is approximately 178 acres. The proposed site development consists of seven hundred and thirteen (713) single-family residential lots, eight (8) commercial lots, and twelve (12) tracts within the development for several parks and two detention ponds. The development will utilize municipal sewer and water.

Scope of Report

This report presents the results of our geologic evaluation and treatment of engineering geologic hazard study.

Land Use and Engineering Geology

This site was found to be suitable for the proposed development. Areas were encountered where the geologic conditions will impose constraints on development and land use. These include areas of collapsible soils, highly expansive soils, potential seasonal shallow groundwater, and shallow bedrock. Based on the proposed development plan, it appears that these areas will have impact on the development. These conditions will be discussed in greater detail in the report.

In general, it is our opinion that the development can be achieved if the observed geologic conditions on site can be properly mitigated with site grading and engineering design. All recommendations are subject to the limitations discussed in the report.

2.0 GENERAL SITE CONDITIONS AND PROJECT DESCRIPTION

The site is located in a portion of the W½ of Section 9, Township 15 South, Range 65 West of the 6th Principal Meridian in El Paso County, Colorado. The site is located approximately 2½ miles east of Security-Widefield, Colorado, at the southeastern corner of South Powers Boulevard and Bradley Road. The location of the site is as shown on the Vicinity Map, Figure 1.

The topography of the site is generally gradually to moderately sloping to the south, with a small ridge along the western portion of the site. The drainages on site flow in southerly direction through the eastern portion of the site. Water was not observed in the drainages at the time of this investigation. The site boundaries are indicated on the USGS Map, Figure 2. Previous land uses have included grazing and pasture land. The site contains primarily field grasses, weeds, cacti, and yuccas. Site photographs, taken March 7, 2017, are included in Appendix A.

Total acreage involved in the proposed development is approximately 178 acres. The proposed site development consists of seven hundred and thirteen (713) single-family residential lots, eight (8) commercial lots, and twelve (12) tracts within the development for several parks and two detention ponds. The proposed lots are approximately 5,500 to 14,000 square feet each. The area will be serviced municipal sewer and water. Significant site grading to develop the site is anticipated. The proposed Development Plan is presented in Figure 3.

3.0 SCOPE OF THE REPORT

The scope of the report will include the following:

- A general geologic analysis utilizing published geologic data. Detailed site-specific mapping will be conducted to obtain general information in respect to major geographic and geologic features, geologic descriptions and their effects on the development of the property.

4.0 FIELD INVESTIGATION

Our field investigation consisted of the preparation of a geologic map of any bedrock features and significant surficial deposits. The Natural Resource Conservation Service (NRCS), previously the Soil Conservation Service (SCS) survey was also reviewed to evaluate the site. The position of mappable units within the subject property are shown on the Geologic Map. Our mapping procedures involved both field reconnaissance and measurements and air photo reconnaissance and interpretation. The same mapping procedures have also been utilized to produce the Engineering Geology Map which identified pertinent geologic conditions affecting development. The field mapping was performed by personnel of Entech Engineering, Inc. on March 7, 2017.

Ten (10) Test Borings were performed on the site to determine general soil and bedrock characteristics. The locations of the test borings are indicated on the Development Plan/Test Boring Location Map, Figure 3. The Test Boring Logs are presented in Appendix B. Results of this testing will be discussed later in this report.

Laboratory testing was also performed on some of the soils to classify and determine the soils engineering characteristics. Laboratory tests included grain-size analysis, ASTM D-422, and Atterberg Limits, ASTM D-4318. Swell/Consolidation and FHA Swell Testing to evaluate expansion potential. Sulfate testing was performed on selected samples to evaluate potential for below grade concrete degradation due to sulfate attack. Results of the laboratory testing are included in Appendix C. A Summary of Laboratory Test Results is presented in Table 1.

5.0 SOIL, GEOLOGY AND ENGINEERING GEOLOGY

5.1 General Geology

Physiographically, the site lies in the western portion of the Great Plains Physiographic Province. Approximately 9 miles to the west is a major structural feature known as the Ute Pass Fault. This fault marks the boundary between the Great Plains Physiographic Province and the

Southern Rocky Mountain Province. The site exists within the southeastern edge of a large structural feature known as the Denver Basin. Bedrock in the area tends to be very gently

dipping in a northeasterly direction (Reference 1). The rocks in the area of the site are sedimentary in nature and typically Upper Cretaceous in age. The bedrock underlying the site consists of the Pierre Shale Formation. Overlying this formation are unconsolidated deposits of residual soils, and alluvial soils of Quaternary Age. The alluvial soils were deposited by water along the drainages on-site. The site's stratigraphy will be discussed in more detail in Section 5.3.

5.2 Soil Conservation Survey

The Natural Resource Conservation Service (Reference 2), previously the Soil Conservation Service (Reference 3) has mapped six soil types on the site (Figure 4). In general, the soils classify as loamy sand, sandy loam, loam, and clay loam. The soils are described as follows:

<u>Type</u>	<u>Description</u>
8	Blakeland Loamy Sand, 0 to 3% slopes
31	Fort Collins Loam, 3 to 8% slopes
52	Manzanita Clay Loam, 0 to 3% slopes
56	Nelson-Tassel Fine Sandy Loams, 3 to 18% slopes
86	Stoneham Sandy Loam, 3 to 8% slopes
108	Wiley Silty Loam, 3 to 9% slopes

Complete descriptions of each soil type are presented in Appendix D. The soils have generally been described to have moderate to moderately rapid permeabilities. Possible hazards with soil erosion are present on the site. The erosion potential can be controlled with vegetation. The majority of the soils have been described to have slight to moderate erosion hazards.

5.3 Site Stratigraphy

The Elsmere Quadrangle Geology Map showing the site is presented in Figure 5 (Reference 4). The Geology Map prepared for the site is presented in Figure 6. Two mappable units were identified on this site which are described as follows:

- Qal Recent Alluvium of Holocene Age:** These are recent deposits that have been deposited along the drainages on-site.
- Kp Pierre Shale of Cretaceous Age:** This formation consists of olive brown to gray claystone and shale. These materials were deposited in a marine environment associated with the Cretaceous Seaway. Typically, there is a layer of residually weathered soil present above the Pierre Shale. The soils and bedrock associated with this formation are typically expansive.

The soils listed above were mapped from site-specific mapping, the *Geologic Map of the Elsmere Quadrangle* distributed by the Colorado Geological Survey in 2002 (Reference 4), the *Geologic Map of the Colorado Springs-Castle Rock Area*, distributed by the US Geological Survey in 1979 (Reference 5), and the *Geologic Map of the Denver 1° x 2° Quadrangle*, distributed by the US Geological Survey in 1981 (Reference 6). The Test Borings and Profile Holes were also used in evaluating the site and are included in Appendix B. The Geology Map prepared for the site is presented in Figure 6.

5.4 Soil Conditions

The soils and bedrock encountered in the Profile Holes can be grouped into three general soil types. The soils were classified using the Unified Soil Classification System (USCS).

Soil Type 1 is very clayey sand (SC), encountered in all of Test Boring No. 7 at the existing surface to a depth of 8 feet bgs. These soils were encountered at medium dense states and moist conditions. The sample tested had 49 percent passing the No. 200 Sieve.

Soil Type 2 is sandy clay (CL), encountered in nine of test borings at the existing ground surface and extending to depths ranging from 3 to 20 feet bgs. These soils were encountered at firm to very stiff consistencies and moist conditions. Samples tested had 65 to 99 percent passing the No. 200 Sieve. Atterberg Limits Testing resulted in liquid limits of 29 to 38 and plastic indexes of 14 to 21. FHA Swell testing resulted in expansion pressures ranging from 690 to 1340 psf. Swell/Consolidation Testing on select samples resulted in a consolidation of 0.3 percent, and a swell of 6.4 percent. These results indicate the clay soils have a low consolidation potential and a moderate to very high expansion potential. Sulfate testing resulted in less than 0.01 to 0.6

percent sulfate by weight indicating the clay exhibits negligible potential for below grade concrete degradation.

Soil Type 3 is sandy claystone and shale (CL), encountered in nine of the test borings at depths ranging from 3 to 14 feet and extending to the termination of the test borings (20 feet). The claystone and shale were encountered at very stiff to hard consistencies and at moist conditions. Samples tested had 85 to 98 percent passing the No. 200 Sieve. Atterberg Limits Testing resulted in liquid limits of 43 to 54 and plastic indexes of 23 to 29. FHA Swell testing resulted in an expansion pressure of 1880 psf. Swell/Consolidation Testing resulted in swells of 2.0 to 3.8 percent. These results indicate that the claystone and shale bedrock have a moderate to high expansion potential. Sulfate testing resulted in 0.29 to 0.32 percent sulfate by weight indicating the clay exhibits severe potential for below grade concrete degradation.

The Test Boring Logs are presented in Appendix B. Laboratory Test Results are presented in Appendix C. A Summary of Laboratory Test Results is presented in Table 1.

5.5 Groundwater

Groundwater was not encountered in the test borings which were drilled to depths of 20 feet. Areas of potential seasonal shallow groundwater water have been mapped along the drainages on-site. These areas are discussed in the following section. Fluctuation in groundwater conditions may occur due to variations in rainfall and other factors not readily apparent at this time.

It should be noted that in the sandy materials on site, some groundwater conditions might be encountered due to the variability in the soil profile. Isolated sand and gravel layers within the soils, sometimes only a few feet in thickness and width, can carry water in the subsurface. Groundwater may also flow on top of the underlying bedrock. Builders and planners should be cognizant of the potential for the occurrence of such subsurface water features during construction on-site and deal with each individual problem as necessary at the time of construction.

6.0 ENGINEERING GEOLOGY – IDENTIFICATION AND MITIGATION OF GEOLOGIC HAZARDS

As mentioned previously, detailed mapping has been performed on this site to produce an Engineering Geology Map (Figure 6). This map shows the location of various geologic conditions of which the developers should be cognizant during the planning, design and construction stages of the project. These hazards and the recommended mitigation techniques are as follows:

Collapsible Soils

The majority of the soils encountered on-site do not exhibit collapsible characteristics, however, areas of soils with consolidation potential were encountered in the test borings drilled on site.

Mitigation: Should loose or collapsible soils be encountered beneath foundations, recompaction and moisture conditioning of the upper 2 to 3 feet of soil at 95% of its maximum Modified Proctor Dry Density ASTM D-1557 will be required. Exterior flatwork and parking areas may also experience movement. Proofrolling and recompaction of soft areas should be performed during site work.

Expansive Soils

Expansive soils are common in the area, and were encountered in the test borings. Swells ranged from low to very high. The clay, claystone and shale, if encountered beneath foundations, can cause differential movement in the structure foundation. These occurrences should be identified and dealt with on an individual basis or possibly mitigated during site grading.

Mitigation Should expansive soils be encountered beneath the foundation, mitigation will be necessary. Mitigation of expansive soils will require special foundation design. Overexcavation and replacement with non-expansive soils at a minimum of 95% of its maximum Modified Proctor Dry Density, ASTM D-1557 is a suitable mitigation, which is common in the area. Floor slabs on expansive soils should be expected to experience movement. Overexcavation and replacement has been successful in minimizing slab movements. Overexcavation depths of 4 to 6 feet are anticipated for the site. Mitigation may also include moisture conditioning and recompaction of the clay soils. The use of structural floors should be considered for basement construction on highly expansive clays.

Drilled piers are another option that is used in areas where highly expansive soils are encountered. Typical minimum pier depths are on the order of 25 feet or more and require penetration into the bedrock material a minimum of 4 to 6 feet, depending upon building loads. Final recommendations should be determined after additional investigation of the lots.

Groundwater and Floodplain Areas

Areas within the drainages on-site have been identified as areas of potential seasonally shallow groundwater areas. Water was not flowing in any of the drainages at the time of this investigation. The site is not mapped within floodplain zones according to the FEMA Map No. 08041CO768F, Figure 9 (Reference 7). These areas are discussed as follows:

Potentially Seasonal Shallow Groundwater

In these areas, we would anticipate the potential for periodically high subsurface moisture conditions and possible frost heave potential, depending on the soil conditions.

Mitigation In these locations, foundations in areas subject to severe frost heave potential should penetrate sufficient depth so as to discourage the formation of ice lenses beneath foundations. At this location and elevation, a foundation depth for frost protection of 2.5 feet is recommended. In areas where high subsurface moisture conditions are anticipated periodically, a subsurface perimeter drain will be necessary to help prevent the intrusion of water into areas located below grade. A typical perimeter drain detail is presented in Figure 16. Additionally, swales should be created to intercept surface runoff and carry it safely around and away from structures. It is anticipated that the site grading will likely mitigate the drainages on site.

6.1 Relevance of Geologic Conditions to Land Use Planning

As mentioned earlier in this report, we understand that the development will consist of single family residential and commercial lots. It is our opinion that the existing geologic and engineering geologic conditions will impose some constraints on the proposed development and construction. The most significant problems affecting development will be those associated with the expansive soils and shallow bedrock on-site that can be mitigated with special designs. Other hazards on site may be satisfactorily mitigated through proper engineering design and construction practices.

The upper materials are typically at medium dense states and firm to very stiff consistencies. Loose soils if encountered at foundation depth will require mitigation. Foundations anticipated for the site are standard spread footings in conjunction with overexcavation in areas of expansive soils. Excavation of the sand and clay soils is anticipated to be moderate to difficult with rubber-tired equipment, excavation of claystone and shale will likely require track-mounted equipment. Expansive soils will require special foundation design and/or overexcavation. These soils will not prohibit development.

Areas of potential seasonally shallow groundwater were observed in the in the eastern portion of the site. These areas will likely be mitigated with site grading and proper stormwater planning.

In summary, development of the site can be achieved if the items mentioned above are mitigated. These items can be mitigated through proper design and construction or through avoidance. Additional subsurface soil investigation is recommended prior to construction.

7.0 ECONOMIC MINERAL RESOURCES

According to the *El Paso County Aggregate Resource Evaluation Map* (Reference 8), the area is not mapped with any aggregate deposits. According to the *Atlas of Sand, Gravel and Quarry Aggregate Resources, Colorado Front Range Counties* distributed by the Colorado Geological Survey (Reference 9), areas of the site are not mapped with any resources. According to the *Evaluation of Mineral and Mineral Fuel Potential* (Reference 10), the area of the site has been mapped as "Fair" for industrial minerals. However, considering the clayey silty nature of the soils, they would be considered to have little significance as an economic resource.

According to the *Evaluation of Mineral and Mineral Fuel Potential of El Paso County State Mineral Lands* (Reference 10), the site is mapped within the Denver Basin Coal Region. However, the area of the site has been mapped as "Poor" for coal resources. No active or inactive mines have been mapped in the area of the site. No metallic mineral resources have been mapped on-site (Reference 10).

The site has been mapped as "Fair" for oil and gas resources (Reference 10). No oil or gas fields have been discovered in the area of the site. The sedimentary rocks in the area may lack

the geologic structure for trapping oil or gas; therefore, it may not be considered a significant resource. Hydraulic fracturing is a new method that is being used to extract oil and gas from rocks. It utilizes pressurized fluid to extract oil and gas from rocks that would not normally be productive. The area of the site has not been explored to determine if the rocks underlying the site would be commercially viable utilizing hydraulic fracturing. The practice of hydraulic fracturing has come under review due to concerns about environmental impacts, health and safety.

8.0 EROSION CONTROL

The soil types observed on the site are mildly to highly susceptible to wind erosion, and moderately to highly susceptible to water erosion. A minor wind erosion and dust problem may be created for a short time during and immediately after construction. Should the problem be considered severe enough during this time, watering of the cut areas or the use of chemical palliative may be required to control dust. However, once construction has been completed and vegetation re-established, the potential for wind erosion should be considerably reduced.

With regard to water erosion, loosely compacted soils will be the most susceptible to water erosion, residually weathered soils become increasingly less susceptible to water erosion. For the typical soils observed on-site, allowable velocities on unvegetated and unlined earth channels would be on the order of 3 to 4 feet/second, depending upon the sediment load carried by the water. Permissible velocities may be increased through the use of vegetation to something on the order of 4 to 7 feet/second, depending upon the type of vegetation established. Should the anticipated velocities exceed these values, some form of channel lining material may be required to reduce erosion potential. These might consist of some of the synthetic channel lining materials on the market or conventional riprap. In cases where ditch-lining materials are still insufficient to control erosion, small check dams or sediment traps may be required. The check dams will serve to reduce flow velocities, as well as provide small traps for containing sediment. The determination of the amount, location and placement of ditch linings, check dams and of the special erosion control features should be performed by or in conjunction with the drainage engineer who is more familiar with the flow quantities and velocities.

Cut and fill slope areas will be subjected primarily to sheetwash and rill erosion. Unchecked rill erosion can eventually lead to concentrated flows of water and gully erosion. The best means to combat this type of erosion is, where possible, the adequate re-vegetation of cut and fill slopes. Cut and fill slopes having gradients more than three (3) horizontal to one (1) vertical become increasingly more difficult to revegetate successfully. Therefore, recommendations pertaining to the vegetation of the cut and fill slopes may require input from a qualified landscape architect and/or the Soil Conservation Service.

9.0 DETENTION FACILITIES

Two detention ponds will be constructed within the Springs at Waterview East Subdivision. One pond is proposed along the west side of the subdivision, located in Tract H, east of Powers Boulevard and the second pond is proposed near the southeast corner of the subdivision, located in Tract E. A Subsurface Soil Investigation was conducted in this area on this property and the findings are included in this report. This report section provides recommendations for constructing detention ponds based on our investigation, laboratory testing, and requirements specified in the El Paso County Engineering Criteria Manual and the El Paso County Drainage Criteria Manual.

The soils in the vicinity of the west pond, Tract H, were recovered from Test Boring No. 8 and soils in Test Boring Nos. 3 and 4 were drilled in the vicinity of the east pond, Tract E. The location of the test borings and the test boring logs are included in this report. The soils recovered from Test Boring Nos. 3 and 4 were determined to consist of 4 to 7 feet of sandy clay overlying sandy claystone with underlying shale encountered in Test Boring No. 3. The soils recovered from Test Boring No. 8 were determined to consist of 9 feet of sandy clay overlying sandy claystone. Groundwater was not encountered in the test borings as noted on the test boring logs.

The west detention pond has been designed to store approximately 5.8 acre-feet at an approximate depth of 7.9 feet and a maximum surface area of 1.5 acres. Approximately 10 feet of fill is proposed for the west pond and the embankments are estimated at less than 8 feet in

height with 3:1 side slopes. The east detention pond has been designed to store approximately 5.8 acre-feet at an approximate depth of 8.1 feet and a maximum surface area of 4.1 acres. Approximately 2 feet of fill is proposed for the east pond and the embankments are estimated at less than 10 feet in height with 3:1 side slopes.

Sandy clay overlies the claystone and based on samples tested from other test borings on the site determined the soil to contain between approximately 65 and 99 percent of the materials passing a No. 200 sieve (CL). Samples of clay resulted in Liquid Limits between 29 and 38 and Plastic Indexes between 14 and 21, and exhibiting a negligible exposure to soluble sulfate attack on buried concrete structures in contact with the clay. Laboratory testing on samples of claystone determined the soil to contain between 86 and 98 of the materials passing a No. 200 sieve (CL). Samples of claystone resulted in Liquid Limits between 43 and 54 and Plastic Indexes between 23 and 29. The claystone exhibits a severe exposure to soluble sulfate attack on buried concrete structures in contact with the claystone. Site sandy clays will be used to fill both Tracts for the detention facilities.

The detention pond design parameters and geometry shall conform to the requirements specified in the El Paso County Engineering Criteria Manual and the El Paso County Drainage Criteria Manual. Sandy clay will likely be used for overlot and pond embankment construction (with 3:1 side slopes) with a soil bearing capacity of 2,000 psf, and soil mitigation may be required for expansive site clays. The embankment foundation shall be fully exposed and observed by personnel of Entech to determine mitigation requirements, if any, prior to constructing the embankment. Groundwater is not expected at the proposed embankment foundation elevations. The embankment fill shall be properly benched into the existing slopes and observed by personnel of Entech prior to fill placement. The embankment soils shall be compacted to the requirements of structural fill at a minimum of 95 percent of the soils maximum Standard Dry Density as determined by ASTM D-698 at -1 to +3 percent of the soils optimum moisture content. Based on the suggested compaction efforts for the embankment soils and the expected foundation soils, it is likely that embankment settlement will be less than 5 percent of the embankment height. Seepage through the embankment should be minimal due to the limited 3-day detention time and the ability for the outlet structure to release the stored waters in 10 hours for both ponds.

10.0 CLOSURE

It is our opinion that the existing geologic engineering and geologic conditions will impose some constraints on development and construction of the site. The majority of these conditions can be mitigated through proper engineering design and construction practices. The proposed development and use is consistent with anticipated geologic and engineering geologic conditions.

It should be pointed out that because of the nature of data obtained by random sampling of such variable and non-homogeneous materials as soil and rock, it is important that we be informed of any differences observed between surface and subsurface conditions encountered in construction and those assumed in the body of this report. Individual investigations for building sites will be required prior to construction. Construction and design personnel should be made familiar with the contents of this report. Reporting such discrepancies to Entech Engineering, Inc. soon after they are discovered would be greatly appreciated and could possibly help avoid construction and development problems.

This report has been prepared for Dakota Springs, Engineering, Inc. for application to the proposed project in accordance with generally accepted geologic soil and engineering practices. No other warranty expressed or implied is made.

We trust that this report has provided you with all the information that you required. Should you require additional information, please do not hesitate to contact Entech Engineering, Inc.

BIBLIOGRAPHY

1. Bryant, Bruce; McGrew, Laura W, and Wabus, Reinhard A. 1981. *Geologic Structure Map of the Denver 1° x 2° Quadrangle, North-Central Colorado*. Sheet 2. U.S. Geologic Survey. Map I-1163.
2. Natural Resource Conservation Service, September 23, 2016. *Web Soil Survey*. United States Department Agriculture, <http://websoilsurvey.sc.egov.usda.gov/App/HomePage.htm>.
3. United States Department of Agriculture Soil Conservation Service. June 1981. *Soil Survey of El Paso County Area, Colorado*.
4. Madole, Richard F. and Thorson, Jon P., 2003. *Geologic Map of the Elsmere Quadrangle, El Paso County, Colorado*. Colorado Geological Survey. Open-File Report 02-2.
5. Trimble, Donald E. and Machette, Michael N. 1979. *Geologic Map of the Colorado Springs-Castle Rock Area, Front Range Urban Corridor, Colorado*. USGS, Map I-857-F.
6. Bryant, Bruce; McGrew, Laura W. and Wobus, Reinhard A. 1981. *Geologic Map of the Denver 1° x 2° Quadrangle, North-Central Colorado*. U.S. Geologic Survey. Map 1-1163.
7. Federal Emergency Management Agency. March 17, 1997. *Flood Insurance Rate Maps for El Paso County, Colorado and Incorporated Areas*. Map Number 08041CO764F
8. El Paso County Planning Development. December 1995. *El Paso County Aggregate Resource Evaluation Maps*.
9. Schwochow, S.D.; Shroba, R.R. and Wicklein, P.C. 1974. *Atlas of Sand, Gravel, and Quarry Aggregate Resources, Colorado Front Range Counties*. Colorado Geological Survey. Special Publication 5-B.
10. Keller, John W.; TerBest, Harry and Garrison, Rachel E. 2003. *Evaluation of Mineral and Mineral Fuel Potential of El Paso County State Mineral Lands Administered by the Colorado State Land Board*. Colorado Geological Survey. Open-File Report 03-07.

TABLES

TABLE 1
SUMMARY OF LABORATORY TEST RESULTS

CLIENT DAKOTA SPRINGS ENGINEERING
PROJECT SPRINGS AT WATERVIEW
JOB NO. 170039

SOIL TYPE	TEST BORING NO.	DEPTH (FT)	WATER (%)	DRY DENSITY (PCF)	PASSING NO. 200 SIEVE (%)	LIQUID LIMIT (%)	PLASTIC INDEX (%)	SULFATE (WT %)	FHA SWELL (PSF)	SWELL/ CONSOL (%)	UNIFIED CLASSIFICATION	SOIL DESCRIPTION
1	7	5			48.6						SC	SAND, VERY CLAYEY
2	1	5	13.7	120.8	93.1	38	21			6.4	CL	CLAY, SANDY
2	2	10	8.3	104.8	64.6	29	14			-0.3	CL	CLAY, SANDY
2	3	2-3			87.0			0.06	690		CL	CLAY, SANDY
2	5	2-3			96.0						CL	CLAY, SANDY
2	6	2-3			77.6			<0.01	980		CL	CLAY, SANDY
2	9	5	16.9	98.0	93.0					1.6	CL	CLAY, SANDY
2	10	5			98.8				1340		CL	CLAY, SANDY
3	4	5	16.9	113.6	86.6	54	29			3.4	CH	CLAYSTONE, SANDY
3	5	10	17.7	109.3	86.0	43	23			2.0	CL	CLAYSTONE, SANDY
3	6	20	19.0	111.0	98.3					3.8	CL	CLAYSTONE, SANDY
3	7	15			85.3			0.29			CL	CLAYSTONE, SANDY
3	8	10			87.6			0.32	1880		CL	CLAYSTONE, SANDY

Table 2: Summary of Depth of Fill, and Depth to Bedrock and Groundwater Depths

Test Boring No.	Depth of Fill (ft.)	Depth to Bedrock (ft.)	Depth to Groundwater (ft.)
1	N/A	9	N/A
2	N/A	N/A	N/A
3	N/A	7	N/A
4	N/A	4	N/A
5	N/A	3	N/A
6	N/A	14	N/A
7	N/A	8	N/A
8	N/A	9	N/A
9	N/A	14	N/A
10	N/A	3	N/A

FIGURES



ENTECH
ENGINEERING, INC.
505 ELKTON DRIVE
COLORADO SPRINGS, CO. 80907 (719) 531-5599

VICINITY MAP
SPRINGS AT WATERVIEW EAST
POWERS BOULEVARD AND BRADLEY ROAD
EL PASO COUNTY, CO.
FOR: DAKOTA SPRINGS ENGINEERING, INC.

DRAWN:
LLL


DATE:
2/15/18

CHECKED:

DATE:

JOB NO.:
170039

FIG NO.:
1



ENTECH
ENGINEERING, INC.
505 ELKTON DRIVE
COLORADO SPRINGS, CO. 80907 (719) 531-5599

USGS MAP
SPRINGS AT WATERVIEW EAST
POWERS BOULEVARD AND BRADLEY ROAD
EL PASO COUNTY, CO.
FOR: DAKOTA SPRINGS ENGINEERING, INC.

DRAWN:
LLL


DATE:
2/15/18

CHECKED:

DATE:

JOB NO.:
170039

FIG NO.:
2



ENTECH
ENGINEERING, INC.
505 ELKTON DRIVE
COLORADO SPRINGS, CO. 80907 (719) 531-5599

SOIL SURVEY MAP
SPRINGS AT WATERVIEW EAST
POWERS BOULEVARD AND BRADLEY ROAD
EL PASO COUNTY, CO.
FOR: DAKOTA SPRINGS ENGINEERING, INC.

DRAWN:
LLL


DATE:
2/15/18

CHECKED:

DATE:

JOB NO.:
170039

FIG NO.:
4



ENTECH
ENGINEERING, INC.
505 ELKTON DRIVE
COLORADO SPRINGS, CO. 80907 (719) 531-3599

ELSMERE QUADRANGLE GEOLOGY MAP
SPRINGS AT WATERVIEW EAST
POWERS BOULEVARD AND BRADLEY ROAD
EL PASO COUNTY CO.
FOR: DAKOTA SPRINGS ENGINEERING, INC.

DRAWN:
LLL



DATE:
2/15/18

CHECKED:

DATE:

JOB NO.:
170039

FIG NO.:
5



NOTES:

-GRAVEL SIZE IS RELATED TO DIAMETER OF PIPE PERFORATIONS-85% GRAVEL GREATER THAN 2x PERFORATION DIAMETER.

-PIPE DIAMETER DEPENDS UPON EXPECTED SEEPAGE. 4-INCH DIAMETER IS MOST OFTEN USED.

-ALL PIPE SHALL BE PERFORATED PLASTIC. THE DISCHARGE PORTION OF THE PIPE SHOULD BE NON-PERFORATED PIPE.

-FLEXIBLE PIPE MAY BE USED UP TO 8 FEET IN DEPTH, IF SUCH PIPE IS DESIGNED TO WITHSTAND THE PRESSURES. RIGID PLASTIC PIPE WOULD OTHERWISE BE REQUIRED.

-MINIMUM GRADE FOR DRAIN PIPE TO BE 1% OR 3 INCHES OF FALL IN 25 FEET.

-DRAIN TO BE PROVIDED WITH A FREE GRAVITY OUTFALL, IF POSSIBLE. A SUMP AND PUMP MAY BE USED IF GRAVITY OUT FALL IS NOT AVAILABLE.



ENTECH
ENGINEERING, INC.
505 ELKTON DRIVE
COLORADO SPRINGS, CO. 80907 (719) 531-5599

PERIMETER DRAIN DETAIL

DRAWN:

DATE:

DESIGNED:

DS

CHECKED:

LLL

JOB NO.:

170039

PIC NO.:

8

APPENDIX A: Site Photographs



**Looking east from the
southwestern portion
of the site.**

March 7, 2017



**Looking north from the
southwestern portion
of the site.**

March 7, 2017



**Looking north from the
southeast portion of
the site.**

March 7, 2017



**Looking northwest
from the southeast
portion of the site.**

March 7, 2017



**Looking north from the
eastern side of the
site.**

March 7, 2017



**Looking south from
the northeastern
portion of the site.**

March 7, 2017




**Looking southwest
from the northeastern
portion of the site.**

March 7, 2017



**Looking east from the
northern portion of the
site.**

March 7, 2017




**Looking west from the
northern portion of the
site.**

March 7, 2017



**Looking south from
the northern portion of
the site.**

March 7, 2017



**Looking southwest
from the western
portion of the site.**

February 10, 2017



**Looking east from the
western portion of the
site.**

March 7, 2017

APPENDIX B: Test Boring Logs

TEST BORING NO. 1
DATE DRILLED 1/30/2017
Job # 170039

TEST BORING NO. 2
DATE DRILLED 1/30/2017
CLIENT DAKOTA SPRINGS ENGINEERING
LOCATION SPRINGS AT WATERVIEW

REMARKS

DRY TO 19.5', 1/31/17

CLAY, SANDY, GRAY BROWN,
STIFF TO VERY STIFF, MOIST

CLAYSTONE, SANDY, GRAY
BROWN, HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			24	9.6	2
5			35	13.2	2
10			50 8"	13.4	3
15			50 6"	12.5	3
20			50 6"	18.6	3

REMARKS

DRY TO 20', 1/31/17

CLAY, SANDY, STIFF TO
SOFT, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			18	7.5	2
5			22	9.1	2
10			14	8.8	2
15			11	15.8	2
20			7	19.5	2



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN:

DATE:

CHECKED:

DATE:

LLL

4/12/17

JOB NO.:
170039

FIG NO.:
B- 1

TEST BORING NO. 3
 DATE DRILLED 1/30/2017
 Job # 170039

TEST BORING NO. 4
 DATE DRILLED 1/30/2017
 CLIENT DAKOTA SPRINGS ENGINEERING
 LOCATION SPRINGS AT WATERVIEW

REMARKS

DRY TO 19.5', 1/31/17

CLAY, SANDY, TAN, STIFF
 TO VERY STIFF, MOIST

CLAYSTONE, SANDY, GRAY
 BROWN, HARD, MOIST

SHALE, DARK BROWN, HARD,
 MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			29	11.9	2
5			47	14.3	2
10			50 10"	15.5	3
15			50 7"	15.8	3
20			50 6"	12.7	3

REMARKS

DRY TO 19.5', 1/31/17

CLAY, SANDY, GRAY BROWN,
 STIFF, MOIST

CLAYSTONE, SANDY, GRAY
 BROWN, HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			27	15.7	2
5			50 10"	13.8	3
10			50 9"	14.5	3
15			50 7"	14.4	3
20			50 6"	13.2	3



**ENTECH
 ENGINEERING, INC.**

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN:

DATE:

CHECKED:

DATE:

LL

4/12/17

JOB NO.:
 170039

FIG NO.:
 B- 2

TEST BORING NO. 5
 DATE DRILLED 1/30/2017
 Job # 170039

TEST BORING NO. 6
 DATE DRILLED 1/30/2017
 CLIENT DAKOTA SPRINGS ENGINEERING
 LOCATION SPRINGS AT WATERVIEW

REMARKS

DRY TO 19', 1/31/17

CLAY, SANDY, GRAY BROWN,
 VERY STIFF, MOIST

CLAYSTONE, SANDY, GRAY
 BROWN, HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			44	11.6	2
5			50 11"	12.5	3
10			50 6"	12.4	3
15			50 6"	15.3	3
20			50 6"	13.4	3

REMARKS

DRY TO 19', 1/31/17

CLAY, SANDY, TAN, STIFF,
 MOIST

CLAYSTONE, SANDY, TAN,
 HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			20	7.9	2
5			19	9.8	2
10			25	12.9	2
15			50 7"	15.9	3
20			50 6"	15.5	3



**ENTECH
 ENGINEERING, INC.**

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN:

DATE:

CHECKED:
 LLL

DATE:
 4/12/17

JOB NO.:
 170039

FIG NO.:
 B- 3

TEST BORING NO. 7
 DATE DRILLED 1/30/2017
 Job # 170039

TEST BORING NO. 8
 DATE DRILLED 1/30/2017
 CLIENT DAKOTA SPRINGS ENGINEERING
 LOCATION SPRINGS AT WATERVIEW

REMARKS

DRY TO 19', 1/31/17

SAND, VERY CLAYEY, FINE
 GRAINED, TAN, MEDIUM
 DENSE, MOIST

CLAYSTONE, SANDY, BROWN,
 HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			15	5.3	1
5			17	5.2	1
10			50 10"	16.8	3
15			50 8"	15.8	3
20			50 8"	15.2	3

REMARKS

DRY TO 19', 1/31/17

CLAY, SANDY, TAN, STIFF TO
 VERY STIFF, MOIST

CLAYSTONE, SANDY, GRAY
 BROWN, HARD, MOIST

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			15	14.8	2
5			36	18.4	2
10			50 9"	12.7	3
15			50 7"	16.0	3
20			50 7"	18.2	3



**ENTECH
 ENGINEERING, INC.**

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN:

DATE:

CHECKED:

DATE:

LLL

4/12/17

JOB NO.:
 170039

FIG NO.:
 B- 4

TEST BORING NO. 9
 DATE DRILLED 1/30/2017
 Job # 170039

TEST BORING NO. 10
 DATE DRILLED 1/30/2017
 CLIENT DAKOTA SPRINGS ENGINEERING
 LOCATION SPRINGS AT WATERVIEW

REMARKS

DRY TO 20', 1/31/17

CLAY, SANDY, GRAY BROWN,
 FIRM TO STIFF, MOIST

CLAYSTONE, SANDY, GRAY
 BROWN, HARD TO VERY STIFF,
 MOIST

WEATHERED ZONE

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			13	11.8	2
5			19	13.5	2
10			17	14.1	2
15			50	17.4	3
20			44	15.8	3

REMARKS

DRY TO 20', 1/31/17

CLAY, SANDY, GRAY BROWN,
 STIFF, MOIST

CLAYSTONE, SANDY, GRAY
 BROWN, HARD TO VERY
 STIFF, MOIST

WEATHERED ZONE

Depth (ft)	Symbol	Samples	Blows per foot	Watercontent %	Soil Type
			18	13.4	2
5			50	10.3	3
10			50 7"	16.5	3
15			50 6"	16.7	3
20			45	20.0	3



**ENTECH
 ENGINEERING, INC.**

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

TEST BORING LOG

DRAWN:

DATE:

CHECKED:

DATE:

LLC

4/12/17


JOB NO.:
 170039

FIG NO.:
 B- 5

APPENDIX C: Laboratory Test Results

UNIFIED CLASSIFICATION	SC	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	1	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	7	JOB NO.	170039
DEPTH (FT)	5	TEST BY	BL

**Sieve Analysis
Grain Size Distribution**



U.S. Sieve #	Percent Finer
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	100.0%
20	98.8%
40	96.9%
100	78.7%
200	48.6%

Atterberg
Limits
Plastic Limit
Liquid Limit
Plastic Index

Swell
Moisture at start
Moisture at finish
Moisture increase
Initial dry density (pcf)
Swell (psf)



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**

DRAWN:

DATE:

CHECKED: *h*


DATE: *2/20/17*

JOB NO.:
170039

FIG NO.:
C-1

<u>UNIFIED CLASSIFICATION</u>	CL	<u>CLIENT</u>	DAKOTA SPRINGS ENGINEERING
<u>SOIL TYPE #</u>	2	<u>PROJECT</u>	SPRINGS AT WATERVIEW
<u>TEST BORING #</u>	1	<u>JOB NO.</u>	170039
<u>DEPTH (FT)</u>	5	<u>TEST BY</u>	BL

**Sieve Analysis
Grain Size Distribution**



<u>U.S. Sieve #</u>	<u>Percent Finer</u>
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	
20	
40	100.0%
100	99.6%
200	93.1%

<u>Atterberg Limits</u>	
Plastic Limit	17
Liquid Limit	38
Plastic Index	21

<u>Swell</u>	
Moisture at start	
Moisture at finish	
Moisture increase	
Initial dry density (pcf)	
Swell (psf)	



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**

<u>DRAWN:</u>	<u>DATE:</u>	<u>CHECKED:</u>	<u>DATE:</u>
		<i>[Signature]</i>	2/10/07


JOB NO.:
170039

FIG NO.:

C-2

UNIFIED CLASSIFICATION	CL	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	2	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	2	JOB NO.	170039
DEPTH (FT)	10	TEST BY	BL

**Sieve Analysis
Grain Size Distribution**



U.S. Sieve #	Percent Finer
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	100.0%
20	99.8%
40	99.3%
100	87.7%
200	64.6%

Atterberg Limits	
Plastic Limit	15
Liquid Limit	29
Plastic Index	14

Swell	
Moisture at start	
Moisture at finish	
Moisture increase	
Initial dry density (pcf)	
Swell (psf)	



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**

DRAWN:

DATE:

CHECKED: *[Signature]*


DATE: *2/10/07*

JOB NO.:
170039

FIG NO.:
C-3

<u>UNIFIED CLASSIFICATION</u>	CL	<u>CLIENT</u>	DAKOTA SPRINGS ENGINEERING
<u>SOIL TYPE #</u>	2	<u>PROJECT</u>	SPRINGS AT WATERVIEW
<u>TEST BORING #</u>	3	<u>JOB NO.</u>	170039
<u>DEPTH (FT)</u>	2-3	<u>TEST BY</u>	BL

**Sieve Analysis
Grain Size Distribution**



<u>U.S. Sieve #</u>	<u>Percent Finer</u>
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	
20	
40	100.0%
100	99.3%
200	87.0%

Atterberg
Limits
Plastic Limit
Liquid Limit
Plastic Index

<u>Swell</u>	
Moisture at start	19.8%
Moisture at finish	23.3%
Moisture increase	3.5%
Initial dry density (pcf)	102
Swell (psf)	690



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**


<u>DRAWN:</u>	<u>DATE:</u>	<u>CHECKED:</u>	<u>DATE:</u>
		<i>[Signature]</i>	2/10/07

JOB NO.:
170039

FIG NO.:
C-4

UNIFIED CLASSIFICATION	CL	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	2	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	5	JOB NO.	170039
DEPTH (FT)	2-3	TEST BY	BL

**Sieve Analysis
Grain Size Distribution**



U.S. Sieve #	Percent Finer
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	
20	
40	100.0%
100	99.7%
200	96.0%

**Atterberg
Limits**
Plastic Limit
Liquid Limit
Plastic Index

Swell
Moisture at start
Moisture at finish
Moisture increase
Initial dry density (pcf)
Swell (psf)



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**


DRAWN:	DATE:	CHECKED:	DATE:
		<i>[Signature]</i>	2/10/12

JOB NO.:
170039

FIG NO.:
C-5

UNIFIED CLASSIFICATION	CL	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	2	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	6	JOB NO.	170039
DEPTH (FT)	2-3	TEST BY	BL

Sieve Analysis Grain Size Distribution



U.S. Sieve #	Percent Finer
3"	100.0%
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	
20	100.0%
40	99.0%
100	93.1%
200	77.6%

Atterberg
Limits
Plastic Limit
Liquid Limit
Plastic Index

<u>Swell</u>	
Moisture at start	11.7%
Moisture at finish	22.5%
Moisture increase	10.8%
Initial dry density (pcf)	102
Swell (psf)	980



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

LABORATORY TEST RESULTS


DRAWN:	DATE:	CHECKED:	DATE:
		<i>[Signature]</i>	2/10/17

JOB NO.:
170039

FIG NO.:
C-6

UNIFIED CLASSIFICATION	CL	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	2	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	9	JOB NO.	170039
DEPTH (FT)	5	TEST BY	BL

Sieve Analysis Grain Size Distribution



U.S.
Sieve #

3"
1 1/2"
3/4"
1/2"
3/8"
4
10
20
40
100
200

Percent
Finer

100.0%
99.1%
93.0%

Atterberg

Limits

Plastic Limit

Liquid Limit

Plastic Index

Swell

Moisture at start

Moisture at finish

Moisture increase

Initial dry density (pcf)

Swell (psf)



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

LABORATORY TEST RESULTS

DRAWN:

DATE:

CHECKED:

DATE:


JOB NO.:
170039

FIG NO.:

C-7

<u>UNIFIED CLASSIFICATION</u>	CL	<u>CLIENT</u>	DAKOTA SPRINGS ENGINEERING
<u>SOIL TYPE #</u>	2	<u>PROJECT</u>	SPRINGS AT WATERVIEW
<u>TEST BORING #</u>	10	<u>JOB NO.</u>	170039
<u>DEPTH (FT)</u>	5	<u>TEST BY</u>	BL

**Sieve Analysis
Grain Size Distribution**



<u>U.S. Sieve #</u>	<u>Percent Finer</u>
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	
20	
40	
100	100.0%
200	98.8%

Atterberg
Limits
Plastic Limit
Liquid Limit
Plastic Index

<u>Swell</u>	
Moisture at start	12.5%
Moisture at finish	25.9%
Moisture increase	13.3%
Initial dry density (pcf)	101
Swell (psf)	1340



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**


DRAWN:	DATE:	CHECKED:	DATE:
		<i>[Signature]</i>	2/20/07

JOB NO.:
170039

FIG NO.:
C-8

UNIFIED CLASSIFICATION	CH	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	3	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	4	JOB NO.	170039
DEPTH (FT)	5	TEST BY	BL

Sieve Analysis Grain Size Distribution



U.S. Sieve #	Percent Finer
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	100.0%
20	99.6%
40	98.8%
100	97.5%
200	86.6%

Atterberg Limits	
Plastic Limit	25
Liquid Limit	54
Plastic Index	29

Swell	
Moisture at start	
Moisture at finish	
Moisture increase	
Initial dry density (pcf)	
Swell (psf)	



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

LABORATORY TEST RESULTS

DRAWN:

DATE:

CHECKED: *am*


DATE: *2/22/17*

JOB NO.:
170039

FIG NO.:
C-9

<u>UNIFIED CLASSIFICATION</u>	CL	<u>CLIENT</u>	DAKOTA SPRINGS ENGINEERING
<u>SOIL TYPE #</u>	3	<u>PROJECT</u>	SPRINGS AT WATERVIEW
<u>TEST BORING #</u>	5	<u>JOB NO.</u>	170039
<u>DEPTH (FT)</u>	10	<u>TEST BY</u>	BL

**Sieve Analysis
Grain Size Distribution**



<u>U.S. Sieve #</u>	<u>Percent Finer</u>
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	100.0%
20	98.6%
40	98.2%
100	97.5%
200	86.0%

<u>Atterberg Limits</u>	
Plastic Limit	20
Liquid Limit	43
Plastic Index	23

<u>Swell</u>	
Moisture at start	
Moisture at finish	
Moisture increase	
Initial dry density (pcf)	
Swell (psf)	



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**

DRAWN:

DATE:

CHECKED: *h*


DATE: *2/10/17*

JOB NO.:
170039

FIG NO.:
C-10

<u>UNIFIED CLASSIFICATION</u>	CL	<u>CLIENT</u>	DAKOTA SPRINGS ENGINEERING
<u>SOIL TYPE #</u>	3	<u>PROJECT</u>	SPRINGS AT WATERVIEW
<u>TEST BORING #</u>	6	<u>JOB NO.</u>	170039
<u>DEPTH (FT)</u>	20	<u>TEST BY</u>	BL

**Sieve Analysis
Grain Size Distribution**



U.S.
Sieve #

3"
1 1/2"
3/4"
1/2"
3/8"
4
10
20
40
100
200

Percent
Finer

100.0%
98.3%

Atterberg

Limits

Plastic Limit

Liquid Limit

Plastic Index

Swell

Moisture at start

Moisture at finish

Moisture increase

Initial dry density (pcf)

Swell (psf)



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**

DRAWN:

DATE:

CHECKED: *LM*

DATE: *2/10/07*


JOB NO.:
170039

FIG NO.:

C-11

UNIFIED CLASSIFICATION	CL	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	3	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	7	JOB NO.	170039
DEPTH (FT)	15	TEST BY	BL

Sieve Analysis Grain Size Distribution



U.S. Sieve #	Percent Finer
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	
20	
40	100.0%
100	98.7%
200	85.3%

Atterberg
Limits
Plastic Limit
Liquid Limit
Plastic Index

Swell
Moisture at start
Moisture at finish
Moisture increase
Initial dry density (pcf)
Swell (psf)



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

LABORATORY TEST RESULTS

DRAWN:

DATE:

CHECKED: *A*


DATE: *2/10/17*

JOB NO.:
170039

FIG NO.:
C-12

UNIFIED CLASSIFICATION	CL	CLIENT	DAKOTA SPRINGS ENGINEERING
SOIL TYPE #	3	PROJECT	SPRINGS AT WATERVIEW
TEST BORING #	8	JOB NO.	170039
DEPTH (FT)	10	TEST BY	BL

**Sieve Analysis
Grain Size Distribution**



U.S. Sieve #	Percent Finer
3"	
1 1/2"	
3/4"	
1/2"	
3/8"	
4	
10	
20	
40	100.0%
100	98.8%
200	87.6%

**Atterberg
Limits**
Plastic Limit
Liquid Limit
Plastic Index

Swell	
Moisture at start	13.4%
Moisture at finish	24.2%
Moisture increase	10.8%
Initial dry density (pcf)	102
Swell (psf)	1880



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

**LABORATORY TEST
RESULTS**

DRAWN:	DATE:	CHECKED:	DATE:
		<i>[Signature]</i>	2/20/07


JOB NO.:
170039

FIG NO.:
C-13

CONSOLIDATION TEST RESULTS

TEST BORING #	1	DEPTH(ft)	5
DESCRIPTION	CL	SOIL TYPE	2
NATURAL UNIT DRY WEIGHT (PCF)			121
NATURAL MOISTURE CONTENT			13.7%
SWELL/CONSOLIDATION (%)			6.4%

JOB NO. 170039
 CLIENT DAKOTA SPRINGS ENGINEERING
 PROJECT SPRINGS AT WATERVIEW



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

SWELL CONSOLIDATION TEST RESULTS

DRAWN:

DATE:

CHECKED:

DATE:

LLL

2/14/17

JOB NO.:
170039


FIG NO.:

C-14

CONSOLIDATION TEST RESULTS

TEST BORING #	2	DEPTH(ft)	10
DESCRIPTION	CL	SOIL TYPE	2
NATURAL UNIT DRY WEIGHT (PCF)	105		
NATURAL MOISTURE CONTENT	8.3%		
SWELL/CONSOLIDATION (%)	-0.3%		

JOB NO. 170039
 CLIENT DAKOTA SPRINGS ENGINEERING
 PROJECT SPRINGS AT WATERVIEW



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

SWELL CONSOLIDATION TEST RESULTS

DRAWN:

DATE:

CHECKED:
LLL

DATE:

2/14/17

JOB NO.:
170039


FIG NO.:

C-15

CONSOLIDATION TEST RESULTS

TEST BORING #	9	DEPTH(ft)	5
DESCRIPTION	CL	SOIL TYPE	2
NATURAL UNIT DRY WEIGHT (PCF)	98		
NATURAL MOISTURE CONTENT	16.9%		
SWELL/CONSOLIDATION (%)	1.6%		

JOB NO. 170039
CLIENT DAKOTA SPRINGS ENGINEERING
PROJECT SPRINGS AT WATERVIEW



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

SWELL CONSOLIDATION TEST RESULTS

DRAWN:

DATE:

CHECKED:
LLL

DATE:
2/14/17


JOB NO.:
170039

FIG NO.:
C-16

CONSOLIDATION TEST RESULTS

TEST BORING #	4	DEPTH(ft)	5
DESCRIPTION	CH	SOIL TYPE	3
NATURAL UNIT DRY WEIGHT (PCF)	114		
NATURAL MOISTURE CONTENT	16.9%		
SWELL/CONSOLIDATION (%)	3.4%		

JOB NO. 170039
 CLIENT DAKOTA SPRINGS ENGINEERING
 PROJECT SPRINGS AT WATERVIEW



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

SWELL CONSOLIDATION TEST RESULTS

DRAWN:

DATE:

CHECKED:

DATE:

LLL

2/14/17


JOB NO.:
170039

FIG NO.:
C-17

CONSOLIDATION TEST RESULTS

TEST BORING #	5	DEPTH(ft)	10
DESCRIPTION	CL	SOIL TYPE	3
NATURAL UNIT DRY WEIGHT (PCF)			109
NATURAL MOISTURE CONTENT			17.7%
SWELL/CONSOLIDATION (%)			2.0%

JOB NO. 170039
 CLIENT DAKOTA SPRINGS ENGINEERING
 PROJECT SPRINGS AT WATERVIEW



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
 COLORADO SPRINGS, COLORADO 80907

SWELL CONSOLIDATION TEST RESULTS

DRAWN:

DATE:

CHECKED:

LLL

DATE:

2/14/17


JOB NO.:
170039

FIG NO.:
C-18

CONSOLIDATION TEST RESULTS

TEST BORING #	6	DEPTH(ft)	20
DESCRIPTION	CL	SOIL TYPE	3
NATURAL UNIT DRY WEIGHT (PCF)	111		
NATURAL MOISTURE CONTENT	19.0%		
SWELL/CONSOLIDATION (%)	3.8%		

JOB NO. 170039
CLIENT DAKOTA SPRINGS ENGINEERING
PROJECT SPRINGS AT WATERVIEW



**ENTECH
ENGINEERING, INC.**

505 ELKTON DRIVE
COLORADO SPRINGS, COLORADO 80907

SWELL CONSOLIDATION TEST RESULTS

DRAWN:

DATE:

CHECKED:
LLL

DATE:
2/14/17

JOB NO.:
170039

FIG NO.:
C-19

APPENDIX D: Soil Survey Descriptions

El Paso County Area, Colorado

8—Blakeland loamy sand, 1 to 9 percent slopes

Map Unit Setting

National map unit symbol: 369v

Elevation: 4,600 to 5,800 feet

Mean annual precipitation: 14 to 16 inches

Mean annual air temperature: 46 to 48 degrees F

Frost-free period: 125 to 145 days

Farmland classification: Not prime farmland

Map Unit Composition

Blakeland and similar soils: 85 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Blakeland

Setting

Landform: Flats, hills

Landform position (three-dimensional): Side slope, talf

Down-slope shape: Linear

Across-slope shape: Linear

Parent material: Alluvium derived from sedimentary rock and/or
eolian deposits derived from sedimentary rock

Typical profile

A - 0 to 11 inches: loamy sand

AC - 11 to 27 inches: loamy sand

C - 27 to 60 inches: sand

Properties and qualities

Slope: 1 to 9 percent

Depth to restrictive feature: More than 80 inches

Natural drainage class: Somewhat excessively drained

Runoff class: Low

Capacity of the most limiting layer to transmit water (Ksat): High to
very high (5.95 to 19.98 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None

Frequency of ponding: None

Calcium carbonate, maximum in profile: 5 percent

Available water storage in profile: Low (about 4.5 inches)

Interpretive groups

Land capability classification (irrigated): 3e

Land capability classification (nonirrigated): 6e

Hydrologic Soil Group: A

Ecological site: Sandy Foothill (R049BY210CO)

Hydric soil rating: No

Minor Components

Other soils

Percent of map unit:

Hydric soil rating: No

Pleasant

Percent of map unit:

Landform: Depressions

Hydric soil rating: Yes

Data Source Information

Soil Survey Area: El Paso County Area, Colorado

Survey Area Data: Version 14, Sep 23, 2016

El Paso County Area, Colorado

31—Fort Collins loam, 3 to 8 percent slopes

Map Unit Setting

National map unit symbol: 3684

Elevation: 5,200 to 6,500 feet

Mean annual precipitation: 14 to 16 inches

Mean annual air temperature: 48 to 52 degrees F

Farmland classification: Not prime farmland

Map Unit Composition

Fort collins and similar soils: 85 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Fort Collins

Setting

Landform: Hills

Landform position (three-dimensional): Side slope

Down-slope shape: Linear

Across-slope shape: Linear

Parent material: Loamy alluvium

Typical profile

A - 0 to 9 inches: loam

Bt - 9 to 16 inches: clay loam

Bk - 16 to 21 inches: clay loam

Ck - 21 to 60 inches: loam

Properties and qualities

Slope: 3 to 8 percent

Depth to restrictive feature: More than 80 inches

Natural drainage class: Well drained

Runoff class: Medium

Capacity of the most limiting layer to transmit water (Ksat):

Moderately high to high (0.57 to 2.00 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None

Frequency of ponding: None

Calcium carbonate, maximum in profile: 15 percent

Salinity, maximum in profile: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)

Available water storage in profile: High (about 10.1 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 6e

Hydrologic Soil Group: B

Ecological site: Loamy Plains (R067BY002CO)

Other vegetative classification: LOAMY PLAINS (069AY006CO)

Hydric soil rating: No

Minor Components

Pleasant

Percent of map unit:

Landform: Depressions

Hydric soil rating: Yes

Other soils

Percent of map unit:

Hydric soil rating: No

Data Source Information

Soil Survey Area: El Paso County Area, Colorado

Survey Area Data: Version 14, Sep 23, 2016

El Paso County Area, Colorado

52—Manzanst clay loam, 0 to 3 percent slopes

Map Unit Setting

National map unit symbol: 2w4nr

Elevation: 4,060 to 6,660 feet

Mean annual precipitation: 14 to 16 inches

Mean annual air temperature: 50 to 54 degrees F

Frost-free period: 130 to 170 days

Farmland classification: Prime farmland if irrigated

Map Unit Composition

Manzanst and similar soils: 85 percent

Minor components: 15 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Manzanst

Setting

Landform: Terraces, drainageways

Landform position (three-dimensional): Tread

Down-slope shape: Linear

Across-slope shape: Linear, concave

Parent material: Clayey alluvium derived from shale

Typical profile

A - 0 to 3 inches: clay loam

Bt - 3 to 12 inches: clay

Btk - 12 to 37 inches: clay

Bk1 - 37 to 52 inches: clay

Bk2 - 52 to 79 inches: clay

Properties and qualities

Slope: 0 to 3 percent

Depth to restrictive feature: More than 80 inches

Natural drainage class: Well drained

Capacity of the most limiting layer to transmit water (Ksat):

Moderately low to moderately high (0.06 to 0.20 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None

Frequency of ponding: None

Calcium carbonate, maximum in profile: 15 percent

Gypsum, maximum in profile: 3 percent

Salinity, maximum in profile: Slightly saline (4.0 to 7.0 mmhos/cm)

Sodium adsorption ratio, maximum in profile: 10.0

Available water storage in profile: High (about 9.0 inches)

Interpretive groups

Land capability classification (irrigated): 3e

Land capability classification (nonirrigated): 4c

Hydrologic Soil Group: C
Ecological site: Saline Overflow (R067BY037CO)
Hydric soil rating: No

Minor Components

Ritoazul

Percent of map unit: 7 percent
Landform: Drainageways, interfluves
Landform position (three-dimensional): Rise
Down-slope shape: Linear
Across-slope shape: Linear
Ecological site: Clayey Plains (R067BY042CO)
Hydric soil rating: No

Arvada

Percent of map unit: 6 percent
Landform: Drainageways, interfluves
Down-slope shape: Linear
Across-slope shape: Linear
Ecological site: Salt Flat (R067XY033CO)
Hydric soil rating: No

Wiley

Percent of map unit: 2 percent
Landform: Interfluves
Down-slope shape: Linear
Across-slope shape: Linear
Ecological site: Loamy Plains (R067BY002CO)
Hydric soil rating: No

Data Source Information

Soil Survey Area: El Paso County Area, Colorado
Survey Area Data: Version 14, Sep 23, 2016

El Paso County Area, Colorado

56—Nelson-Tassel fine sandy loams, 3 to 18 percent slopes

Map Unit Setting

National map unit symbol: 3690

Elevation: 5,600 to 6,400 feet

Mean annual precipitation: 12 to 14 inches

Mean annual air temperature: 48 to 52 degrees F

Frost-free period: 135 to 155 days

Farmland classification: Not prime farmland

Map Unit Composition

Nelson and similar soils: 45 percent

Tassel and similar soils: 30 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Nelson

Setting

Landform: Hills

Landform position (three-dimensional): Crest, side slope

Down-slope shape: Linear

Across-slope shape: Linear

Parent material: Calcareous residuum weathered from interbedded sedimentary rock

Typical profile

A - 0 to 5 inches: fine sandy loam

Ck - 5 to 23 inches: fine sandy loam

Cr - 23 to 27 inches: weathered bedrock

Properties and qualities

Slope: 3 to 12 percent

Depth to restrictive feature: 20 to 40 inches to paralithic bedrock

Natural drainage class: Well drained

Runoff class: Medium

Capacity of the most limiting layer to transmit water (Ksat):

Moderately low to high (0.06 to 2.00 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None

Frequency of ponding: None

Calcium carbonate, maximum in profile: 10 percent

Salinity, maximum in profile: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)

Available water storage in profile: Very low (about 2.8 inches)

Interpretive groups

Land capability classification (irrigated): 4e

Land capability classification (nonirrigated): 6e

Hydrologic Soil Group: B

Ecological site: Shaly Plains (R067BY045CO)
Other vegetative classification: SHALY PLAINS (069AY046CO)
Hydric soil rating: No

Description of Tassel

Setting

Landform: Hills
Landform position (three-dimensional): Crest, side slope
Down-slope shape: Linear
Across-slope shape: Linear
Parent material: Calcareous slope alluvium over residuum
weathered from sandstone

Typical profile

A - 0 to 4 inches: fine sandy loam
C - 4 to 10 inches: fine sandy loam
Cr - 10 to 14 inches: weathered bedrock

Properties and qualities

Slope: 3 to 18 percent
Depth to restrictive feature: 6 to 20 inches to paralithic bedrock
Natural drainage class: Well drained
Runoff class: Medium
Capacity of the most limiting layer to transmit water (Ksat):
Moderately high (0.20 to 0.60 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum in profile: 10 percent
Available water storage in profile: Very low (about 1.2 inches)

Interpretive groups

Land capability classification (irrigated): None specified
Land capability classification (nonirrigated): 6s
Hydrologic Soil Group: D
Ecological site: Shaly Plains (R067BY045CO)
Other vegetative classification: SHALY PLAINS (069AY046CO)
Hydric soil rating: No

Minor Components

Other soils

Percent of map unit:
Hydric soil rating: No

Pleasant

Percent of map unit:
Landform: Depressions

Hydric soil rating: Yes

Data Source Information

Soil Survey Area: El Paso County Area, Colorado

Survey Area Data: Version 14, Sep 23, 2016

El Paso County Area, Colorado

86—Stoneham sandy loam, 3 to 8 percent slopes

Map Unit Setting

National map unit symbol: 36b2
Elevation: 5,100 to 6,500 feet
Mean annual precipitation: 13 to 15 inches
Mean annual air temperature: 48 to 52 degrees F
Frost-free period: 135 to 155 days
Farmland classification: Not prime farmland

Map Unit Composition

Stoneham and similar soils: 85 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Stoneham

Setting

Landform: Hills
Landform position (three-dimensional): Side slope
Down-slope shape: Linear
Across-slope shape: Linear
Parent material: Calcareous loamy alluvium

Typical profile

A - 0 to 4 inches: sandy loam
Bt - 4 to 8 inches: sandy clay loam
Btk - 8 to 11 inches: sandy clay loam
Ck - 11 to 60 inches: loam

Properties and qualities

Slope: 3 to 8 percent
Depth to restrictive feature: More than 80 inches
Natural drainage class: Well drained
Runoff class: Medium
Capacity of the most limiting layer to transmit water (Ksat):
Moderately high to high (0.60 to 2.00 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum in profile: 15 percent
Salinity, maximum in profile: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)
Available water storage in profile: High (about 9.5 inches)

Interpretive groups

Land capability classification (irrigated): 3e
Land capability classification (nonirrigated): 4e
Hydrologic Soil Group: B
Ecological site: Sandy Plains (R067BY024CO)

Other vegetative classification: SANDY PLAINS (069AY026CO)

Hydric soil rating: No

Minor Components

Pleasant

Percent of map unit:

Landform: Depressions

Hydric soil rating: Yes

Other soils

Percent of map unit:

Hydric soil rating: No

Data Source Information

Soil Survey Area: El Paso County Area, Colorado

Survey Area Data: Version 14, Sep 23, 2016

El Paso County Area, Colorado

108—Wiley silt loam, 3 to 9 percent slopes

Map Unit Setting

National map unit symbol: 367b
Elevation: 5,200 to 6,200 feet
Mean annual precipitation: 12 to 14 inches
Mean annual air temperature: 48 to 52 degrees F
Frost-free period: 135 to 155 days
Farmland classification: Not prime farmland

Map Unit Composition

Wiley and similar soils: 85 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Wiley

Setting

Landform: Hills
Landform position (three-dimensional): Side slope
Down-slope shape: Linear
Across-slope shape: Linear
Parent material: Calcareous silty eolian deposits

Typical profile

A - 0 to 4 inches: silt loam
Bt - 4 to 16 inches: silt loam
Bk - 16 to 60 inches: silt loam

Properties and qualities

Slope: 3 to 9 percent
Depth to restrictive feature: More than 80 inches
Natural drainage class: Well drained
Runoff class: Medium
Capacity of the most limiting layer to transmit water (Ksat):
Moderately high to high (0.60 to 2.00 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum in profile: 15 percent
Salinity, maximum in profile: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)
Available water storage in profile: High (about 11.5 inches)

Interpretive groups

Land capability classification (irrigated): 4e
Land capability classification (nonirrigated): 6e
Hydrologic Soil Group: B
Ecological site: Loamy Plains (R067BY002CO)
Other vegetative classification: LOAMY PLAINS (069AY006CO)

Hydric soil rating: No

Minor Components

Pleasant

Percent of map unit:

Landform: Depressions

Hydric soil rating: Yes

Other soils

Percent of map unit:

Hydric soil rating: No

Data Source Information

Soil Survey Area: El Paso County Area, Colorado

Survey Area Data: Version 14, Sep 23, 2016