MDT-SF21026-R4-FDR.pdf Markup Summary

1 (2)

Subject: Stormwater Comments Color

Page Index: 1

Date: 2/2/2022 2:18:07 PM

Author: dotprete

Color: Layer: Space: Page Label: 1

Subject: PCD Comment Legend

Page Index: 1

Date: 2/2/2022 5:52:08 PM

Author: dsdrice

Color: Layer: Space:

Page Label: 1

7 (1)

Subject: Callout Page Index: 7

Date: 1/24/2022 11:10:40 AM

Author: CDurham

Color: Layer: Space: Page Label: 7 13.3 and 18.0 cfs

8 (1)

Subject: Text Box Page Index: 8

Date: 1/24/2022 4:36:08 PM

Author: CDurham

Color: Layer: Space: Page Label: 8 How does the water cross the street to head towards the pond? Swale to direct flow if it crosses

the road?

9 (3)

Lots 70-73. Flows generated by this basin i by a 2'x6" concrete swale along the lot of the slope. These flows are directed to the

Subject: Callout Page Index: 9

Date: 1/24/2022 11:16:33 AM

Author: CDurham

Color: Layer: Space: Page Label: 9 Include what flow is for each of these basins.

storm pipe and are conveyed tow e southeast. The flows from Basin A11 aptured by this inlet (N), with emerge

manhole within Tract A. This design paid discharges to the northeast via 43° are Qs=54.8° cts and Qt0=119.4° cts. To the north pond.

Subject: Text Box Page Index: 9

Date: 1/24/2022 4:36:34 PM

Author: CDurham

Color: Layer: Space: Page Label: 9

Swale to direct flows?

ane and Wyedale Way. The floconveyed towards the propose es all the flows from Basins B1 cfs. Where and how does

overflow go? If the property of the property

Subject: Text Box Page Index: 9

Date: 1/24/2022 4:37:20 PM

Author: CDurham

Color: Layer: Space: Page Label: 9 Where and how does overflow go?

13 (1)

esented in this report

Subject: Text Box Page Index: 13

Date: 1/24/2022 1:35:54 PM

Author: CDurham

Color: Layer: Space:

Page Label: 13

Include table for interim condition.

159 (1)

Subject: Text Box Page Index: 159

Date: 1/24/2022 3:21:48 PM

Author: CDurham

Color: Layer: Space:

Page Label: 159

Include layouts for all storm systems

212 (1)



Subject: Callout Page Index: 212

Date: 1/24/2022 1:30:24 PM

Author: CDurham

Color: Layer: Space:

Page Label: 212

This should be ~1 Small adjustment to overflow weir elevations should get to the requirement

227 (1)

Label for what culvert this is for

Subject: Text Box Page Index: 227

Date: 1/24/2022 4:41:47 PM

Author: CDurham

Color: Layer: Space:

Page Label: 227

Label for what culvert this is for

228 (2)

Add additional contour labels for existing and proposed contours Subject: Text Box Page Index: 228

Date: 1/24/2022 1:41:01 PM

Author: CDurham

Color: Layer: Space:

Page Label: 228

Add additional contour labels for existing and proposed contours

note section

cook near

make sure

serily per match

Subject: Callout Page Index: 228

Date: 2/1/2022 10:01:44 AM

Author: dsdrice Color: Layer: Space:

Page Label: 228

make sure linetypes match

229 (6)



Subject: Callout Page Index: 229

Date: 1/24/2022 4:29:04 PM

Author: CDurham

Color: Layer: Space:

Page Label: 229

Delete

Subject: Callout Page Index: 229

Date: 1/24/2022 1:56:12 PM

Author: CDurham

Color: Layer: Space:

Page Label: 229

Label structure



Subject: Callout Page Index: 229

Date: 1/24/2022 1:56:15 PM

Author: CDurham

Color: Layer: Space:

Page Label: 229

What is radius? Maintenance access needs to be

within 25' of all forebays, outlets, etc.



Subject: Callout Page Index: 229

Date: 1/24/2022 2:03:34 PM

Author: CDurham

Color: Layer:

Page Label: 229

How is access for maintenance being achieved for

this forebay?



Subject: Callout Page Index: 229


Date: 1/24/2022 4:30:59 PM

Author: CDurham

Color: Layer: Space:

Page Label: 229

UDSewer has pipes still listed as 43x68 ellipticals. Please coordinate between design and plans.



Subject: Callout Page Index: 229

Date: 1/24/2022 4:46:53 PM

Author: CDurham

Color: Layer: Space:

Page Label: 229

Missing pipe size

230 (2)



Subject: Callout Page Index: 230

Date: 1/24/2022 2:00:01 PM

Author: CDurham

Color: Layer: Space:

Page Label: 230

Label ex inlet



Subject: Callout Page Index: 230

Date: 1/24/2022 2:01:16 PM

Author: CDurham

Color: Layer: Space:

Page Label: 230

Fix cut off text

231 (6)



Subject: Callout Page Index: 231

Date: 1/24/2022 1:48:47 PM

Author: CDurham

Color: Layer: Space:

Page Label: 231

Label existing storm



Subject: Callout Page Index: 231

Date: 1/24/2022 1:49:47 PM

Author: CDurham

Color: Layer: Space:

Page Label: 231

Label existing storm

Fix cut off text

Subject: Callout Page Index: 231

Date: 1/24/2022 2:08:07 PM

Author: CDurham

Color: Layer: Space:

Page Label: 231

Fix cut off text

Subject: Callout Page Index: 231

Date: 1/24/2022 2:09:29 PM

Author: CDurham

Color: Layer: Space:

Page Label: 231

Label existing storm

may be used to the second of t

Subject: Callout Page Index: 231

Date: 1/24/2022 4:20:35 PM

Author: CDurham

Color: Layer: Space:

Page Label: 231

Include design of this system in UDSewer



Subject: Text Box Page Index: 231

Date: 1/24/2022 4:49:56 PM

Author: CDurham

Color: Layer: Space:

Page Label: 231

Include analysis of this swale to show 2' section

can convey flows.

232 (3)

WILL REQUIRE REPL TRMATION OF DESIGN. THIS ARE, TAIN IMPERVIOUS, O ECTED TOWARDS TH 1 FACILITY.

Subject:

Page Index: 232

Date: 2/1/2022 10:03:33 AM

Author: dsdrice Color: Layer: Space:

Page Label: 232



Subject: Callout Page Index: 232

Date: 2/1/2022 10:07:10 AM

Author: dsdrice
Color: Layer:
Space:

Page Label: 232

pervious/ permeable

Subject: Engineer Page Index: 232
Date: 2/2/2022 1:54:35 PM
Author: dotprete
Color: ■

Layer: Space:

Page Label: 232

Since this area will be graded and undeveloped for this phase of work, change to Remaining

Undeveloped hatching.