# ENG-PUDSP21002-R2-CDs-Storm.pdf Markup Summary

13 (1)

Subject: Callout
Page Index: 13
Date: 8/6/2021 12:49:29 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 13

Move the forebay as far from the pond outlet as possible

14 (1)

Subject: Callout
Page Index: 14
Date: 8/6/2021 12:50:11 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 14

Verify that the inlets aren't too close to the ped ramps with depresssions...