ENG-SP19003-R4-PDR-redlines.pdf Markup Summary

7 (1)

A manhole is required?

Subject: Callout
Page Index: 7
Date: 2/10/2021 2:47:35 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 7

A manhole is required?

9 (1)

NC2?

Subject: Callout
Page Index: 9
Date: 2/10/2021 3:53:18 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 9

NC2?

11 (1)

south

Subject: Callout
Page Index: 11
Date: 2/10/2021 3:57:56 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 11

south

12 (1)

area of the Type C inlet?

Subject: Callout
Page Index: 12
Date: 2/10/2021 3:59:59 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 12

area of the Type C inlet?

13 (1)

And the geotechnical report recommendations

Subject: Callout
Page Index: 13
Date: 2/10/2021 4:02:11 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 13

And the geotechnical report recommendations

180 (3)

Subject: Arrow
Page Index: 180
Date: 2/10/2021 2:18:22 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 180

Subject: Callout
Page Index: 180
Date: 2/10/2021 2:19:13 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 180

show emergency overflow path and grading

Subject: Callout
Page Index: 180
Date: 2/10/2021 2:43:12 PM
Author: dsdrice
Color: ■
**Layer:**
Space:
Page Label: 180

show pipe

181 (3)

Subject: Callout
Page Index: 181
Date: 2/10/2021 2:15:44 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 181

contours are cut off - show all

Subject: Callout
Page Index: 181
Date: 2/10/2021 3:42:51 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 181

Proposed 24" RCP

Subject: Callout
Page Index: 181
Date: 2/10/2021 3:59:17 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 181

label inlet