

Markup Summary

dsdgrimm (3)


MAP NUMBERS FOR THE FLOODS INDICATED ON THE FLOODS IN PASO COUNTY: COLORADO AND IBERS 08041C0276 F & 08041C0278 F

Map numbers for the site are 08041C0260 F & 08041C02676 F

WHEN ON THE PLAN WAS PREPARED BY


Subject: Engineer
Page Label: [1] 61092-GEC-CS-CS
Author: dsdgrimm
Date: 5/21/2018 5:01:59 PM
Color: ■

Map numbers for the site are 08041C0260 F & 08041C02676 F



Subject: Engineer
Page Label: [3] 61092-GEC-EC-EC
Author: dsdgrimm
Date: 5/30/2018 10:09:26 AM
Color: ■

Provide letter of approval to work in the adjacent property.



Subject: Callout
Page Label: [2] 61092-GEC-GP-GP
Author: dsdgrimm
Date: 5/31/2018 8:48:03 AM
Color: ■

Based on the existing contours, discharge from the outfall and spillway location appears to be directed to the existing structure downstream on the adjacent property; therefore this does not appear to be a suitable outfall.

Additionally, provide a copy of a written approval from the adjacent property owner for the proposed off-site improvement.

Unresolved

dsdlaforce (1)

Per ECM 3.2.4, a suitable outfall refers to a stream which is a hydraulically adequate natural stream or channel segment. Therefore provide conveyance from the outfall to the existing creek.

Subject: Text Box
Page Label: [2] 61092-GEC-GP-GP
Author: dsdlaforce
Date: 5/30/2018 4:58:53 PM
Color: ■

Per ECM 3.2.4, a suitable outfall refers to a stream which is a hydraulically adequate historic natural stream or channel segment. Therefore provide conveyance from the outfall to the existing creek.