

ENG-CDR21010-R3-GEC-Vollmer-North.pdf Markup Summary


1 (1)

Comments remain cursory.

Subject: Text Box
Page Index: 1
Date: 4/11/2022 1:32:58 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] 1 2518800 Vollmer North GESC-CV01 -
Vollmer GESC CV01

Comments remain cursory.


2 (1)



Subject: Callout
Page Index: 2
Date: 4/11/2022 1:19:28 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [2] 2 INITIAL - GR01-1 (3)

BMP in ditch?


3 (1)



Subject: Callout
Page Index: 3
Date: 4/11/2022 1:22:19 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [3] 3 INITIAL - GR01-1 (2)


Silt fence isn't appropriate if it will channelize runoff.

9 (2)




Subject: Callout
Page Index: 9
Date: 3/29/2022 2:09:25 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [9] 9 INTERIM - GR01-2

Unresolved:
Contours aren't tying in - Show all grading




Subject: Callout
Page Index: 9
Date: 3/29/2022 2:10:38 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [9] 9 INTERIM - GR01-2

Unresolved:
Verify grading per cross-sections (is a berm/double ditch needed here?)




Subject: Callout
Page Index: 10
Date: 4/11/2022 1:27:52 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [10] 10 FINAL - GR01-1

PS



Subject: Text Box
Page Index: 10
Date: 4/11/2022 1:28:15 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [10] 10 FINAL - GR01-1

Add permanent seeding and mulching



Subject: Callout
Page Index: 10
Date: 4/11/2022 1:29:57 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [10] 10 FINAL - GR01-1

Add parcel info