

November 29, 2018

Erin Ganaway N.E.S. Inc. 619 North Cascade Avenue, Suite 200 Colorado Springs, CO 80903 eganaway@nescolorado.com

RE: Redtail Ranch Subdivision

Transportation Memo, El Paso County, CO

Dear Ms. Ganaway:

Per your request, CLH Associates completed this Transportation Memo for the proposed Redtail Ranch Subdivision in unincorporated El Paso County, CO. The proposed development would subdivide existing lands into plots for a total of 12 single family units. The site is in unincorporated El Paso County, with proposed primary access to Vollmer Road between Shoup Road and Swan Road. A secondary access is proposed leading to Swan Road. For the purposes of this analysis, all traffic is assumed to enter and exit via Vollmer Road. While there may be some cross traffic between Redtail Ranch and the development to the north along Ward Lane, we do not anticipate that it will be significant and would mostly even out. As such, the Ward Lane intersection with Swan Road did not need to be investigated for this memo. No improvements to Ward Road are needed.

Traffic counts were collected during the morning and evening peak periods on Wednesday and Thursday, March 14th and 15th, 2018, on Vollmer Road at the proposed access location. Peak hours are highlighted.

Time Period	Northbound	Southbound			
7:00 – 7:15 am	9	24			
7:15 – 7:30 am	<mark>13</mark>	<mark>37</mark>			
7:30 – 7:45 am	<mark>11</mark>	<mark>32</mark>			
7:45 – 8:00 am	<mark>14</mark>	<mark>25</mark>			
8:00 – 8:15 am	<mark>13</mark>	<mark>12</mark>			
8:15 – 8:30 am	16	25			
8:30 – 8:45 am	16	21			
8:45 – 9:00 am	13	19			
4:00 – 4:15 pm	19	11			
4:15 – 4:30 pm	20	14			
4:30 – 4:45 pm	29	15			
4:45 – 5:00 pm	<mark>16</mark>	<mark>21</mark>			
5:00 – 5:15 pm	<mark>29</mark>	<mark>11</mark>			
5:15 – 5:30 pm	<mark>18</mark>	<mark>12</mark>			
5:30 – 5:45 pm	<mark>33</mark>	<mark>18</mark>			
5:45 – 6:00 pm	23	13			



Traffic operations were analyzed using methodologies in the Transportation Research Board's <u>Highway Capacity Manual</u> 6th Edition (HCM) and the Synchro software (Version 10). Level of Service (LOS) for this section of Vollmer Road was calculated using procedures in Chapter 15 – Two Lane Highway of the HCM. The calculation is based on the actual average travel speed (affected by factors such as volume, percent trucks, rolling terrain, and percent of no passing zones) compared to the free flow speed (speed limit is 45 mph). Due to the very low volumes on this section of roadway, the factors mentioned above have an insignificant effect on travel speeds. LOS was determined to be "A" for both peak hours. This matched field observations which showed no slowing of traffic. This LOS is not anticipated to change with the low trip generation forecast for this development (see below).


Given the low existing traffic volumes and expected completion year for this development being 2019, there will be negligible background traffic growth. No background traffic increase was assumed for this memo and analysis.

The proposed trip generation is presented below. Average trip generation rates presented in the ITE <u>Trip Generation</u> <u>Manual</u>, 9th edition, 2012, for Land Use Code 210 (single-family detached housing), were used.

<u>Trip Generation Rates</u>						<u>Trip Generation</u>				
	Average	AM Peak Hour		PM Peak Hour		Average	AM Peak Hour		PM Peak Hour	
<u>Units</u>	Weekday	In	Out	In	Out	Weekday	In	Out	In	Out
12	9.52	.188	.563	.63	.37	114	2	7	8	4

The diagram at right presents the AM and PM peak hour volumes at the new proposed development access (to be named Sanctuary Pine Drive) intersection with Vollmer Road. PM volumes are shown in parentheses. The distribution of traffic was assumed to follow the existing traffic patterns on Vollmer Road. Analysis using Synchro indicates that LOS "A" will be experienced during both the AM and PM peak hours. Intersection analysis printouts are attached to this memo.

The proposed location of Sanctuary Pine Drive is appropriate. Two small vertical curves exist on either side of the proposed access, but neither is high enough to block intersection or stopping sight distance for cars. Intersection and stopping sight distance standards for a 50-mph design speed, according to "El Paso County Engineering Criteria Manual", 12/13/16 Revision 6, are listed



below, along with the field measured actual sight distances. It should be noted that the measured sight distance indicated below is to see a 4.25-foot target car traveling down the road or stopped to turn left into Sanctuary Pine Drive. Stopping sight distance is usually measured for a 1/2-foot target object height. The small vertical curves on either side of the driveway would block seeing a 2-foot high object, but not a stopped car. The Preliminary Site Plan shows the proposed location of the Sanctuary Pine Drive Access so lanes align properly with the proposed access on the east side.

Standards

Intersection Sight Distance – Left Turning Vehicles with "Stop" Sign Control: 555 feet Intersection Sight Distance – Right Turning Vehicles with "Stop" Sign Control: 480 feet Stopping Sight Distance: 425 feet

Measured Sight Distance

Sight Distance to the North: >2,000 feet

Sight Distance to the South: >1,600 feet (to Shoup Road)



The El Paso County requirements for exclusive left turn and right turn lanes were also examined. For a Collector road like Vollmer Road, a left turn lane is required for any access with a projected peak hour ingress turning volume of 25 vehicles per hour (vph) or greater. Only 5 vph is forecast to make the left turn. A right turn lane is required for any access with a projected peak hour right turning volume of 50 vehicles per hour (vph) or greater. Only 3 vph is forecast to make the right turn. Therefore, left and right turn lanes are not required and neither are any acceleration or deceleration lanes. No additional signing and striping is needed except what is standard for a residential side street of this type.

There are currently no on-road or roadside facilities for pedestrians or bicycles in this area. To the best of our knowledge, there are no neighborhood or public input issues associated with this development.


We trust that this information will assist you in obtaining approvals for this subdivision. Please let me know if you have any questions or need additional information.

Sincerely,

CLH Associates LLC

Chuck Huffine, P.E., PTOE, AICP

President



Address Vollmer Road pavement condition, width, shoulders... Are improvements necessary at the Sanctuary Pine intersection to bring Vollmer up to County criteria? Vollmer Road appears to be only 23 feet wide on the plans, without defined shoulders. Provide recommendations for pavement widening and shoulder improvements, both north and south of Sanctuary Pine Drive, to bring Vollmer Road up to ECM standards for the speed limit around the access for safety. (unresolved previous comments)

Replace Synchro sheets

Markup Summary

dsdrice (3)

Subject: Callout Page Label: 3 Author: dsdrice

Date: 12/31/2018 10:16:12 AM

Color:

provide date

Replace Synchro sheets

Subject: Text Box Page Label: 3 Author: dsdrice

Date: 12/31/2018 10:16:36 AM

Color:

Subject: Text Box Page Label: 3 Author: dsdrice

Date: 12/31/2018 10:30:49 AM

Color:

Address Vollmer Road pavement condition, width, shoulders... Are improvements necessary at the Sanctuary Pine intersection to bring Vollmer up to County criteria? Vollmer Road appears to be only 23 feet wide on the plans, without defined shoulders. Provide recommendations for pavement widening and shoulder improvements, both north and south of Sanctuary Pine Drive, to bring Vollmer Road up to ECM standards for the speed limit around the access for safety.

(unresolved previous comments)