ENG-CDR19004-R2-FDR-Redlines .pdf Markup Summary



Subject: Callout reference Filing 2 FDR Page Index: 4 Date: 7/16/2020 10:30:06 AM Author: dsdrice Color: Layer: Space: Page Label: 4 Subject: Callout Needs to be in this report. Page Index: 4 Date: 7/16/2020 12:14:28 PM Author: dsdrice Color: Layer: Space: Page Label: 4 6 (4) Subject: Callout ter quality capture volume to slow the relea ultimately er Quality Policy & Procedu and does not directly discha Page Index: 6 Date: 7/16/2020 12:07:51 PM ultimately Author: dsdrice PS. The Falcon DBPS also flows from basin MT060 an Color: Layer: Space: Page Label: 6 Subject: Callout Not correct - flows will enter the east side of Pond Page Index: 6 SR4 west of the new road "Falcon Market Place"; Date: 7/16/2020 12:08:45 PM also, Pond SR4 is currently under construction. Author: dsdrice Color: 📘 Layer: Space: Page Label: 6 Subject: Callout and upstream basin Page Index: 6 Date: 7/16/2020 12:09:09 PM Author: dsdrice Color: Layer: Space: Page Label: 6 Subject: " bypass future Pond SR-4 and go Page Index: 6 directly to Pond MN Date: 7/16/2020 12:09:36 PM Author: dsdrice Color: Layer: Space: Page Label: 6

7 (4)		
	Subject: Highlight Page Index: 7 Date: 7/16/2020 12:10:05 PM Author: dsdrice Color: Layer: Space: Page Label: 7	
iprap pads es.	Subject: Highlight Page Index: 7 Date: 7/16/2020 12:10:37 PM Author: dsdrice Color: Layer: Space: Page Label: 7	
The Barra Cases strengthment Has instructional on the strength of the strength of the strength of the strength of the stren	Subject: Callout Page Index: 7 Date: 7/16/2020 12:12:21 PM Author: dsdrice Color: Layer: Space: Page Label: 7	The Bent Grass development has routed more flow to the road; what improvements are necessary to stabilize the roadside channel?
	Subject: Highlight Page Index: 7 Date: 7/16/2020 12:13:43 PM Author: dsdrice Color: Layer: Space: Page Label: 7	
8 (3)		
improvements made to the site with Pord SR-4. A corp of the report fin previously, the "School Site" flows west side of Meridian Road. This e bypasses future Pond SR-4. From Galloway & Company, Inc.	Subject: Page Index: 8 Date: 7/16/2020 12:16:23 PM Author: dsdrice Color: Layer: Space: Page Label: 8	bypasses future Pond SR-4
rsly, the "School Site" flows within E de of Meridan Road. This existing i es future Pond SR-4. From the ana enters y & Company, Inc.	Subject: Callout Page Index: 8 Date: 7/16/2020 12:16:46 PM Author: dsdrice Color: Layer: Space: Page Label: 8	enters



Subject: Callout Page Index: 8 Date: 7/16/2020 2:32:10 PM Author: dsdrice Color: Layer: Space: Page Label: 8

Address the interim condition with the added flows. Is interim protection proposed?

.....

9 (3)

sin MT070's Curve Number ntering existing Pond MN rema Subject: Page Index: 9 Date: 7/16/2020 12:17:17 PM Author: dsdrice Color: Layer: Space: Page Label: 9

g existing Pond MN

species the special species of the special s

Subject: Cloud+ Page Index: 9 Date: 7/16/2020 2:29:00 PM Author: dsdrice Color: Layer: Space: Page Label: 9

within?

Subject: Page Index: 9 Date: 7/16/2020 2:29:58 PM Author: dsdrice Color: Layer: Space: Page Label: 9

.

.

21 (2)



Subject: Arrow Page Index: 21 Date: 7/16/2020 2:18:17 PM Author: dsdrice Color: Layer: Space: Page Label: 21



Subject: Arrow Page Index: 21 Date: 7/16/2020 2:18:27 PM Author: dsdrice Color: Layer: Space: Page Label: 21

22 (3)



Layer: Space: Page Label: 43

	Subject: Page Index: 43 Date: 7/16/2020 2:07:43 PM Author: dsdrice Color: Layer: Space: Page Label: 43 Subject: Text Box Page Index: 43 Date: 7/16/2020 2:11:13 PM	4.00 Address proposed stabilization.
	Author: dsdrice Color: Layer: Space: Page Label: 43	
83 (1)		
Needrage and inflow data.	Subject: Callout Page Index: 83 Date: 7/16/2020 2:03:03 PM Author: dsdrice Color: Layer: Space: Page Label: 83	Needs more storage and inflow data.
84 (1)		
No. Sector No. Sector No. Sector No. Sector	Subject: Text Box Page Index: 84 Date: 7/16/2020 2:02:33 PM Author: dsdrice Color: Layer: Space: Page Label: 84	I don't think these calculations are valid or useful.
85 (1)		
Someting is wrong with calculations (pord volume)	Subject: Callout Page Index: 85 Date: 7/16/2020 1:58:42 PM Author: dsdrice Color: Layer: Space: Page Label: 85	Something is wrong with calculations (pond volume)
88 (6)		
Please rotate clockwise	Subject: Text Box Page Index: 88 Date: 7/16/2020 1:53:00 PM Author: dsdrice Color: Layer: Space: Page Label: 88	Please rotate clockwise



Subject: Page Index: 88 Date: 7/16/2020 1:54:41 PM Author: dsdrice Color: Layer: Space: Page Label: 88



Subject: Page Index: 88 Date: 7/16/2020 1:54:42 PM Author: dsdrice Color: Layer: Space: Page Label: 88

.

- - - - - - - - - - - - -

.



Subject: Page Index: 88 Date: 7/16/2020 1:54:43 PM Author: dsdrice Color: Layer: Space: Page Label: 88



Subject: Callout Page Index: 88 Date: 7/16/2020 1:55:16 PM Author: dsdrice Color: Layer: Space: Page Label: 88

.....

.....

Provide DPs on north ditch, north and south sides of BGM Dr. and south ditch



Subject: Page Index: 88 Date: 7/16/2020 1:55:44 PM Author: dsdrice Color: Layer: Space: Page Label: 88

89 (4)



Subject: Page Index: 89 Date: 7/16/2020 1:55:35 PM Author: dsdrice Color: Layer: Space: Page Label: 89



Subject: Page Index: 89 Date: 7/16/2020 1:55:36 PM Author: dsdrice Color: Layer: Space: Page Label: 89

.



Subject: Page Index: 89 Date: 7/16/2020 1:55:37 PM Author: dsdrice Color: Layer: Space: Page Label: 89



Subject: Page Index: 89 Date: 7/16/2020 1:55:39 PM Author: dsdrice Color: Layer: Space: Page Label: 89

90 (1)

91 (3)



UNPLATTED

Subject: Callout Page Index: 90 Date: 7/16/2020 1:51:24 PM Author: dsdrice Color: L Layer: Space: Page Label: 90

Address the basins and DP flowing from the west



Layer: Space: Page Label: 91

DIS

10.057

14000ED 160-00-

(2) MOTORD 6"

Subject: Callout Page Index: 91 Date: 7/16/2020 1:51:08 PM Author: dsdrice Color: Layer: Space: Page Label: 91

Address the basins and DP flowing from the west

Page Index: 91 Date: 7/16/2020 12:22:15 PM Flows to Pond SR4



Subject: Callout Page Index: 91 Date: 7/16/2020 12:23:22 PM Author: dsdrice Color: Layer: Space: Page Label: 91

Existing/adjusted riprap