FIRE PROTECTION REPORT

Date:10/28/2020RE:847 Struthers Ranch Road Plat Amendment

Please revise the fire protection report per the newly revised Land Development Code standards on fire protection reports, which was just amended in early 2021.

Please refer to PDF page 10 and onward
for the Fire Protection and WildfireThe above-referenced property is located within the jurisdictioMitigation Section 6.3.3, and provide an
analysis of the applicable fire code.

rating of 3 for hydrant areas and 3Y for rural, non-hydran Link: station to the above referenced project location is Station

https://assets-planningdevelopment.elpaso co.com/wp-content/uploads/LDC-Resolutio n/Resolution-21-36.pdf

The Department operates from three stations for the protection n/Resolution-21-36.pdf

with two full time stations and one part time station. WF

- Station 1, at 15415 Gleneagle Drive, is staffed.
- Station 2, at 15055 Hwy 83, is staffed.
- Station 3, at 15000 Sun Hills Drive, is not staffed.

How many firefighting apparatuses are in the Falcon F.D. fleet?

• 3 fire engines

Drive, Colorado Springs.

- 1 Ladder
- 1 water tender
- 1 brush truck
- 2 Command Vehicles
- 1 Utility truck
- 1 Ambulance
- 1 Hummer
- ATV
- Air trailer
- Chipper

Fire Protection Report_V1.pdf Markup Summary

Sophie Kiepe (1)



Subject: Reports on File Page Label: 1 Author: Sophie Kiepe Date: 3/15/2021 3:08:33 PM Status: Color: ■ Layer: Space:

Please revise the fire protection report per the newly revised Land Development Code standards on fire protection reports, which was just amended in early 2021.

Please refer to PDF page 10 and onward for the Fire Protection and Wildfire Mitigation Section 6.3.3, and provide an analysis of the applicable fire code.

Link:

https://assets-planningdevelopment.elpasoco.com/ wp-content/uploads/LDC-Resolution/Resolution-21 -36.pdf