


# ENG-CDR21014-R2-GEC.pdf Markup Summary

4 (1)



**Subject:** SW - Textbox with Arrow  
**Page Index:** 4  
**Date:** 2/9/2022 10:58:54 AM  
**Author:** EPC Stormwater - Glenn Reese  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [5] 5 INTERIM EROSION CONTROL PLAN


SL is not an appropriate BMP within a major drainageway such as this. They will likely be washed downstream during a decent runoff event. Consider using a different BMP here or none at all.

6 (15)




**Subject:** Callout  
**Page Index:** 6  
**Date:** 2/8/2022 2:42:31 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS


We can't have berms along the channel (highlighted in other areas also)




**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:36:39 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS




**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:36:55 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS



**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:37:25 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS




**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:37:50 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS



---


**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:37:54 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS



---


**Subject:** Text Box  
**Page Index:** 6  
**Date:** 2/8/2022 2:38:41 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS

Provide flow arrows




---

**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:39:34 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS




---

**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:40:08 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS




---

**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:40:48 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS




---


**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:41:07 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS




**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:41:24 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS



**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:41:28 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS




**Subject:**  
**Page Index:** 6  
**Date:** 2/8/2022 2:42:00 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS



**Subject:** SW - Textbox with Arrow  
**Page Index:** 6  
**Date:** 2/9/2022 10:56:56 AM  
**Author:** EPC Stormwater - Glenn Reese  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [7] 7 DETAILS

PS will be needed in both staging areas

7 (1)



**Subject:** Contractor  
**Page Index:** 7  
**Date:** 2/7/2022 8:34:04 PM  
**Author:** EPC Stormwater - Glenn Reese  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [8] 8 DETAILS

Unresolved comment:  
 replace with EPC approved VTC detail (VT-1 and VT-2 in DCMv2, Chap 3.3) or revise to be 75ft min length.