
ENG-SF22030-R2-GEC-redlines.pdf Markup Summary

1 (1)		
ER 2022 , sp-22-030 stud te 'St' not St'	Subject: SW - Textbox with Arrow Page Index: 1 Date: 12/15/2022 5:06:48 PM Author: Glenn Reese - EPC Stormwater Color: Layer: Space: Page Label: [1] 1 CV01	Should be "SF" not SP
2 (13)		
	Subject: Callout Page Index: 2 Date: 12/30/2022 10:52:41 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC	Update lot numbers to match the plat
	Subject: Callout Page Index: 2 Date: 12/30/2022 10:48:47 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC	Revise grading to elevate the lot
	Subject: Callout Page Index: 2 Date: 12/30/2022 10:50:04 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC	Label riprap
	Subject: Callout Page Index: 2 Date: 12/30/2022 10:50:55 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC	Label concrete channel
	Subject: Callout Page Index: 2 Date: 12/30/2022 10:52:24 AM Author: dsdrice Color: Layer:	Is silt fence needed here?

Space: Page Label: [2] 2 Initial GESC



Subject: Callout Page Index: 2 Date: 12/30/2022 10:52:18 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC



.....



Subject: Arrow Page Index: 2 Date: 12/30/2022 10:55:12 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC



Subject: Arrow Page Index: 2 Date: 12/30/2022 10:55:07 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC

.



Subject: Callout Page Index: 2 Date: 12/30/2022 10:57:10 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC

.....

.....

Show property line



Subject: Callout Page Index: 2 Date: 12/30/2022 10:57:26 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC

Label trail(?)

Encore the search access Subject: Callout Page Index: 2 Date: 12/30/2022 10:58:08 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC

Ensure that grading allows for trail/ maint. access



Subject: Callout Page Index: 2 Date: 12/30/2022 10:58:33 AM Author: dsdrice Color: 📘 Layer: Space: Page Label: [2] 2 Initial GESC

Label trail

NOT TO SCALE

Subject: Callout Page Index: 2 Date: 12/30/2022 10:59:20 AM Author: dsdrice Color: Layer: Space: Page Label: [2] 2 Initial GESC

Provide trail/ maint. access road cross-section

3(1)



Subject: SW - Textbox with Arrow Page Index: 3 Date: 12/15/2022 5:06:53 PM Author: Glenn Reese - EPC Stormwater Color: Layer: Space: Page Label: [3] 3 Initial - Initial GESC (1)

This grading is different from the previous submittal. Move the viewport limits over to the right to include entire limits of proposed grading area.

4(1)



Subject: Callout Page Index: 4 Date: 12/30/2022 11:01:42 AM Author: dsdrice Color: Layer: Space: Page Label: [4] 4 Initial GESC (2)

6(2)



Subject: SW - Textbox with Arrow Page Index: 6 Date: 12/21/2022 12:09:05 PM Author: Glenn Reese - EPC Stormwater Color: Layer: Space: Page Label: [6] 6 Initial - Initial GESC (4)



Subject: Callout Page Index: 6 Date: 12/30/2022 11:02:44 AM Author: dsdrice Color: Layer: Space: Page Label: [6] 6 Initial - Initial GESC (4)

label trail/maint. access roads

Please find a better spot for the CWA. It is a driving safety hazard if located in the middle of the road and it is not desirable to have it located next to an inlet.

A barricade and/or fencing would help with the road safety part at least.

Per FDR there is an interim sedimentation pond that Marksheffel drains to. Please show and label or add a note about where it is and who is to maintain it.

.....