



# MDT-SF22013-R2-CDs.pdf Markup Summary


3 (3)



**Subject:**  
**Page Index:** 3  
**Date:** 8/3/2022 12:31:49 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01




**Subject:**  
**Page Index:** 3  
**Date:** 8/3/2022 12:32:05 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01




**Subject:**  
**Page Index:** 3  
**Date:** 8/3/2022 12:32:16 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

4 (2)




**Subject:**  
**Page Index:** 4  
**Date:** 8/3/2022 12:33:01 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01



**Subject:** Callout  
**Page Index:** 4  
**Date:** 8/3/2022 1:49:13 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Place sidewalks (Pedestrian Accessible Route)  
behind inlets (all inlets)


5 (1)



**Subject:** Callout  
**Page Index:** 5  
**Date:** 8/3/2022 12:33:55 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Replace sidewalk


6 (1)



**Subject:** Callout  
**Page Index:** 6  
**Date:** 8/3/2022 12:35:29 PM  
**Author:** dsdrice  
**Color:**    
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


adjust overlapping text

8 (2)



**Subject:** Callout  
**Page Index:** 8  
**Date:** 8/3/2022 12:45:07 PM  
**Author:** dsdrice  
**Color:**    
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Provide a detail with grades, cross-slopes and spot elevations to show that the midblock ramp will work



**Subject:** Callout  
**Page Index:** 8  
**Date:** 8/3/2022 12:46:27 PM  
**Author:** dsdrice  
**Color:**    
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


2.14%?

10 (3)




**Subject:**  
**Page Index:** 10  
**Date:** 8/3/2022 12:50:17 PM  
**Author:** dsdrice  
**Color:**    
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

delete?



**Subject:**  
**Page Index:** 10  
**Date:** 8/3/2022 12:50:21 PM  
**Author:** dsdrice  
**Color:**    
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

delete?




**Subject:** Callout  
**Page Index:** 10  
**Date:** 8/3/2022 12:50:45 PM  
**Author:** dsdrice  
**Color:**    
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

---

11 (1)

---




**Subject:** Callout  
**Page Index:** 11  
**Date:** 8/3/2022 12:52:41 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Recommend detailing mid-block ramp elevations and slopes

---


12 (2)

---



**Subject:** Callout  
**Page Index:** 12  
**Date:** 8/3/2022 12:42:42 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Add pedestrian ramp




**Subject:** Callout  
**Page Index:** 12  
**Date:** 8/3/2022 1:26:05 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

deviation request needed if no N-S crossing

---


13 (3)

---




**Subject:** Callout  
**Page Index:** 13  
**Date:** 8/3/2022 1:29:37 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Adjust size of symbols, add street names



**Subject:** Callout  
**Page Index:** 13  
**Date:** 8/3/2022 1:29:37 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Address turnaround



**Subject:** Callout  
**Page Index:** 13  
**Date:** 8/3/2022 1:31:44 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Add leaders

16 (2)



**Subject:** Callout  
**Page Index:** 16  
**Date:** 8/3/2022 1:38:36 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Hide the future roads, lots, etc.



**Subject:** Callout  
**Page Index:** 16  
**Date:** 8/3/2022 2:12:40 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


with watertight joints where indicated

17 (2)



**Subject:** Callout  
**Page Index:** 17  
**Date:** 8/3/2022 1:42:37 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Show design tying in to channel improvements



**Subject:** Callout  
**Page Index:** 17  
**Date:** 8/3/2022 2:15:35 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Replace contours on all P&P sheets


19 (1)



**Subject:** Callout  
**Page Index:** 19  
**Date:** 8/3/2022 2:06:49 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Watertight pipe joints required - add note

20 (1)



**Subject:** Callout  
**Page Index:** 20  
**Date:** 8/3/2022 2:09:27 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Manhole not shown - show on plan


21 (1)



**Subject:** Callout  
**Page Index:** 21  
**Date:** 8/3/2022 2:16:30 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Hide striping?

23 (7)



**Subject:** Callout  
**Page Index:** 23  
**Date:** 8/3/2022 2:19:30 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Watertight joints required

ET 14-3  
TA: ???  
6185.07  
7056 07


**Subject:**  
**Page Index:** 23  
**Date:** 8/3/2022 2:20:12 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

ET 14-3  
TA: ???  
6153.82  
7146 14

**Subject:**  
**Page Index:** 23  
**Date:** 8/3/2022 2:21:58 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


ET 14-2  
STA: ???  
16166.07  
37130.67


**Subject:**  
**Page Index:** 23  
**Date:** 8/3/2022 2:22:04 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01




**Subject:** Callout  
**Page Index:** 23  
**Date:** 8/3/2022 2:22:22 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Adjust label



**Subject:** Callout  
**Page Index:** 23  
**Date:** 8/3/2022 2:22:52 PM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Adjust label




**Subject:** Callout  
**Page Index:** 23  
**Date:** 8/3/2022 2:23:24 PM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Show water surface elevation


24 (3)



**Subject:** SW - Textbox with Arrow  
**Page Index:** 24  
**Date:** 7/26/2022 9:20:38 AM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Revise to Pond C




**Subject:** Callout  
**Page Index:** 24  
**Date:** 8/3/2022 2:27:38 PM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Is spillway protection needed to bottom of the slope or is overflow depth low enough?




**Subject:**  
**Page Index:** 24  
**Date:** 8/3/2022 2:26:45 PM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

25 (4)




**Subject:** SW - Textbox with Arrow  
**Page Index:** 25  
**Date:** 7/26/2022 9:22:13 AM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

For consistency with FDR and GEC Plan, please call this Pond C on all sheets of CDs.




**Subject:** SW - Textbox with Arrow  
**Page Index:** 25  
**Date:** 7/26/2022 7:31:00 PM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

If the calcs for this are on pg 92 of the FDR, this is supposed to be 10.4in




**Subject:** Arrow  
**Page Index:** 25  
**Date:** 7/26/2022 7:32:32 PM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01



**Subject:** SW - Textbox with Arrow  
**Page Index:** 25  
**Date:** 7/26/2022 7:33:37 PM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Can you line up the plan and section in a straight vertical line so it is clear how they correspond?

26 (3)




**Subject:** SW - Textbox with Arrow  
**Page Index:** 26  
**Date:** 7/26/2022 7:34:20 PM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

If the calcs for this are on pg 93 of the FDR, this is supposed to be 6.2in




**Subject:** Arrow  
**Page Index:** 26  
**Date:** 7/26/2022 7:33:21 PM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01





**Subject:** SW - Textbox with Arrow  
**Page Index:** 26  
**Date:** 7/26/2022 7:33:29 PM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01

Can you line up the plan and section in a straight vertical line so it is clear how they correspond?





**Subject:** Arrow  
**Page Index:** 27  
**Date:** 7/27/2022 8:27:51 AM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01




**Subject:** SW - Textbox with Arrow  
**Page Index:** 27  
**Date:** 7/27/2022 8:28:29 AM  
**Author:** Glenn Reese - EPC Stormwater  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


Shift either the plan or profile over a little bit so they align vertically.





**Subject:** Callout  
**Page Index:** 27  
**Date:** 8/4/2022 11:38:41 AM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01


7106.76?




**Subject:**  
**Page Index:** 27  
**Date:** 8/4/2022 11:41:09 AM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01



**Subject:**  
**Page Index:** 27  
**Date:** 8/4/2022 11:41:12 AM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01



**Subject:**  
**Page Index:** 27  
**Date:** 8/4/2022 11:41:16 AM  
**Author:** dsdrice  
**Color:**   
**Layer:**  
**Space:**  
**Page Label:** [14] 14 DT01 - DT01