

# MDT-SF21026-R4-GEC.pdf Markup Summary

1 (2)




**Subject:** Stormwater Comments Color  
**Page Index:** 1  
**Date:** 2/2/2022 2:17:21 PM  
**Author:** dotprete  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** 1




**Subject:** PCD Comment Legend  
**Page Index:** 1  
**Date:** 2/2/2022 5:54:55 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** 1

8 (2)



**Subject:** Engineer  
**Page Index:** 8  
**Date:** 2/2/2022 12:51:29 PM  
**Author:** dotprete  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** 8

riprap pad dimintions do not meet requirements in drainage report



**Subject:** Length Measurement  
**Page Index:** 8  
**Date:** 2/2/2022 12:51:24 PM  
**Author:** dotprete  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** 8


27'-0"

10 (2)



**Subject:** Callout  
**Page Index:** 10  
**Date:** 1/20/2022 8:51:38 AM  
**Author:** CDurham  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** 10

Missing opening width dimension



**Subject:** Snapshot  
**Page Index:** 10  
**Date:** 1/31/2022 2:52:28 PM  
**Author:** dsdrice  
**Color:** ■  
**Layer:**  
**Space:**  
**Page Label:** 10