
MERIDIAN RANCH: WINDINGWALK FILINGS 1 & 2

PUD DEVELOPMENT, PRELIMINARY PLAN AND FINAL PLAT FILING 1

FIRE PROTECTION REPORT

JANUARY 2018, REVISED FEBRUARY 15, 2018

PROPERTY OWNER:

Meridian Ranch Investments Inc.
PO BOX 80036,
San Diego, CA 92138

DEVELOPER:

GTL Development, Inc.
3575 Kenyon Street,
San Diego, CA 92110

CONSULTANT:

N.E.S. Inc.
619 North Cascade Avenue,
Colorado Springs, CO 80903

LOCATION

The WindingWalk Filing 1 and 2 are located southeast of the intersection of Londonderry Road and Rainbow Bridge Drive, Peyton, Colorado. The site comprises of approximately 139 acres and is zoned PUD.



WindingWalk Filings 1 & 2 at Meridian Ranch subdivisions are within the Falcon Fire Protection District service area. The 133-square-mile fire district extends from Peyton Highway on the east to County Line Road on the north to Black Forest Road on the west and one mile north of Colorado Highway 94 on the south. The District serves more than 23,400 citizens, and protects almost 10,000 structures. Ninety-four percent of the structures within the District are residential and 6 percent are commercial buildings.

The following stations and equipment are maintained by the District:

Station 1: This is the primary staffed station for District 1. The new station provides reduced response times to the most populated areas that also generate the highest call volumes.

Apparatus at Station 1 include:

- An engine
- A water tender (water truck)
- A brush truck
- An AMR ambulance
- A utility truck
- Battalion Chief Command vehicle

Station 2: Apparatus at Station 2 include:

- A 4-wheel drive engine
- A water tender
- A brush truck

Station 3/Headquarters/Training Facility: With the opening of Station 1, the Falcon Fire Department's building on Old Meridian Road becomes a true headquarters facility that includes administration functions such as human relations and payroll. It will continue to host monthly Falcon Fire Protection District Board meetings, and serve as the Department's primary classroom and training facility for emergency medical services, fire, hazardous materials and technical rescue disciplines. It also serves as the fleet maintenance and repair facility for minor work on apparatus and equipment. Apparatus at Station 3 include:

- An engine
- A tender
- A utility truck
- A brush truck

Station 6 (formally Station 3): Apparatus at Station 6 include:

- A water tender
- A brush truck

RESPONSE TIMES

Below is an extract from the Fire District's Annual Report, which provides details of incidents and response times. Meridian Ranch is within District 1 where the average response time is 6 minutes 38 seconds.

