



May 16, 2024

Marea Newmark SCO Construction Admin Manager Richmond American Homes 4350 S. Monaco St. Denver, CO 80237

RE: Comcast consent; Eaves Encroachment Feathergrass / Urban Collection at Palmer Lake. Lots 13-24; 2429 Vanhoutte View thru 2495 Vanhoutte View Lots 25-40 ; 2426 Serviceberry Grove thru 2467 Serviceberry Grove Lots 41-44; 7371 Fountain Grass Grove thru 7383 Fountain Grass Grove Lots 47-54; 2454 Hannah Ridge Drive thru 2482 Hannah Ridge Drive

You contacted us requesting a letter of consent to encroach on the side lot easement for the above listed address.

Comcast has no issue and will grant consent.

This consent does not release any easement rights that Comcast has for this property.

Don't hesitate to contact me if there are any further questions.

Best Regards,

Jason Jacobsen

Jason Jacobsen Construction Supervisor Jason_Jacobsen@cable.comcast.com



Memorandum

To: Marea Newmark, Richmond American Homes

Date: May 08, 2024

From: Drew Makings

Dept: Development Services

Re: Easement Encroachment Request for certain lots in Feathergrass.

This memo is in response to your May 1st, 2024 request for overhead roof eaves, soffit (aerial) and window well(s) (surficial) to encroach into the respective side lot easements for the following properties:

• 2495 Vanhoutte View	2474 Serviceberry Grove
• 2489 Vanhoutte View	2480 Serviceberry Grove
• 2483 Vanhoutte View	2486 Serviceberry Grove
• 2477 Vanhoutte View	2492 Serviceberry Grove
• 2471 Vanhoutte View	2485 Serviceberry Grove
• 2465 Vanhoutte View	• 2479 Serviceberry Grove
• 2459 Vanhoutte View	2473 Serviceberry Grove
• 2453 Vanhoutte View	• 2467 Serviceberry Grove
• 2447 Vanhoutte View	• 7389 Fountain Grass Grove
• 2441 Vanhoutte View	• 7383 Fountain Grass Grove
• 2435 Vanhoutte View	• 7377 Fountain Grass Grove
• 2429 Vanhoutte View	7371 Fountain Grass Grove
2426 Serviceberry Grove	• 2482 Hannah Ridge Drive
2432 Serviceberry Grove	• 2478 Hannah Ridge Drive
2438 Serviceberry Grove	• 2474 Hannah Ridge Drive
2444 Serviceberry Grove	• 2470 Hannah Ridge Drive
• 2450 Serviceberry Grove	• 2466 Hannah Ridge Drive
• 2456 Serviceberry Grove	• 2462 Hannah Ridge Drive
• 2462 Serviceberry Grove	• 2458 Hannah Ridge Drive
• 2468 Serviceberry Grove	2454 Hannah Ridge Drive

Colorado Springs Utilities does not object to the request to allow the subject easement encroachment provided that the following acknowledgements are made:

- 1. The projection does not deviate from the permitted plans with respect to location and dimension.
- 2. The location of any Utilities owned Natural Gas service is per Colorado Springs Utilities Gas Line Extension & Service Standards (2022)
- 3. The projection does not extend into the Side Lot Easement more than a maximum of Eighteen (18) inches.
- 4. If it is necessary to relocate any existing utility facilities, then such relocation shall be at the Applicant's expense, and if required, Applicant shall grant new easements for the relocated facilities.
- 5. This Response is only pertinent to Colorado Springs Utilities as ONE of MANY entities that has rights to this easement. Approval by CSU does NOT represent a WHOLESALE APPROVAL for this activity as there are other public entities that retain right under the Public Utility Easement.

Please contact me if you need additional information. Thank you,

Drew Makings, Engineer V Utilities Development Services 668-8127

SITE



2023 PPRBC 2021 IECC

Parcel: 5405101084

Address: 2454 HANNAH RIDGE DR, COLORADO SPRINGS

Received: 30-Apr-2024

(BECKYA)

Description:

RESIDENCE

Type of Unit:

Garage Main Level Upper Level 1 450 636

812

1898 Total Square Feet

Required PPR	BD Departments ((2)
---------------------	------------------	-----

Enumeration

APPROVED

BECKYA

4/30/2024 4:08:45 PM

Floodplain

(N/A) RBD GIS

Required Outside Departments (1)

County Zoning

APPROVED Plan Review

05/23/2024 8:53:45 AM

dsdyounger EPC Planning & Community Development Department

Release of this plan does not preclude compliance with all applicable codes, ordinances and other pertinent regulations. This plan set must be present on the job site for every inspection.