



ENG-SF21033-R4-CDs.pdf Markup Summary

16 (2)



Subject: Callout
Page Index: 16
Date: 1/6/2023 2:11:11 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [16] 16 El Raiceno Trail


Mail kiosk should be east of the intersection




Subject: Callout
Page Index: 16
Date: 1/6/2023 3:16:22 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [16] 16 El Raiceno Trail

Revise ditch to go around the kiosk. Update ROW and easements as needed.


23 (6)




Subject:
Page Index: 23
Date: 1/6/2023 2:18:31 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [24] 24 WP01 (1)




Subject:
Page Index: 23
Date: 1/6/2023 2:18:35 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [24] 24 WP01 (1)




Subject:
Page Index: 23
Date: 1/6/2023 2:18:50 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [24] 24 WP01 (1)



Subject:
Page Index: 23
Date: 1/6/2023 2:18:53 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [24] 24 WP01 (1)




Subject:
Page Index: 23
Date: 1/6/2023 2:19:15 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [24] 24 WP01 (1)



Subject:
Page Index: 23
Date: 1/6/2023 2:19:37 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [24] 24 WP01 (1)

36 (1)



Subject: Callout
Page Index: 36
Date: 1/4/2023 3:39:16 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [37] 37 Outlet Structure

Provide construction details for spreader