

ENG-CDR20001-V6-CDs Summary_Markup Summary

1 (2)



Subject:
Page Index: 1
Date: 4/27/2020 5:59:16 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2



Subject:
Page Index: 1
Date: 4/27/2020 5:59:19 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

3 (2)



Subject: Text Box
Page Index: 3
Date: 4/27/2020 5:47:12 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

Jane Lundeen / Pinehurst Circle Roundabout



Subject: Text Box
Page Index: 3
Date: 4/27/2020 6:11:32 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2


Provide plowable nose median detail ECM SD_2-22.

7 (1)



Subject: Callout
Page Index: 7
Date: 4/27/2020 6:27:22 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

Label cover material (reference ECM 2.5.6 and SD_2-21 (or modified pattern). Any medians less than 4' (TBC-TBC) should be paved.




Subject: Cloud+
Page Index: 9
Date: 4/25/2020 2:51:08 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

An inlet or chase/rundown is needed




Subject: Callout
Page Index: 9
Date: 4/25/2020 2:59:38 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

Provide ped. ramps.




Subject: Callout
Page Index: 9
Date: 4/25/2020 2:59:58 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

Verify that inlet is not too close to the ped ramp to meet ADA requirements.




Subject: Callout
Page Index: 9
Date: 4/25/2020 3:01:32 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

Ped ramps as shown may need adjustment to meet requirements.




Subject: Callout
Page Index: 11
Date: 4/27/2020 6:32:49 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

maybe pull median back west to where asphalt is 12'?



Subject: Callout
Page Index: 11
Date: 4/27/2020 6:33:41 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

asphalt needs to be 12'



Subject: Text Box
Page Index: 11
Date: 4/27/2020 6:38:23 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

Scale is weird (2.9" =150'?)



Subject: Length Measurement
Page Index: 11
Date: 4/27/2020 6:39:13 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2


18.00 ft



Subject: Callout
Page Index: 11
Date: 4/27/2020 6:41:57 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

The eastbound lane paved (asphalt) width from HWY 83 to STA 21+ should be 18'.

12 (1)



Subject: Callout
Page Index: 12
Date: 4/27/2020 6:42:49 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2


See comments on GEC Plan

13 (4)




Subject: Callout
Page Index: 13
Date: 4/27/2020 6:44:32 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

See comments on GEC Plan




Subject: Length Measurement
Page Index: 13
Date: 4/27/2020 6:48:29 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

46.47 ft



Subject: Callout
Page Index: 13
Date: 4/27/2020 6:49:29 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2


Needs to be 48'



Subject: Callout
Page Index: 13
Date: 4/27/2020 6:50:52 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2


Verify compound curve dimensions for WB-67

14 (3)




Subject: Callout
Page Index: 14
Date: 4/27/2020 6:52:12 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

label



Subject: Callout
Page Index: 14
Date: 4/27/2020 6:54:26 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2


asphalt needs to be 12'




Subject: Callout
Page Index: 14
Date: 4/27/2020 6:55:36 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

show shoulder

15 (7)




Subject:
Page Index: 15
Date: 4/27/2020 6:57:06 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2




Subject: Callout
Page Index: 15
Date: 4/27/2020 6:57:35 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

concrete apron (like on inside)




Subject: Length Measurement
Page Index: 15
Date: 4/27/2020 6:59:09 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

4.02 ft




Subject: Callout
Page Index: 15
Date: 4/27/2020 7:00:50 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

show gutter pans



Subject: Cloud+
Page Index: 15
Date: 4/27/2020 7:07:13 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

11'8"?




Subject: Cloud+
Page Index: 15
Date: 4/27/2020 7:10:36 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

48'10"?




Subject: Cloud+
Page Index: 15
Date: 4/27/2020 7:11:25 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

reduce to width necessary for trailer tracking +1' (10?). The other dimensions don't match.




Subject: Length Measurement
Page Index: 16
Date: 4/27/2020 12:17:59 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

59.20 ft




Subject: Radius Measurement
Page Index: 16
Date: 4/27/2020 12:24:41 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

8.00 ft



Subject: Snapshot
Page Index: 16
Date: 4/27/2020 12:28:31 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2



Subject: Cloud+
Page Index: 16
Date: 4/27/2020 5:56:35 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

M1?



Subject: Callout
Page Index: 16
Date: 4/27/2020 7:16:54 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] F2

See comment letter regarding snowplow tracking in this quadrant.