

ENG-SF22004-R3-FDR.pdf Markup Summary

3 (2)

Criteria Manual, Volun

Jennifer Irvine
County Engineer/ECM A

Conditions:

Subject: Line
Page Index: 3
Date: 7/20/2022 5:23:07 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: 3

EL PASO COUNTY


Filed in accordance with the require
Criteria Manual, Volun

Jennifer Irvine
County Engineer/ECM Administrator

Subject: Callout
Page Index: 3
Date: 7/20/2022 5:23:18 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: 3

Remove

33 (1)



Subject: Callout
Page Index: 33
Date: 7/22/2022 3:29:53 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 33

These don't appear to add up to 37.6

63 (1)

4.2		0.00	0.00	107	1.04	0.76	12.4
4.3		0.00	0.00	107	1.07	0.76	12.5
4.4		0.00	0.00	107	1.07	0.76	12.5

Please add DPs where applicable

Subject: Callout
Page Index: 63
Date: 7/22/2022 3:02:45 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 63

Please add DPs where applicable

66 (1)

Duplicate - delete

4.2		0.00	0.00	107	1.04	0.76	12.4
4.3		0.00	0.00	107	1.07	0.76	12.5
4.4		0.00	0.00	107	1.07	0.76	12.5

Subject: Text Box
Page Index: 66
Date: 7/22/2022 1:55:05 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 66

Duplicate - delete


148 (1)

See comment in narrative section

Subject: Text Box
Page Index: 148
Date: 7/22/2022 3:28:08 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 148

See comment in narrative section

173 (1)



Subject: Callout
Page Index: 173
Date: 7/22/2022 4:00:08 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 173

Doesn't match revised drainage plan

241 (9)

61.5

Subject: Highlight
Page Index: 241
Date: 7/20/2022 5:38:47 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: 241

61.5

1.480

Subject: Highlight
Page Index: 241
Date: 7/20/2022 5:38:59 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: 241

1.480

5813.07

58

Subject: Highlight
Page Index: 241
Date: 7/20/2022 5:39:13 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: 241

5817.95

5817.95

58

5801.50

58


16 | 5800.74


Subject: Highlight
Page Index: 241
Date: 7/20/2022 5:39:34 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: 241


5812.51


24 | 5812.51

37 | 5816.39

5797.46 | 58 | **Subject:** Highlight
Page Index: 241
5801.24 | 58 | **Date:** 7/20/2022 5:39:41 PM
Author: CDurham
5813.07 | 58 | **Color:** 
Layer:
Space:
Page Label: 241

1.100 | **Subject:** Highlight
Page Index: 241
3.003 | **Date:** 7/20/2022 5:39:58 PM
Author: CDurham
0.001 | **Color:** 
Layer:
Space:
Page Label: 241


Subject: Highlight
Page Index: 241
8.0 | **Date:** 7/20/2022 5:40:00 PM
Author: CDurham
Color: 
Layer:
Space:
Page Label: 241

35 | 5818.86 | **Subject:** Highlight
Page Index: 241
50 | 5801.74 | **Date:** 7/20/2022 5:40:08 PM
Author: CDurham
36 | 5798.29 | **Color:** 
Layer:
Space:
Page Label: 241

5.90 | 18 c | 23.0 | 5798.46 | **Subject:** Text Box
Page Index: 241
 **Date:** 7/20/2022 5:40:20 PM
Author: CDurham
Color: 
Layer:
Space:
Page Label: 241
Highlighted items do not match CD's


255 (1)

 **Subject:** Text Box
Page Index: 255
Date: 7/22/2022 3:47:53 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 255
Could not verify table as not all DP's were listed in hydrology spreadsheet.



Subject: Callout
Page Index: 259
Date: 7/22/2022 4:05:11 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 259

Should these be lower if C9 flows have been separated?



Subject: Callout
Page Index: 259
Date: 7/22/2022 4:01:51 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 259

This acreage is too large to discharge offsite untreated and needs additional facilities. It would be logical to install the curb and gutter as previously shown and then remove it once the offsite downstream improvements have been constructed.