ENG-SP18004-R4-PDRFDR-redlines.pdf Markup Summary

6 (1)

whether controls already are perform to easy during parts included a proper of the first process. And the first fi

Subject: Callout Page Index: 6

Date: 3/26/2019 12:03:21 PM

Author: dsdrice

Color: Layer: Space:

Page Label: 6

Discuss further.

12 (1)



Subject: Text Box Page Index: 12

Date: 3/15/2019 2:41:29 PM

Author: dsdrice Color: Layer: Space: Page Label: 12 Address roadside ditch stabilization and calculations and plan in appendix.

38 (1)

Provide for 56 cfs.

Subject: Text Box Page Index: 38

Date: 3/15/2019 2:27:58 PM

Author: dsdrice
Color: Layer:
Space:

Page Label: 38

Provide for 56 cfs.

101 (1)



Subject: Callout Page Index: 101

Date: 3/26/2019 1:30:37 PM

Author: dsdrice
Color: Layer:
Space:

Page Label: 101

Does this culvert need to be modified?