
## ENG-CDR19004-R4-TS-CD-Redlines .pdf Markup Summary





3

Subject: Callout lighten or gray back the shoulder (change hatch?) Page Index: 4 Date: 9/21/2020 10:27:47 AM Author: dsdrice Color: Layer: Space: Page Label: 4 Subject: Cloud+ It's not a good idea to provide partial pedestrian Page Index: 4 infrastructure (without ramps or crossing) Date: 9/21/2020 10:30:22 AM Author: dsdrice Color: Layer: Space: Page Label: 4 -----Subject: Callout Channelizing island would provide benefits at this Page Index: 4 location and it might be a better location for the Date: 9/21/2020 10:31:35 AM signal pole and lighting. Author: dsdrice Color: Layer: Space: Page Label: 4 Subject: Page Index: 4 Date: 9/21/2020 10:34:30 AM Author: dsdrice Color: Layer: Space: Page Label: 4 . . . . . . . . . . Subject: Page Index: 4 Date: 9/21/2020 10:34:30 AM Author: dsdrice Color: Laver: Space: Page Label: 4 . . . . . . . . . . . Subject: Page Index: 4 Date: 9/21/2020 10:34:30 AM Author: dsdrice Color: Layer: Space: Page Label: 4

IS LED FUD SUMAL READ SEN 2 ONL-PRIC-MOUNTED VISED ANCE VENICLE OFFICE VISED ANCE VENICLE OFFICE VISED ANCE VENICLE OFFICE Fradar	Subject: Cloud+ Page Index: 4 Date: 9/21/2020 10:35:17 AM Author: dsdrice Color: Layer: Space: Page Label: 4	radar
) "CR <mark>(CAMERA)</mark> CAL)	Subject: Page Index: 4 Date: 9/21/2020 10:35:30 AM Author: dsdrice Color: Layer: Space: Page Label: 4	
	Subject: Callout Page Index: 4 Date: 9/21/2020 12:46:04 PM Author: dsdrice Color: Layer: Space: Page Label: 4	See comment letter
	Subject: Page Index: 4 Date: 9/21/2020 12:46:53 PM Author: dsdrice Color: Layer: Space: Page Label: 4	
	Subject: Area Measurement Page Index: 4 Date: 9/21/2020 3:43:05 PM Author: dsdrice Color: Layer: Space: Page Label: 4	183.82 sf