## 8/1/2017 4:32:13 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/1/2017 4:32:13 PM

Color:

See ECM Section 2.3.6.G for intersection sight triangle easement procedure.

# 8/1/2017 4:35:56 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/1/2017 4:35:56 PM

Color:

label the street classification and ROW width.

# 8/14/2017 12:08:40 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status: Checkmark

Checkmark: Unchecked Author: dsdparsons Date: 8/14/2017 12:08:40 PM

Color:

Add Geologic hazard note provided in MTD letter.

Identify the hazard areas on map.

## 8/14/2017 12:08:50 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdparsons Date: 8/14/2017 12:08:50 PM

Color:

Identify the adjacent zoning and land uses for all boundaries. The east boundary will have existing and proposed.

## 8/14/2017 12:11:10 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdparsons

Date: 8/14/2017 12:11:10 PM

Color:

Identify row width and "public" for all roads

### 8/14/2017 12:12:22 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status: Checkmark: Unchecked **Author:** dsdparsons Date: 8/14/2017 12:12:22 PM

Color:

darken the font please

## 8/14/2017 12:15:56 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdparsons

Date: 8/14/2017 12:15:56 PM

Color:

Maintained by whom? I suggest this is placed in a tract so that there are no issues with the adjacent property owner. Does the property owner to the west intend to subdivide? They will be limited to a total of 3 lots as a driveway unless ROW is preserved. Provided documentation.

## 8/14/2017 12:16:34 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdparsons

Date: 8/14/2017 12:16:34 PM

Color:

Clarify easement lines

## 8/14/2017 12:20:08 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdparsons Date: 8/14/2017 12:20:08 PM

Color:

A waiver for physical and 30' linear frontage to a ROW is required, if Lot 1 has no ROW access. Provide justification in the LOI. Section 8.4.3.A

### 8/14/2017 12:23:29 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdparsons

Date: 8/14/2017 12:23:29 PM

Color:

### Delete proposed. The rezone will be approved prior to the prelim.

## 8/14/2017 12:25:01 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status: Checkmark: Unchecked

Author: dsdparsons Date: 8/14/2017 12:25:01 PM

Color:

Add note regarding western access easement.

## 8/14/2017 12:25:46 PM (1)

ving areas:

| portion) | Lot # is 22 |
| Adde "Hay" that is galled heap)
| Winness are flag port
| Front, 15 Sales and Selected with the final Plat.

Ter on file:

Ter of file:

Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdparsons

Date: 8/14/2017 12:25:46 PM

Color:

Where is the flag lot?

### 8/14/2017 12:26:40 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdparsons

Date: 8/14/2017 12:26:40 PM

Color:

Who are the utility providers to be? Add notes.

### 8/14/2017 12:31:11 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdparsons

Date: 8/14/2017 12:31:11 PM

Color:


Add note: Water Supply: (utilized when the water supply is individual wells)

(Note: The exact wording of plat notes regarding well water supply depends upon the language of the water decree and/or augmentation plan, and will be reviewed and approved by the County Attornev's Office)

Individual wells are the responsibility of each property owner. Permits for individual wells must be obtained from the State Engineer who by law has the authority to set conditions for the issuance of these permits.

Water in the Denver Basin Aquifers is allocated based on a 100-year aquifer life; however, for El Paso County planning purposes, water in the Denver Basin Aquifers is evaluated based on a 300-year aquifer life. Applicants and all future owners in the subdivision should be aware that the economic life of a water supply based on wells in a given Denver Basin Aquifer may be less than either the 100 years or 300 years indicated due to anticipated water level declines. Furthermore, the water supply plan should not rely solely upon non-renewable aquifers. Alternative renewable water resources should be acquired and incorporated in a permanent water supply plan that provides future generations with a water supply.

### 8/14/2017 12:32:58 PM (1)



Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdparsons Date: 8/14/2017 12:32:58 PM

Color:

Add note: Sewage treatment is the responsibility of each individual property owner. The El Paso County Department of Health and Environment must approve each system and, in some cases the Department may require an engineer designed system prior to permit approval. These systems may cost more to design, install, and maintain.

### 8/2/2017 11:47:47 AM (1)



Subject: Callout Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/2/2017 11:47:47 AM

Color:

The property to the west appears to be landlocked. Provide a ROW stub in the event the adjacent owner decides to subdivide the property.

## 8/3/2017 10:02:08 AM (1)



Subject: Cloud+ Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/3/2017 10:02:08 AM

Color:

Revise to Preliminary Drainage Report.

### 8/3/2017 10:02:43 AM (1)



Subject: Cloud+ Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/3/2017 10:02:43 AM

Color:

Revise to Preliminary Plan

## 8/3/2017 10:03:58 AM (1)



Subject: Callout Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/3/2017 10:03:58 AM

Color:

Revise title to "Preliminary Plan

Settlers View Subdivision"

### 8/3/2017 10:32:40 AM (1)



Subject: Cloud+ Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/3/2017 10:32:40 AM

Color:

Is the intent to have shared access as shown? If so a shared access easement b/w Lot 1 and 2 needs to be identified with the final plat.

# 8/3/2017 10:32:48 AM (1)



Subject: Cloud+ Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/3/2017 10:32:48 AM

Color:

Show the permanent easement for the detention pond.

Add a note identifying who maintains the pond.

### 8/3/2017 10:35:40 AM (1)



Subject: Text Box Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/3/2017 10:35:40 AM

Color:

Add a typical roadway cross section detail. Per the EPC standard detail for Rural Local Roadway, a 5' public improvement along the ROW

shall be granted to El Paso County.

## 8/3/2017 10:40:37 AM (1)



Subject: Cloud+ Page Label: 1 Lock: Unlocked

Status:

Checkmark: Unchecked Author: dsdlaforce

Date: 8/3/2017 10:40:37 AM

Color:

Add the criteria language for the temporary cul-de-sac identified in ECM Chapter 2 Section 2.3.8.C (pg 2-63). The note must also be added in the final plat.

Depending on the timing between Settlers View and Abert Ranch, the first developer to construct will be required to install the temporary cul-de-sac at the interface between the two development while the second developer will be required to remove the temporary cul-de-sac when the

connection is made.

If both subdivision construction occurs simultaneously, the temporary cul-de-sac may not

be required.

### 8/3/2017 10:43:07 AM (1)



Subject: Cloud+ Page Label: 1 Lock: Unlocked

Status:

**Checkmark:** Unchecked **Author:** dsdlaforce

Date: 8/3/2017 10:43:07 AM

Color:

Note on the plan that the temporary cul-de-sac improvement to be removed and replaced with a standard roadway cross section.

The easement vacation, cul-de-sac removal and standard street section construction and site restoration is the responsibility of the developer extending Silver Nell Drive.

## 8/3/2017 9:41:15 AM (1)



Subject: Text Box Page Label: 1 Lock: Unlocked Status:

Checkmark: Unchecked Author: dsdlaforce Date: 8/3/2017 9:41:15 AM

Color:

Add: PCD File No.: SP-17-006