


ADD24131

Not Required BESQCP

04/04/2024 8:27:14 AM 04/04/2024 8:47:38 AM EPC Planning & Community
Development Department

EPC Planning & Community
Development Department



ANY APPROVAL GIVEN BY EL PASO COUNTY DOES NOT OBVIATE THE NEED TO COMPLY WITH APPLICABLE FEDERAL, STATE, OR LOCAL LAWS AND/OR REGULATION Planning & Community Development Department approval is contingent upon compliance with all applicable notes on the recorded plat. An access permit must be granted by the Planning & Community Development Department prior to the establishment of any driveway onto a County road.

APPROVED

Plan Review

Diversion of blockage of any drainage way is not permitted without approval of the Planning & Community Development Department

<u>TAX SCHEDULE No.:</u> 1300000170

<u>Property owner:</u> Diego martin & edelmira reyes

<u>ADDRESS:</u> 6615 MULBERRY RD

CALHAN CO, 80808-8939

ZONE: A-35 UNPLATTED


<u>LEGAL DESCRIPTION:</u> A TR OF LAND IN SEC 11-13-61 DES AS FOLS: COM AT NW COR SEC 11, TH S 00 45'57" E 2921.20 FT TO POB, TH CONT S 00 45'57" E 584.24 FT, N 88 00'21" E 2632.13 FT, N 00 38'54" W 585.75 FT, S 87 58'24" W 2633.35 FT TO POB, A/K/A LOT 6

<u>SETBACKS:</u> FRONT = 25'-0" SIDE = 25'-0"

REAR = 25'-0"

<u>LOT SIZE:</u> 35 ACRES

2633 25' SIDE SETBACK 900'± PROPOSED 442 SQ. FT. BEDROOM ADDITION EXISTING HOUSE -25' SIDE SETBACK 2633



3RD Dim

BEDROOM ADDITION 6615 MULBERRY RD.

DRAWN BY:

DATE:

JOB NO:

RESIDENTIAL



2023 PPRBC 2021 IECC

Parcel: 1300000170

Address: 6615 MULBERRY RD, CALHAN

Description:

ADDITION

Contractor: HOMEOWNER

Type of Unit:

Received: 22-Mar-2024 (QUINTONW)

Required PPRBD Departments (3)

Floodplain Construction

(N/A) RBD GIS

Mechanical

Required Outside Departments (2)

County Zoning

APPROVED

Plan Review

04/04/2024 8:27:46 AM dsdyounger

EPC Planning & Community Development Department

Health Dept.

Release of this plan does not preclude compliance with all applicable codes, ordinances and other pertinent regulations. This plan set must be present on the job site for every inspection.