

PLANNING & COMMUNITY DEVELOPMENT DEPARTMENT Land Use Review Division

APPLICATION FORM FOR GEOLOGIC HAZARD WAIVER

Applicant: Challenger Communities Telephone: 719-635-4095			
Address: 8605 Explorer Drive, Suite 250 Zip Code: 80920 Email: mmason@mychallengerhomes.com			
Premises Involved: NW corner of Powers Blvd and Hancock Expressway, Skyview Village			
Tax Schedule Number: 64362-00-018			
In accordance with the Geologic Hazard Ordinance 7.4.501, City Planning, in consultation with written approval of the City Engineer, may waive the requirement for the submittal of a Geologic Hazard Study on a property that is not otherwise excluded or exempted from the provisions of this part for the following:			
have be 1. Develop followir a.		thirty three percent (33%) or which are ble. ivity.	
A letter shall accompany this application that states that the project meets the above noted criteria, and is prepared by a professional geologist or professional geotechnical engineer, who is qualified in accord with section 7.4.504.			
A completed waiver request will be reviewed within a <u>3 day</u> time period.			
Professional Geologist / Professional Geotechnical Engineer Acknowledgment:			
I hereby formally request that the development at			
X Professional Geologist / Professional Geotechnical Engineer as defined by section 7.4.504			
Submitted for and on behalf of <u>Challenger Communities</u>			
	Kelli Zigler		
Submitted by:	Kelli Zigler	Date: April 7, 2021	
City Engineering:	neering:City Planning:		
Date:	Date:		

Architecture Structural Geotechnical



Materials Testing Forensic Civil/Planning

ROCKY MOUNTAIN GROUP EMPLOYEE OWNED

Job No. 177709

April 7, 2021

Challenger Communities 8605 Explorer Drive, Suite 250 Colorado Springs, CO 80920

Re: Geologic Hazard Waiver

Skyview Village

Colorado Springs, Colorado

Dear Mr. Mason:

RMG - Rocky Mountain Group was requested to provide a Geologic Hazard Waiver for the above-referenced development. The purpose of the review was to identify whether the site is subject to geologic hazards relating to slopes exceeding 33 percent, underground mining or subsidence, or a history of landfill or uncontrolled and/or undocumented fill activity. Our findings are provided in this letter.

The following is excluded from the scope of this report including (but not limited) seismicity, snow avalanches, water flooding, corrosive soils, erosion, radon, wild fire protection, hazardous waste, natural resources, geologic and natural hazards such as landslides, dipping bedrock, rockfall and unstable slopes.

Project Description

It is our understanding the proposed construction is to consist of one single-family residence with an attached multi-car garage on each proposed lot within the proposed Skyview Village development. Per the Preliminary Site Plan, prepared by Enertia Consulting Group, last dated January 27, 2021, the development is to contain 73 lots with paved interior roadways.

Existing Site Conditions

The site consists of approximately 6.89 acres and is identified as El Paso County Schedule No. 64362-00-018. The parcel is currently zoned PBC AO, "Planned Business Center, within the Airport Overlay". It is our understanding that the zoning is to be changed to PUD – "Planned Unit Development". The parcel has a relatively gentle slope down to the southwest with an elevation difference of approximately 13 to 16 feet across the site.

Previous Studies and Field Investigation

Reports of previous geotechnical engineering/ geological investigations for this site by RMG was considered in the preparation of this report and is listed below.

1. Preliminary Subsurface Soils Investigation, Hancock and Powers Road, EPC Schedule No. 643200018 and 6436100017, Colorado Springs, Colorado, prepared by RMG – Rocky Mountain Group, last dated August 17, 2020, Job No. 177709.

Geologic Conditions

Based upon our site reconnaissance, review of the *Colorado Springs Subsidence Investigation* and *State of Colorado Mined Land Reclamation*, by Dames and Moore, 1985, the site exhibits the following characteristics with regard to the requirements specified in the referenced Application Form for a Geologic Hazard Waiver:

- **Does not** have slopes (existing or proposed) exceeding thirty-three percent or which are otherwise considered to be unstable or potentially unstable,
- Does not lie within a known area of underground mining, and
- **Does not** have a history of undocumented fill activity or a history of known landfill activity.

Closing

Our professional services were performed using that degree of care and skill ordinarily exercised, under similar circumstances, by geotechnical engineers practicing in this or similar localities. RMG does not warrant the work of regulatory agencies or other third parties supplying information which may have been used during the preparation of this report. No warranty, express or implied is made by the preparation of this report. Third parties reviewing this report should draw their own conclusions regarding site conditions and specific construction techniques to be used on this project.

The scope of services for this project does not include, either specifically or by implication, environmental assessment of the site or identification of contaminated or hazardous materials or conditions. Development of recommendations for the mitigation of environmentally related conditions, including but not limited to biological or toxicological issues, are beyond the scope of this report. If the Client desires investigation into the potential for such contamination or conditions, other studies should be undertaken.

If we can be of further assistance in discussing the contents of this report or analysis of the proposed development, from a geotechnical engineering point-of-view, please feel free to contact our office.

Tony Munger, P.E.

Cordially, Reviewed by,

RMG – Rocky Mountain Group RMG – Rocky Mountain Group

Kelli Zigler

Kelli Zigler

Project Geologist Geotechnical Project Manager

RMG – Rocky Mountain Group