



ENG-CDR20004-R5-CDs.pdf Markup Summary

1 (1)



Subject: Stormwater Comments Color
Page Index: 1
Date: 10/30/2022 7:46:18 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 1


3 (1)



Subject: Callout
Page Index: 3
Date: 10/18/2022 1:09:24 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 3


Doesn't match on all sheets

5 (2)



Subject: Engineer
Page Index: 5
Date: 10/30/2022 2:42:57 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 5


define colors



Subject: Engineer
Page Index: 5
Date: 10/30/2022 2:43:13 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 5

show on figure

9 (2)



Subject: Callout
Page Index: 9
Date: 10/16/2022 5:12:47 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 9


turn off?



Subject: Engineer
Page Index: 9
Date: 10/30/2022 2:47:02 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 9


match line types

10 (3)



Subject: Callout
Page Index: 10
Date: 10/16/2022 5:13:51 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 10

Turn off future lots or label and add a note that these are not approved.




Subject:
Page Index: 10
Date: 10/16/2022 5:14:28 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 10



Subject: Callout
Page Index: 10
Date: 10/16/2022 5:15:47 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 10

Not shown on this sheet?

11 (1)



Subject:
Page Index: 11
Date: 10/16/2022 5:16:00 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 11

12 (1)



Subject:
Page Index: 12
Date: 10/16/2022 5:17:16 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 12

17 (1)



Subject: Callout
Page Index: 17
Date: 10/16/2022 5:25:19 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 17

2 sets of stations is confusing

22 (14)




Subject:
Page Index: 22
Date: 10/16/2022 5:31:32 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22




Subject: Callout
Page Index: 22
Date: 10/16/2022 5:32:10 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22

Adjust viewport




Subject: Callout
Page Index: 22
Date: 10/16/2022 5:32:36 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22

Show property line and utilities




Subject: Callout
Page Index: 22
Date: 10/16/2022 5:35:07 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22

Label station, elevations



Subject: Callout
Page Index: 22
Date: 10/16/2022 5:36:04 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22

Label average channel grade




Subject: Callout
Page Index: 22
Date: 10/17/2022 11:27:38 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22

This line should be upstream from the top of each downstream grade control structure. Label stable grade. A dotted linetype might be better.




Subject: Callout
Page Index: 22
Date: 10/16/2022 5:39:26 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22


delete gray line?



Subject: Arrow
Page Index: 22
Date: 10/17/2022 11:28:00 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22



Subject: Arrow
Page Index: 22
Date: 10/17/2022 11:28:43 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22




Subject: Delete
Page Index: 22
Date: 10/17/2022 11:29:21 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22

Delete




Subject: Delete
Page Index: 22
Date: 10/17/2022 11:29:27 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 22


Delete



Subject: Arrow
 Page Index: 22
 Date: 10/17/2022 11:29:44 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 22



Subject:
 Page Index: 22
 Date: 10/18/2022 10:16:45 AM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 22




Subject:
 Page Index: 22
 Date: 10/18/2022 10:16:53 AM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 22

23 (2)



Subject: Callout
 Page Index: 23
 Date: 10/16/2022 5:41:10 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 23

41?




Subject:
 Page Index: 23
 Date: 10/16/2022 5:42:32 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 23

24 (7)




Subject: Callout
 Page Index: 24
 Date: 10/16/2022 5:44:53 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 24

relocate trail?




Subject: Callout
Page Index: 24
Date: 10/16/2022 5:45:19 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 24


label spillway/rundown protection



Subject: Arrow
Page Index: 24
Date: 10/17/2022 11:13:43 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 24




Subject: Arrow
Page Index: 24
Date: 10/17/2022 11:14:19 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 24




Subject: Text Box
Page Index: 24
Date: 10/17/2022 11:16:44 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 24

1.35/796.35=0.0017




Subject: Arrow
Page Index: 24
Date: 10/17/2022 11:18:18 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 24




Subject: Callout
Page Index: 24
Date: 10/18/2022 10:39:16 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 24

Extend sheet pile down past stable grade?




Subject: Callout
Page Index: 25
Date: 10/17/2022 11:04:34 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25


This line doesn't look right



Subject: Arrow
Page Index: 25
Date: 10/18/2022 10:41:56 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25




Subject: Arrow
Page Index: 25
Date: 10/18/2022 10:40:37 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25




Subject: Arrow
Page Index: 25
Date: 10/18/2022 10:29:20 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25

Based on stable grade, another grade control appears to be needed here or here.




Subject: Callout
Page Index: 25
Date: 10/18/2022 10:41:48 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25


Modeling indicates supercritical flows - verify stability.



Subject: Callout
Page Index: 25
Date: 10/18/2022 10:34:09 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25



Subject: Arrow
Page Index: 25
Date: 10/18/2022 10:40:00 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25




Subject: Callout
Page Index: 25
Date: 10/18/2022 10:42:03 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25

Extend sheet pile down past stable grade?




Subject: Line
Page Index: 25
Date: 10/18/2022 10:43:15 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25




Subject: Callout
Page Index: 25
Date: 10/18/2022 10:50:16 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 25

Detail spillway and outfall pipe




Subject: Highlight
Page Index: 25
Date: 10/30/2022 3:31:14 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 25

26 (8)




Subject: Arrow
Page Index: 26
Date: 10/18/2022 12:10:21 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26




Subject: Callout
Page Index: 26
Date: 10/18/2022 10:34:56 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26

Modeling indicates supercritical flows - verify stability.




Subject: Callout
Page Index: 26
Date: 10/18/2022 12:10:32 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26

Show cutoff wall




Subject: Line
Page Index: 26
Date: 10/18/2022 10:46:06 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26




Subject: Callout
Page Index: 26
Date: 10/18/2022 10:47:13 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26

Extend sheet pile down past stable ground?




Subject: Line
Page Index: 26
Date: 10/18/2022 10:47:35 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26



Subject: Callout
Page Index: 26
Date: 10/18/2022 10:52:34 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26


too many contours?



Subject: Callout
Page Index: 26
Date: 10/18/2022 1:10:39 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 26

Too many contours?


27 (12)




Subject: Arrow
Page Index: 27
Date: 10/18/2022 11:20:47 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27



Subject: Arrow
Page Index: 27
Date: 10/17/2022 11:23:39 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27




Subject: Arrow
Page Index: 27
Date: 10/17/2022 11:23:10 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27




Subject: Callout
Page Index: 27
Date: 10/18/2022 10:53:59 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27


Show and label existing grade control sheet pile structure and elevations



Subject: Arrow
Page Index: 27
Date: 10/18/2022 10:55:02 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27




Subject: Arrow
Page Index: 27
Date: 10/18/2022 11:18:49 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27




Subject: Callout
Page Index: 27
Date: 10/18/2022 11:19:48 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27

Label grades and grade break



Subject: Callout
Page Index: 27
Date: 10/18/2022 2:59:10 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27


Extend sheet pile down past stable grade? (15' total on detail)




Subject:
Page Index: 27
Date: 10/18/2022 11:21:05 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27



Subject:
Page Index: 27
Date: 10/18/2022 11:21:18 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27




Subject:
Page Index: 27
Date: 10/18/2022 11:21:25 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27



Subject: Callout
Page Index: 27
Date: 10/18/2022 11:21:57 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 27

Extend viewport a little


31 (11)



Subject:
Page Index: 31
Date: 10/18/2022 11:24:39 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 31




Subject:
Page Index: 31
Date: 10/18/2022 11:24:40 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 31




Subject: Callout
Page Index: 31
Date: 10/18/2022 11:25:52 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 31


Tie all ends in to existing grade





Subject:
Page Index: 31
Date: 10/18/2022 11:26:17 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 31





Subject:
Page Index: 31
Date: 10/18/2022 11:26:34 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 31





Subject:
Page Index: 31
Date: 10/18/2022 11:26:45 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 31





Subject:
Page Index: 31
Date: 10/18/2022 11:26:52 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 31





Subject:
Page Index: 31
Date: 10/18/2022 11:26:53 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 31




Subject:
Page Index: 31
Date: 10/18/2022 11:27:05 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 31




Subject:
Page Index: 31
Date: 10/18/2022 11:27:12 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 31




Subject: Engineer
Page Index: 31
Date: 10/30/2022 3:49:29 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 31


adjust text




Subject:
Page Index: 32
Date: 10/18/2022 11:27:47 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 32




Subject:
Page Index: 32
Date: 10/18/2022 11:27:57 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 32




Subject:
Page Index: 32
Date: 10/18/2022 11:28:03 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 32




Subject:
Page Index: 32
Date: 10/18/2022 11:28:15 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 32





Subject:
Page Index: 32
Date: 10/18/2022 11:28:27 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 32





Subject:
Page Index: 32
Date: 10/18/2022 11:28:36 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 32




Subject:
Page Index: 32
Date: 10/18/2022 11:28:39 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 32



Subject:
Page Index: 32
Date: 10/18/2022 11:28:48 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 32




Complete all cross-sections

Subject: Text Box
Page Index: 32
Date: 10/18/2022 11:29:08 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 32

Complete all cross-sections


Show both maintenance roads/trail and lot lines


HPMTHBARX


Subject: Text Box
Page Index: 32
Date: 10/18/2022 11:33:13 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 32


Show both maintenance roads/trail and lot lines

33 (4)



Subject:
Page Index: 33
Date: 10/18/2022 11:29:21 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 33




Subject: Engineer
Page Index: 33
Date: 10/30/2022 3:50:23 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 33


adjust text

WEST SUBDIVISION
SHEROS SUBDIVISION
THING = 410095.404
TING = 235052.131
VATION = 7000.40


LEGEND


Subject: Engineer
Page Index: 33
Date: 10/30/2022 3:50:36 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 33

WEST SUBDIVISION
THING = 411399.962
IG = 233849.817
TION = 7030.82


Subject: Engineer
Page Index: 33
Date: 10/30/2022 3:50:42 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 33


34 (1)





Subject:
Page Index: 34
Date: 10/18/2022 11:30:58 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 34

35 (2)





Subject:
Page Index: 35
Date: 10/18/2022 11:32:26 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 35




Subject:
Page Index: 35
Date: 10/18/2022 11:32:31 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 35

37 (8)




Subject: Callout
Page Index: 37
Date: 10/18/2022 11:34:53 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 37

TRM for slopes >3:1?




Subject: Callout
Page Index: 37
Date: 10/18/2022 11:55:01 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 37

Label existing contour elev.




Subject: Callout
Page Index: 37
Date: 10/18/2022 11:55:53 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 37

complete the contours




Subject: Callout
Page Index: 37
Date: 10/18/2022 11:57:12 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 37

Also label as existing TSB?




Subject: Engineer
Page Index: 37
Date: 10/30/2022 3:58:11 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 37

Stabilized access ramp shall be a minimum of 15ft wide and no greater than 12% slope, in accordance with DCMv1, Chap 11.2.2.




Subject: Engineer
Page Index: 37
Date: 10/30/2022 3:58:18 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 37

Pond bottom should have a minimum slope of 3% to the low flow channel (USDCM Vol 3, detail T-5). Please adjust to minimize future maintenance needs.



Subject: Engineer
Page Index: 37
Date: 10/30/2022 4:01:26 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 37


call out section sheet



Subject: Engineer
Page Index: 37
Date: 10/30/2022 4:15:04 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 37


define line type

38 (3)




Subject: Length Measurement
Page Index: 38
Date: 10/18/2022 12:03:18 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 38

13'-6"



Subject: Length Measurement
Page Index: 38
Date: 10/18/2022 12:03:18 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 38


21'-1"



Subject: Callout
Page Index: 38
Date: 10/18/2022 12:05:09 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 38


Label dimensions or stations

39 (4)




Subject: Callout
Page Index: 39
Date: 10/18/2022 11:58:45 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 39

label slope



Subject: Line
Page Index: 39
Date: 10/30/2022 4:12:58 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 39




Subject: Engineer
 Page Index: 39
 Date: 10/30/2022 4:12:51 PM
 Author: dotprete
 Color: ■
 Layer:
 Space:
 Page Label: 39




Subject: Engineer
 Page Index: 39
 Date: 10/30/2022 4:15:29 PM
 Author: dotprete
 Color: ■
 Layer:
 Space:
 Page Label: 39

provide low flow channel detail

40 (4)




Subject:
 Page Index: 40
 Date: 10/18/2022 12:07:18 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 40



Subject:
 Page Index: 40
 Date: 10/18/2022 12:07:19 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 40

ED OUTLET
 EET ## FOR


Subject:
 Page Index: 40
 Date: 10/18/2022 12:07:49 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 40




Subject: Callout
 Page Index: 40
 Date: 10/18/2022 12:12:36 PM
 Author: dsdrice
 Color: ■
 Layer:
 Space:
 Page Label: 40


Should bottom cutoff wall be at end of culvert?


OUTLET W
ET ## FO

Subject:
Page Index: 41
Date: 10/16/2022 5:41:22 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 41


D OUTLET
ET ## FOR


Subject:
Page Index: 41
Date: 10/16/2022 5:41:33 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 41





Subject: Callout
Page Index: 41
Date: 10/18/2022 12:18:12 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 41

Tie-in grading





Subject:
Page Index: 41
Date: 10/18/2022 12:19:04 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 41




Subject: Callout
Page Index: 41
Date: 10/18/2022 12:19:34 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 41

Something is wrong with existing contours




Subject: Callout
Page Index: 41
Date: 10/18/2022 12:19:52 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 41

provide spot elevations and slope



Subject: Callout
Page Index: 41
Date: 10/18/2022 12:42:30 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 41


Reference sheets 45 and 66 for headwall/wingwall design




Subject: Engineer
Page Index: 41
Date: 10/30/2022 4:29:13 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 41

show section line

42 (7)




Subject:
Page Index: 42
Date: 10/18/2022 12:31:48 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 42



Subject: Callout
Page Index: 42
Date: 10/18/2022 12:32:27 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 42

turn off fence?



Subject: Callout
Page Index: 42
Date: 10/18/2022 12:42:40 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 42


Reference sheets 47 and 67 for headwall/wingwall design





Subject: Engineer
Page Index: 42
Date: 10/30/2022 4:22:00 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 42

Please be consistent with pond labels. Right now they are labeled SRMD Pond #, Stock Pond #, Existing Stock Pond #, and Pond #

SEE 27' PZ-
EET 43 FOR

Subject: Engineer
Page Index: 42
Date: 10/30/2022 4:22:59 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 42




Subject: Engineer
Page Index: 42 and 47
Date: 10/30/2022 4:24:11 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 42

POND 2 SECTION A-A ALIGN
SEE PROFILE ON SHEET 43
show section line.


Subject: Engineer
Page Index: 42 show section line.
Date: 10/30/2022 4:27:30 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 42


43 (6)


Provide complete structural design
for outlet structures


Subject: Text Box
Page Index: 43 Provide complete structural design for outlet structures
Date: 10/18/2022 12:37:57 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 43

CONCRETE SHEET PILE
SEE THIS SHEET FOR
7

Subject:
Page Index: 43
Date: 10/18/2022 12:39:19 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 43




Subject:
Page Index: 43
Date: 10/18/2022 12:39:24 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 43




Subject: Callout
Page Index: 43
Date: 10/18/2022 12:40:17 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 43

Label stations/elevations



Subject: Text Box
Page Index: 43
Date: 10/18/2022 12:44:51 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 43


48



Subject: Text Box
Page Index: 43
Date: 10/18/2022 12:45:13 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 43

48

45 (1)



Subject: Engineer
Page Index: 45
Date: 10/30/2022 4:34:03 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 45

1


47 (1)



Subject: Engineer
Page Index: 47
Date: 10/30/2022 4:34:17 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 47

2


49 (1)




Subject: Callout
Page Index: 49
Date: 10/18/2022 3:07:41 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 49

Please show 100-year WS on all 8 cross-sections

51 (2)




Subject:
Page Index: 51
Date: 10/18/2022 12:53:39 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 51



Subject: Callout
Page Index: 51
Date: 10/18/2022 12:54:47 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 51

Culvert construction first? Show culvert if so


52 (1)



Subject: Callout
Page Index: 52
Date: 10/18/2022 1:11:52 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 52


Supercritical flows?

56 (2)



Subject: Callout
Page Index: 56
Date: 10/18/2022 1:05:42 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 56

Something is wrong with contours




Subject: Engineer
Page Index: 56
Date: 10/30/2022 4:47:23 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 56

call out trail type and provide/reference detail

58 (2)




Subject: Highlight
Page Index: 58
Date: 10/18/2022 1:08:12 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 58



Subject: Callout
Page Index: 58
Date: 10/18/2022 1:13:05 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 58

Show sheet pile


60 (1)



Subject: Callout
Page Index: 60
Date: 10/18/2022 3:00:05 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 60


Verify depth

62 (2)



Subject: Callout
Page Index: 62
Date: 10/18/2022 3:03:09 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 62

Verify depth per profile sheet comments.



Subject: Callout
Page Index: 62
Date: 10/18/2022 3:07:07 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 62

Please show 100-year WS on all 8 cross-sections


65 (3)


I+05.00
 08.95

Subject:
Page Index: 65
Date: 10/18/2022 3:10:10 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 65

08.950


Subject:
Page Index: 65
Date: 10/18/2022 3:10:24 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 65





Subject:
Page Index: 65
Date: 10/18/2022 3:10:54 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 65

68 (5)


ED OUTLET
ET ## FOR

Subject:
Page Index: 68
Date: 10/18/2022 3:30:48 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 68




Subject: Engineer
Page Index: 68
Date: 10/30/2022 4:48:44 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 68


MAINTENANC
EET 70 FOR

Subject: Engineer
Page Index: 68
Date: 10/30/2022 4:49:18 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 68


ED OUTLET
EET ## FOR

Subject: Engineer
Page Index: 68
Date: 10/30/2022 4:49:24 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 68


SED MAINTEN
EET 72 FOR


Subject: Engineer
Page Index: 68
Date: 10/30/2022 4:50:14 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 68

SECOND CR

Subject:
Page Index: 69
Date: 10/18/2022 3:31:11 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 69


SECOND



Subject: Engineer
Page Index: 69
Date: 10/18/2022 3:31:34 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 69


-Consider using a base course that will minimize migration of fines when the pond is detaining water.




Subject: Callout
Page Index: 69
Date: 10/18/2022 3:48:20 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 69


Provide plan for trail on west side



Subject: Callout
Page Index: 70
Date: 10/18/2022 3:33:54 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 70


Label conflicts/revisions




Subject: Callout
Page Index: 71
Date: 10/18/2022 3:38:38 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 71

Adjust labels




Subject: Callout
Page Index: 71
Date: 10/18/2022 3:38:47 PM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 71


Label Briargate



Subject:
Page Index: 71
Date: 10/18/2022 3:49:26 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 71



Subject:
Page Index: 71
Date: 10/18/2022 3:49:40 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 71




Subject:
Page Index: 71
Date: 10/18/2022 3:49:51 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 71



Subject: Callout
Page Index: 71
Date: 10/18/2022 3:50:36 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 71


Hatch trail



Subject: Engineer
Page Index: 71
Date: 10/30/2022 4:46:20 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 71

provide detail

72 (3)




Subject: Callout
Page Index: 72
Date: 10/18/2022 3:44:45 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 72

Show proposed lot lines and numbers



Subject: Callout
Page Index: 72
Date: 10/18/2022 3:44:28 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 72


Label Briargate



Subject: Callout
Page Index: 72
Date: 10/18/2022 3:44:58 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 72


Label access trail

73 (3)




Subject: Callout
Page Index: 73
Date: 10/18/2022 3:45:38 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 73

Show turnaround



Subject: Callout
Page Index: 73
Date: 10/18/2022 3:51:11 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 73


Don't show future lots and roads or label as conceptual (not reviewed)



Subject: Callout
Page Index: 73
Date: 10/18/2022 3:47:51 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 73


Label access road

74 (4)




Subject: Callout
Page Index: 74
Date: 10/18/2022 3:52:53 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 74

Hatch trail



Subject: Callout
Page Index: 74
Date: 10/18/2022 3:54:04 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 74

Label lot numbers



Subject:
Page Index: 74
Date: 10/18/2022 3:54:13 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 74



Subject: Callout
Page Index: 74
Date: 10/18/2022 3:54:31 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 74


Provide detail

75 (2)



Subject: Callout
Page Index: 75
Date: 10/19/2022 8:03:25 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 75

Show lot lines and numbers



Subject: Callout
Page Index: 75
Date: 10/19/2022 8:04:41 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 75

If there can be a pedestrian trail north of here please show that

76 (1)



Subject: Callout
Page Index: 76
Date: 10/19/2022 8:11:58 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 76

How does overflow spillway tie in? Does it need to be replaced with an inlet?



Subject: Callout
Page Index: 77
Date: 10/19/2022 8:15:45 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 77

Is clearance to sanitary line okay?




Subject: Text Box
Page Index: 77
Date: 10/19/2022 8:14:24 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 77

Label wall heights on these sheets

ENTS SPECIFIED IN




Subject:
Page Index: 78
Date: 10/18/2022 12:35:09 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 78



Subject: Engineer
Page Index: 78
Date: 10/30/2022 7:09:26 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 78

adjust sheet numbers




Subject: Engineer
Page Index: 78
Date: 10/30/2022 7:09:47 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 78

you can remove this since its upfront on the Cds




Subject: Engineer
Page Index: 78
Date: 10/30/2022 7:19:43 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 78

add a note about existing vegetation and percent cover



Subject: Engineer
Page Index: 79
Date: 10/30/2022 7:11:01 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 79

show on figure



Subject: Engineer
Page Index: 79
Date: 10/30/2022 7:12:14 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 79

-Silt fence should be parallel to contours. Placement as shown could channelize runoff. All silt fence not running parallel to contours shall be installed with J-hooks or adjusted as necessary.




Subject: Engineer
Page Index: 79
Date: 10/30/2022 7:40:12 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 79

label all ponds, roads, and adjacent subdivisions/property owners




Subject: Engineer
Page Index: 79
Date: 10/30/2022 7:44:12 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 79

install temporary BMPs to prevent sediment from migrating down stream




Subject: Engineer
Page Index: 81
Date: 10/30/2022 7:18:40 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 81

show hatching on legend




Subject: Callout
Page Index: 83
Date: 10/19/2022 8:23:11 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 83

label these lines




Subject: Engineer
Page Index: 85
Date: 10/30/2022 7:34:18 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 85

add TSBs and SCLs




Subject: Callout
Page Index: 86
Date: 10/19/2022 9:26:06 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 86

If this area is a wetland should the TSB be in a defined area?




Subject: Engineer
Page Index: 86
Date: 10/30/2022 7:26:16 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 86

Provide details of temporary sediment basin including riser pipe diameter and perforation sizing, number of rows of holes, required volume, location of outlet pipe and spillway, and tributary area to the sediment basin. And provide contours for sediment basin.




Subject: Engineer
Page Index: 86
Date: 10/30/2022 7:29:22 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 86

what is this line?



Subject: Engineer
Page Index: 86
Date: 10/30/2022 7:30:25 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 86


label contours



Subject: Engineer
Page Index: 86
Date: 10/30/2022 7:31:02 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 86

is CF necessary here if you have SF along the LOC perimeter

91 (2)



Subject: Engineer
Page Index: 91
Date: 10/30/2022 7:36:32 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 91


include quantities for ECB, seeding/mulching



Subject: Engineer
Page Index: 91
Date: 10/30/2022 7:38:06 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 91

final should have all temporary BMPs removed (or grayed out) from the figures

92 (1)



Subject: Callout
Page Index: 92
Date: 10/19/2022 11:10:06 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 92


clarify or delete these paths

93 (4)



Subject: Callout
Page Index: 93
Date: 10/19/2022 11:12:02 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 93

clarify or delete these paths




Subject: Callout
Page Index: 93
Date: 10/19/2022 11:16:44 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 93


Label lot numbers (all sheets)



Subject:
Page Index: 93
Date: 10/19/2022 11:13:43 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 93

Label lot numbers (all sheets)





Subject: Callout
Page Index: 93
Date: 10/19/2022 11:15:22 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 93


Delete any unnecessary lines, label if needed

94 (4)





Subject:
Page Index: 94
Date: 10/19/2022 11:16:01 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 94



Subject: Callout
Page Index: 94
Date: 10/19/2022 11:16:25 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 94


label



Subject: Callout
Page Index: 94
Date: 10/19/2022 11:17:44 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 94


Label road names (all sheets)




Subject: Engineer
Page Index: 94
Date: 10/30/2022 7:41:00 PM
Author: dotprete
Color: 
Layer:
Space:
Page Label: 94

remove

95 (3)




Subject: Callout
Page Index: 95
Date: 10/19/2022 11:18:07 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: 95

Label Briargate



Subject: Callout
Page Index: 95
Date: 10/19/2022 11:18:32 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 95

Remove CF?



Subject: Engineer
Page Index: 95
Date: 10/30/2022 7:41:34 PM
Author: dotprete
Color: ■
Layer:
Space:
Page Label: 95

show location on key

96 (1)



Subject:
Page Index: 96
Date: 10/19/2022 11:19:07 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 96

97 (1)



Subject: Text Box
Page Index: 97
Date: 10/19/2022 9:25:13 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: 97

Provide all applicable details including RRB and rock check dam detail for channel