ENG-CDR20004-R5-MDDP.pdf Markup Summary

2 (1)

Paso County:

d in accordance with the requirements of the El Paso C image Criteria Manual, Volumes 1 and 2 and Engineerin

Joshua Palmer

Subject: Callout Page Index: 2

Date: 10/14/2022 11:21:52 AM

Author: dsdrice Color: Layer:

Space: Page Label: 2 Joshua Palmer

13 (1)

In a specious may associate the state energy rotated tunestant combining with the contfall of Poul STDDS & 2D P2, Ather results summary from the approved MDDP shows that at DI at TSDD15B appears to be at the design point with the Bows in counted for. Based on as-ball information from previous 3, in SC3-15A is shown draining to DP 26 undetained then disc d Creek, with a story of the story of the story of the Homestead Filing 1 dt 16A and 16B have been consolidated into Poul FSD16 for Subject: Callout Page Index: 13

Date: 10/14/2022 12:12:55 PM

Author: dsdrice Color:

Layer: Space:

Page Label: 13

via storm drain through Homestead Filing 1

17 (2)

1585.2 1882.2 Subject:

Page Index: 17

Date: 10/14/2022 12:20:20 PM

Author: dsdrice

Color: Layer:
Space:

Page Label: 17

1882.2

| Topy No. | Topy No.

Subject: Callout Page Index: 17

Date: 10/14/2022 12:40:39 PM

Author: dsdrice

Layer: Space: Page Label: 17 Staff is still awaiting City concurrence that this is an acceptable flow rate.

19 (1)



Subject: Callout Page Index: 19

Date: 10/14/2022 12:53:35 PM

Author: dsdrice Color:

Layer:

Space: Page Label: 19 Address bank stabilization along the west side of the channel in the Homestead North development (from the Wheatland Drive cul-de-sac to Poco Road) and along Filing 3 at the south end.

90 (1)



Subject: Highlight Page Index: 90

Date: 10/14/2022 12:59:20 PM

Author: dsdrice Color: Layer: Space:

Page Label: 90

361 (1)



Subject: Callout Page Index: 361

Date: 10/14/2022 4:02:09 PM

Author: dsdrice
Color: Layer:
Space:

Page Label: 361

Add a note justifying these changes.

389 (6)



Subject: Callout Page Index: 389

Date: 10/14/2022 11:50:07 AM

Author: dsdrice Color:

Layer: Space:

Page Label: 389

Change color of one layer of the green lines



Subject: Callout Page Index: 389

Date: 10/14/2022 11:57:21 AM

Author: dsdrice

Color: Layer: Space:

Page Label: 389

basin line missing?



Subject: PolyLine Page Index: 389

Date: 10/14/2022 12:11:03 PM

Author: dsdrice

Color: Layer: Space:

Page Label: 389



Subject: Callout Page Index: 389

Date: 10/14/2022 12:11:50 PM

Author: dsdrice

Color: Layer: Space:

Page Label: 389

Storm drain from DP26 to SC



Subject: Highlight

Page Index: 389 Date: 10/14/2022 4:11:05 PM

Author: dsdrice

Color: Layer: Space:

Page Label: 389



Subject: Callout

Page Index: 389 Date: 10/14/2022 4:12:59 PM

Author: dsdrice

Color: Layer: Space:

Page Label: 389

The basin line between main and east tributaries

should follow the existing contours