


ENG-PUDSP21005-R3-GEC.pdf Markup Summary

2 (3)




Subject: Contractor
Page Index: 2
Date: 4/7/2022 12:13:57 PM
Author: EPC Stormwater - Glenn Reese
Color: ■
Layer:
Space:
Page Label: [1] SHT 2 EC INITIAL

Unresolved from Review #1 and #2:
show linetype on legend.



Subject: Callout
Page Index: 2
Date: 4/22/2022 9:13:16 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 2 EC INITIAL

It appears that this is the overflow location of the stock pond - provide a breach on the east to direct flows as intended.



Subject: Arrow
Page Index: 2
Date: 4/22/2022 9:03:27 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 2 EC INITIAL

3 (1)



Subject: Callout
Page Index: 3
Date: 4/22/2022 12:43:23 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 3 INITIAL

Is this a TSB initially? Label if so.

4 (3)



Subject: SW - Comment
Page Index: 4
Date: 4/7/2022 12:13:38 PM
Author: EPC Stormwater - Glenn Reese
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

Unresolved from Review #1 and #2:
Item H and M. If "limits of disturbance" and "construction boundary" are the same, change to "construction boundary/limits of disturbance" or otherwise show as separate linetypes for each on the legend and figure.



Subject: Callout
Page Index: 4
Date: 4/18/2022 3:00:09 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM


Overlapping texts



Subject: Callout
Page Index: 4
Date: 4/18/2022 3:01:58 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

Grading needs to be 50' from existing channel.

6 (5)



Subject: SW - Comment
Page Index: 6
Date: 4/7/2022 12:17:49 PM
Author: EPC Stormwater - Glenn Reese
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

Unresolved comment from Review #1 and #2: Item H and M. If "limits of disturbance" and "construction boundary" are the same, change to "construction boundary/limits of disturbance" or otherwise show as separate linetypes for each on the legend and figure.



Subject: Callout
Page Index: 6
Date: 4/18/2022 3:04:27 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

show all contours



Subject: Callout
Page Index: 6
Date: 4/18/2022 3:05:07 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

Curb and gutter shouldn't be out this far




Subject: Callout
Page Index: 6
Date: 4/22/2022 12:54:13 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

See PDR and comment letter regarding channel design.



Subject: Callout
Page Index: 6
Date: 4/22/2022 12:55:13 PM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

Show maintenance road to outlet structure



Subject: SW - Comment
Page Index: 7
Date: 4/7/2022 12:18:48 PM
Author: EPC Stormwater - Glenn Reese
Color: ■
Layer:
Space:
Page Label: [1] SHT 7 FINAL

Unresolved from Review #1 and #2:
Item H and M. If "limits of disturbance" and
"construction boundary" are the same, change to
"construction boundary/limits of disturbance" or
otherwise show as separate linetypes for each on
the legend and figure.