


ENG-PUDSP21005-R6-GEC.pdf Markup Summary

1 (1)



Subject: Callout
Page Index: 1
Date: 12/14/2022 10:25:55 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 1 COVER


Joshua Palmer

2 (2)



Subject: Callout
Page Index: 2
Date: 12/5/2022 3:57:03 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 2 EC INITIAL


Inlet & Outlet protection?



Subject: Callout
Page Index: 2
Date: 12/14/2022 10:29:12 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 2 EC INITIAL

Areas of dewatering?


3 (1)



Subject: Callout
Page Index: 3
Date: 12/14/2022 10:29:31 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 3 INITIAL


Areas of dewatering?


4 (25)




Subject: Callout
Page Index: 4
Date: 12/14/2022 10:49:07 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM


Label pipes being installed and adjust limits of construction or don't show grading and pipes.





Subject:
Page Index: 4
Date: 12/14/2022 10:39:46 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM




Subject:
Page Index: 4
Date: 12/14/2022 10:39:48 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM




Subject:
Page Index: 4
Date: 12/14/2022 10:39:53 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM




Subject:
Page Index: 4
Date: 12/14/2022 10:39:59 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM



Subject:
Page Index: 4
Date: 12/14/2022 10:40:01 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM




Subject: Callout
Page Index: 4
Date: 12/14/2022 11:55:00 AM
Author: dsdrice
Color: 
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

TSB?




Subject: Callout
Page Index: 4
Date: 12/14/2022 10:49:52 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM


If bank stabilization is being installed approved CDs are required. Adjust limits of construction if so.



Subject:
Page Index: 4
Date: 12/14/2022 10:42:10 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM



Subject:
Page Index: 4
Date: 12/14/2022 10:47:40 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM




Subject:
Page Index: 4
Date: 12/14/2022 10:49:32 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM




Subject: Callout
Page Index: 4
Date: 12/14/2022 10:50:40 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

TSB?



Subject: Callout
Page Index: 4
Date: 12/14/2022 11:55:23 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

Address drainage from low points. Maintain TSBs where appropriate.



Subject: Callout
Page Index: 4
Date: 12/14/2022 10:54:17 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

Add TSB




Subject: Callout
Page Index: 4
Date: 12/14/2022 11:08:56 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

Label pipe




Subject: Callout
Page Index: 4
Date: 12/14/2022 11:09:28 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

Adjust LOD?




Subject:
Page Index: 4
Date: 12/14/2022 11:09:53 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM




Subject: Callout
Page Index: 4
Date: 12/14/2022 11:54:41 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM

TSB?



Subject:
Page Index: 4
Date: 12/14/2022 11:11:05 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 4 EC INTERIM



Subject: Callout
Page Index: 6
Date: 12/5/2022 4:00:13 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

Fix overlapping text




Subject: Note
Page Index: 6
Date: 12/5/2022 4:00:06 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL




Subject: Callout
Page Index: 6
Date: 12/5/2022 4:03:08 PM
Author: CDurham
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

What happened to sanitary sewer & force main?



Subject: SW - Textbox with Arrow
Page Index: 6
Date: 12/13/2022 3:46:36 PM
Author: EPC Stormwater - Glenn Reese
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

Add back in the missing yellow UIA's



Subject: Text Box
Page Index: 6
Date: 12/14/2022 11:08:01 AM
Author: dsdrice
Color: ■
Layer:
Space:
Page Label: [1] SHT 6 FINAL

For Information Only? For Pres-subdivision site grading there will be no curb and gutter and storm drain, only seeding and mulching.