



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
COLORADO SPRINGS, CO 80907
PHONE (719) 531-5599
FAX (719) 531-5238

May 2, 2018

Classic Communities
6385 Corporate Drive, Suite 200
Colorado Springs, Colorado 80919

Attn: Benny Bustos

Re: Density Testing – Roadway Subgrade, Soil Cement
Forest Lakes, Filing 2, Phase 2B
Colorado Springs, Colorado
Report No. 3, Tests 18 – 22

Dear Mr. Bustos:

As requested, personnel of Entech Engineering, Inc. have performed density testing at the above referenced site.

Density testing on this site was performed on April 25, 2018. The density testing indicates that the materials have been adequately compacted at the depths and in the locations noted. Results of the density tests are enclosed with this letter.

We trust that this has provided you with the information you require. Should you have any questions or need further information, please do not hesitate to contact us.

Respectfully Submitted,

ENTECH ENGINEERING, INC.

MHH
Mark H. Hauschild, P.E.
Senior Engineer

MHH/slf

Enclosure

Entech Job No. 152314

F:\AA projects\2015\152314\152314.6cl3.doc




Client: Classic Communities
Entech Job #: 152314.6
Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Filing 2, Phase 2B
Tested By: S. Reardanz
S = standard, ASTM D-698
Subject: Roadway Subgrade
Report Date: 05-02-2018
T = AASHTO, T-180

Test #	Test Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
18	15' east off property line of lots 18 & 19, Lake Mist Drive, 4' south off center line of road, at grade, (soil-cement).	4/25/18	98	95	9.0	SM	M - 128.0 @ 8.4	<input checked="" type="checkbox"/>
19	10' west off property line of lots 2 and 3, Lake Mist Drive, 12' south off center line of road, at grade, (soil-cement).	4/25/18	98	95	8.8	SM	M - 128.0 @ 8.4	<input type="checkbox"/>
20	20' east off property line of lots 26 and 27, Lake Mist Drive, 5' north off center line of road, at grade, (soil-cement).	4/25/18	100	95	9.0	SM	M - 128.0 @ 8.4	<input type="checkbox"/>
21	Lakes Edge Drive, 25' north off property line of lots 13 and 14, 5' west off center line of road, at grade, (soil-cement).	4/25/18	99	95	9.2	SM	M - 128.0 @ 8.4	<input type="checkbox"/>
22	Lakes Edge Drive, 10' north off property line of lot 13 and Tract "A", 4' east off center line of road, at grade, (soil-cement).	4/25/18	98	95	8.4	SM	M - 128.0 @ 8.4	<input type="checkbox"/>

Comments:


Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline



ENTECH ENGINEERING, INC.
 505 Elkton Drive
 Colorado Springs, CO 80907
 (719) 531-5599 • (719) 531-5238 (fax)

FIELD DENSITY RESULTS



Mark H. Hauschild, P.E.