

951 P²⁰¹

SEWAGE DISPOSAL INSPECTION FORM

7122001010

File

Appr: VA & FHA
Yes No

Date of Insp. 4 Sep 70
Sanitarian Xominy

Location: street Number 3120 Mt. Herman Rd occupant Snyder
Legal Description Lot 3, Panaramic Acres, Monument, Colo.
Contractor Snyder plumber Snyder
Type Construction Frame Grade House Sewer 1/4
No. of Bedrooms 2

(Septic Tank)

Primary Treatment:

Type of material Heavy Concrete Block No. Compartments _____
Width 5 Length 11 Depth (eff) 5
Depth (Total) _____ Liquid capacity _____ Gallons 2000

Secondary Treatment:

Leaching Pits (No.) _____ Soil Sand Perc. Test 5 min
Lining Material _____ Capacity in Gallons _____
Diam. _____ Depth _____

Disposal Field _____ Soil Sand Perc. Test 5 min
Total Length of tile lines 100 Number of lines 1
Distance between lines NA Length of each line 100 Absorb. Area: 250
Type of tile plastic Trench Depth 24" Trench Width 30" Grade _____
Type Filter Material 1/2 to 1 1/2 washed Rock Depth: Under Tile 6" Over Tile 2"

Cesspool:

Lining Material _____ Soil _____
Diam. _____ Depth (effl.) _____ Cap. _____

