



ENTECH
 ENGINEERING, INC.
 505 Elkton Drive
 Colorado Springs, CO 80907
 (719) 531-5599 • (719) 531-5238 (fax)

Client:	FLRD #2
Project:	Forest Lakes Residential Development, Filing 5
Entech Job #	192273

CONCRETE TEST

EO			Test #:	9		
Date:	# of Specimens	Specified Strength (psi)	Time of Test	Hours Field Cured	Lab Receive Date:	
8/5/2020	4	4500	11:20 AM	24	8/6/2020	
Specimen Type		Test Type		Type of Cure		
Cylinders 4x8		Field		Tank		
Contractor:		Supplier:		Mix Design Number		
PPC Construction		Pete Lien		90DJ50		
Truck Number		Ticket Number		Batch Time:		
2275		973920		10:16 AM		

Location
 (Curb and Gutter) 4' east of Fire Hydrant #17F1C, west side of Long Valley Drive.

Slump (in.)	Air (%):	Unit Weight (PCF):	Concrete Temp (°F)	Air Temp (°F)
3.5	5.7	140.3	86	77
7-Day Strength	28-Day Strength	-Day Strength	56-Day Strength	-Day Strength
4250				
Average:	Average:	Average:	Average:	Average:
4250				
Break Date:	Break Date:	Break Date:	Break Date:	Break Date:
8/12/2020	9/2/2020			

Remarks:
 7 day results

Specifications: 4500 PSI, 4" Max Slump, 5-8% Air	Break Sequence: 1 @ 7, 2 @ 28, 1 @ hold
-----------------------------------------------------	--------------------------------------------

Summary Comments:
 PPC Construction, Pete Lien

Reviewed By: *PPJ*