



**ENTECH**  
 ENGINEERING, INC.  
 505 Elkton Drive  
 Colorado Springs, CO 80907  
 (719) 531-5599 • (719) 531-5238 (fax)

Client: **FLRD #5**  
 Project: **Forest Lakes Residential Development, Filing 5**  
 Entech Job # **192273**

**CONCRETE TEST**

<b>TG</b>			Test #: <b>19</b>		
Date: <b>8/18/2020</b>	# of Specimens: <b>4</b>	Specified Strength (psi): <b>4500</b>	Time of Test: <b>1:15 PM</b>	Hours Field Cured: <b>24</b>	Lab Receive Date: <b>8/19/2020</b>
<b>Specimen Type</b>		<b>Test Type</b>		<b>Type of Cure</b>	
<b>Cylinders 4x8</b>		<b>Field</b>		<b>Tank</b>	
Contractor: <b>PPC Construction</b>		Supplier: <b>Pete Lien</b>		Mix Design Number: <b>90DJ50</b>	
Truck Number: <b>2277</b>		Ticket Number: <b>974586</b>		Batch Time: <b>12:12 PM</b>	

Location:  
**Inlet walls (south side), Lot 30/31.**

Slump (in.): <b>4.0</b>	Air (%): <b>7.2</b>	Unit Weight (PCF):	Concrete Temp (°F): <b>86</b>	Air Temp (°F): <b>90</b>
-------------------------	---------------------	--------------------	-------------------------------	--------------------------

<i>7-Day Strength</i>	<i>28-Day Strength</i>	<i>-Day Strength</i>	<i>56-Day Strength</i>	<i>-Day Strength</i>
3240	4400			
	4740			
Average: <b>3240</b>	Average: <b>4820</b>	Average:	Average:	Average:
Break Date: <b>8/25/2020</b>	Break Date: <b>9/15/2020</b>	Break Date:	Break Date:	Break Date:

Remarks:  
**28 Day Results**

Specifications: 4500 PSI, 4" Max Slump, 4.5-7.5% Air	Break Sequence: 1@7, 2@28, 1@hold
---------------------------------------------------------	--------------------------------------

Summary Comments:  
**PPC Construction, Pete Lien**

Reviewed By: *RPF*

