



ENTECH
ENGINEERING, INC.

505 ELKTON DRIVE
COLORADO SPRINGS, CO 80907
PHONE (719) 531-5599
FAX (719) 531-5238

August 7, 2020

FLRD #2
2138 Flying Horse Club Drive
Colorado Springs, CO 80921

Attn: Jim Boulton

Re: Density Testing – Sanitary Sewer
Forest Lakes Residential Development, Filing #5
Colorado Springs, Colorado
Report No. 5, Tests 141 – 230

Dear Mr. Boulton,

As requested, personnel of Entech Engineering, Inc. have performed density testing at the above referenced site.

Density testing on this site was performed on July 21 – 31, 2020. The density testing indicates that the materials have been adequately compacted at the depths and in the locations noted. Results of the density tests are enclosed with this letter.

We trust that this has provided you with the information you require. Should you have any questions or need further information, please do not hesitate to contact us.

Respectfully Submitted,

ENTECH ENGINEERING, INC.

MHH
Mark H. Hauschild, P.E.
Senior Engineer

MHH/bo

Enclosure



Entech Job No. 192273

F:\AA projects\2019\192273-FLRD #2-Forest Lakes Residential Development Filing #5-110-ConMat\192273_2cl5.doc

Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
141	Service, Lot 30, Forest Lakes Drive, 6' below grade.	7/21/20	97	95	8.9	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
142	Service, Lot 30, Forest Lakes Drive, 4' below grade.	7/21/20	97	95	9.1	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
143	Service, Lot 30, Forest Lakes Drive, 2' below grade.	7/21/20	97	95	8.5	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
144	Service, Lot 19, Forest Lakes Drive, 10' below grade.	7/21/20	98	95	7.7	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
145	Service, Lot 19, Forest Lakes Drive, 8' below grade.	7/21/20	97	95	8.2	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
146	Service, Lot 19, Forest Lakes Drive, 6' below grade.	7/21/20	97	95	8.1	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
147	Service, Lot 30, Forest Lakes Drive, at grade.	7/22/20	97	95	9.0	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
148	Service, Lot 32, Forest Lakes Drive, 8' below grade.	7/22/20	99	95	8.4	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
149	Service, Lot 3, Forest Lakes Drive, 8' below grade.	7/22/20	98	95	8.3	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
150	Service, Lot 32, Forest Lakes Drive, 6' below grade.	7/22/20	97	95	8.6	SM	M - 127.9 @ 9.2	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline



ENTECH
ENGINEERING, INC.
505 Elkton Drive
Colorado Springs, CO 80907
(719) 531-5599 • (719) 531-5238 (fax)

FIELD DENSITY RESULTS

Mark H. Hauschild, P.E.

Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
151	Service, Lot 3, Forest Lakes Drive, 6' below grade.	7/22/20	98	95	8.5	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
152	Service, Lot 32, Forest Lakes Drive, 4' below grade.	7/22/20	97	95	8.1	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
153	Service, Lot 3, Forest Lakes Drive, 4' below grade.	7/22/20	99	95	9.0	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
154	Service, Lot 19, Forest Lakes Drive, 4' below grade.	7/22/20	99	95	8.0	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
155	Service, Lot 32, Forest Lakes Drive, 2' below grade.	7/22/20	98	95	9.3	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
156	Service, Lot 3, Forest Lakes Drive, 2' below grade.	7/22/20	99	95	9.1	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
157	Service, Lot 5, Forest Lakes Drive, 4' below grade.	7/22/20	97	95	8.3	SM	M - 127.9 @ 9.2	<input type="checkbox"/>
158	Service, Lot 25, Forest Lakes Drive, 8' below grade.	7/27/20	98	95	8.4	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
159	Service, Lot 25, Forest Lakes Drive, 6' below grade.	7/27/20	99	95	8.8	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
160	Service, Lot 25, Forest Lakes Drive, 4' below grade.	7/27/20	99	95	9.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline



ENTECH
ENGINEERING, INC.
505 Elkton Drive
Colorado Springs, CO 80907
(719) 531-5599 • (719) 531-5238 (fax)

FIELD DENSITY RESULTS

Mark H. Hauschild, P.E.


Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
161	Service, Lot 24, Forest Lakes Drive, 8' below grade.	7/27/20	98	95	9.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
162	Service, Lot 24, Forest Lakes Drive, 6' below grade.	7/27/20	98	95	8.7	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
163	Service, Lot 14, Forest Lakes Drive, 8' below grade.	7/27/20	98	95	8.5	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
164	Service, Lot 14, Forest Lakes Drive, 6' below grade.	7/27/20	96	95	7.9	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
165	Service, Lot 25, Forest Lakes Drive, 2' below grade.	7/27/20	99	95	8.2	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
166	Service, Lot 25, Forest Lakes Drive, at grade.	7/27/20	98	95	8.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
167	Service, Lot 24, Forest Lakes Drive, 4' below grade.	7/27/20	99	95	8.6	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
168	Service, Lot 13, Forest Lakes Drive, 8' below grade.	7/28/20	99	95	8.4	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
169	Service, Lot 13, Forest Lakes Drive, 6' below grade.	7/28/20	98	95	9.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
170	Service, Lot 14, Forest Lakes Drive, 4' below grade.	7/28/20	98	95	8.9	SM	M - 126.9 @ 8.8	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline

 <p>ENTECH ENGINEERING, INC. 505 Elkton Drive Colorado Springs, CO 80907 (719) 531-5599 • (719) 531-5238 (fax)</p>	<p>FIELD DENSITY RESULTS</p>	<p><i>Marl H. Haaschild, P.E.</i></p>
--	------------------------------	---------------------------------------

Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Test Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
171	Service, Lot 14, Forest Lakes Drive, 2' below grade.	7/28/20	97	95	9.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
172	Service, Lot 14, Forest Lakes Drive, at grade.	7/28/20	99	95	9.0	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
173	Service, Lot 24, Forest Lakes Drive, 2' below grade.	7/28/20	98	95	8.5	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
174	Service, Lot 24, Forest Lakes Drive, at grade.	7/28/20	98	95	8.9	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
175	Service, Lot 13, Forest Lakes Drive, 4' below grade.	7/28/20	98	95	9.5	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
176	Service, Lot 13, Forest Lakes Drive, 2' below grade.	7/28/20	98	95	9.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
177	Service, Lot 29, Forest Lakes Drive, 8' below grade.	7/28/20	99	95	9.6	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
178	Service, Lot 10, Forest Lakes Drive, 10' below grade.	7/28/20	97	95	8.4	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
179	Service, Lot 29, Forest Lakes Drive, 6' below grade.	7/28/20	99	95	7.7	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
180	Service, Lot 10, Forest Lakes Drive, 8' below grade.	7/28/20	98	95	8.5	SM	M - 126.9 @ 8.8	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline



ENTECH
ENGINEERING, INC.
505 Elkton Drive
Colorado Springs, CO 80907
(719) 531-5599 • (719) 531-5238 (fax)

FIELD DENSITY RESULTS

Mark H. Haseckild, P.E.

Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
181	Service, Lot 13, Forest Lakes Drive, at grade.	7/28/20	98	95	8.8	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
182	Service, Lot 10, Forest Lakes Drive, 6' below grade.	7/28/20	99	95	8.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
183	Service, Lot 33, Forest Lakes Drive, 12' below grade.	7/28/20	98	95	7.9	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
184	Service, Lot 33, Forest Lakes Drive, 10' below grade.	7/28/20	98	95	8.6	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
185	Service, Lot 33, Forest Lakes Drive, 8' below grade.	7/29/20	97	95	8.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
186	Service, Lot 10, Forest Lakes Drive, 4' below grade.	7/29/20	97	95	7.9	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
187	Service, Lot 10, Forest Lakes Drive, 2' below grade.	7/29/20	97	95	8.2	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
188	Service, Lot 33, Forest Lakes Drive, 6' below grade.	7/29/20	98	95	8.7	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
189	Service, Lot 10, Forest Lakes Drive, at grade.	7/29/20	97	95	9.4	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
190	Service, Lot 2, Forest Lakes Drive, 12' below grade.	7/29/20	95	95	9.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline



ENTECH
ENGINEERING, INC.
505 Elkton Drive
Colorado Springs, CO 80907
(719) 531-5599 • (719) 531-5238 (fax)

FIELD DENSITY RESULTS

Mark H. Haaschild, P.E.

Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
191	Service, Lot 2, Forest Lakes Drive, 10' below grade.	7/29/20	96	95	8.2	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
192	Service, Lot 2, Forest Lakes Drive, 8' below grade.	7/29/20	97	95	9.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
193	Service, Lot 2, Forest Lakes Drive, 6' below grade.	7/29/20	98	95	7.9	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
194	Service, Lot 33, Forest Lakes Drive, 4' below grade.	7/29/20	99	95	8.8	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
195	Service, Lot 2, Forest Lakes Drive, 4' below grade.	7/29/20	97	95	8.6	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
196	Service, Lot 33, Forest Lakes Drive, 2' below grade.	7/29/20	96	95	9.2	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
197	Service, Lot 2, Forest Lakes Drive, 2' below grade.	7/29/20	95	95	8.5	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
198	Service, Lot 33, Forest Lakes Drive, at grade.	7/29/20	98	95	8.7	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
199	Service, Lot 2, Forest Lakes Drive, at grade.	7/29/20	97	95	8.2	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
200	Service, Lot 4, Forest Lakes Drive, 10' below grade.	7/29/20	99	95	7.6	SM	M - 130.4 @ 8.1	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline



ENTECH
ENGINEERING, INC.
505 Elkton Drive
Colorado Springs, CO 80907
(719) 531-5599 • (719) 531-5238 (fax)

FIELD DENSITY RESULTS

Mark H. Hauschild, P.E.


Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
201	Service, Lot 5, Forest Lakes Drive, 10' below grade.	7/29/20	98	95	7.7	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
202	Service, Lot 4, Forest Lakes Drive, 8' below grade.	7/29/20	97	95	8.5	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
203	Service, Lot 4, Forest Lakes Drive, 6' below grade.	7/29/20	98	95	8.3	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
204	Service, Lot 5, Forest Lakes Drive, 8' below grade.	7/30/20	98	95	8.0	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
205	Service, Lot 5, Forest Lakes Drive, 6' below grade.	7/30/20	97	95	7.5	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
206	Service, Lot 4, Forest Lakes Drive, 4' below grade.	7/30/20	97	95	7.3	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
207	Service, Lot 5, Forest Lakes Drive, 4' below grade.	7/30/20	99	95	8.1	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
208	Service, Lot 4, Forest Lakes Drive, 2' below grade.	7/30/20	96	95	8.2	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
209	Service, Lot 5, Forest Lakes Drive, 2' below grade.	7/30/20	97	95	7.8	SM	M - 130.4 @ 8.1	<input type="checkbox"/>
210	Service, Lot 5, Forest Lakes Drive, at grade.	7/30/20	98	95	8.3	SM	M - 130.4 @ 8.1	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline

 <p>ENTECH ENGINEERING, INC. 505 Elkton Drive Colorado Springs, CO 80907 (719) 531-5599 • (719) 531-5238 (fax)</p>	<p>FIELD DENSITY RESULTS</p>	<p><i>Mark H. Hauschild, P.E.</i></p>
--	------------------------------	---------------------------------------


Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
211	Service, Lot 4, Forest Lakes Drive, at grade.	7/30/20	96	95	8.0	SM	M - 130.4 @ 8.1	<input checked="" type="checkbox"/>
212	Service, Lot 9, Forest Lakes Drive, 6' below grade.	7/30/20	99	95	8.4	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
213	Service, Lot 9, Forest Lakes Drive, 4' below grade.	7/30/20	98	95	9.2	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
214	Service, Lot 11, Forest Lakes Drive, 6' below grade.	7/30/20	97	95	9.0	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
215	Service, Lot 11, Forest Lakes Drive, 4' below grade.	7/30/20	98	95	8.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
216	Service, Lot 9, Forest Lakes Drive, 2' below grade.	7/30/20	96	95	8.6	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
217	Service, Lot 11, Forest Lakes Drive, 2' below grade.	7/30/20	97	95	8.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
218	Service, Lot 12, Forest Lakes Drive, 8' below grade.	7/30/20	96	95	8.4	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
219	Service, Lot 12, Forest Lakes Drive, 6' below grade.	7/30/20	98	95	9.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
220	Service, Lot 11, Forest Lakes Drive, at grade.	7/30/20	96	95	9.7	SM	M - 126.9 @ 8.8	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline

 <p>ENTECH ENGINEERING, INC. 505 Elkton Drive Colorado Springs, CO 80907 (719) 531-5599 • (719) 531-5238 (fax)</p>	<p>FIELD DENSITY RESULTS</p>	<p><i>Mark H. Hauschild, P.E.</i></p>
--	------------------------------	---------------------------------------


Client: FLRD #2	Entech Job #: 192273.2	Proctor Value Key: M = modified, ASTM D-1557
Project: Forest Lakes Residential Development, Filing 5	Tested By: S. Reardanz	S = standard, ASTM D-698
Subject: Sanitary Sewer	Report Date: 08-06-2020	T = AASHTO, T-180

Test #	Location	Testing Date	Percent Compaction	Percent Required	Percent Moisture	Soil Type	Proctor Type/Value	Pass/Fail
221	Service, Lot 9, Forest Lakes Drive, at grade.	7/30/20	97	95	9.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
222	Service, Lot 12, Forest Lakes Drive, 4' below grade.	7/31/20	97	95	8.5	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
223	Service, Lot 12, Forest Lakes Drive, 2' below grade.	7/31/20	96	95	8.6	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
224	Service, Lot 15, Forest Lakes Drive, 10' below grade.	7/31/20	97	95	8.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
225	Service, Lot 15, Forest Lakes Drive, 8' below grade.	7/31/20	95	95	7.7	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
226	Service, Lot 15, Forest Lakes Drive, 6' below grade.	7/31/20	95	95	7.9	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
227	Service, Lot 12, Forest Lakes Drive, at grade.	7/31/20	96	95	8.3	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
228	Service, Lot 15, Forest Lakes Drive, 4' below grade.	7/31/20	95	95	7.7	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
229	Service, Lot 15, Forest Lakes Drive, 2' below grade.	7/31/20	96	95	8.5	SM	M - 126.9 @ 8.8	<input type="checkbox"/>
230	Service, Lot 15, Forest Lakes Drive, at grade.	7/31/20	95	95	8.1	SM	M - 126.9 @ 8.8	<input type="checkbox"/>

Comments:

Scope of Observation: PERIODIC; CONTRACTOR'S OR CLIENT'S REPRESENTATIVE ADVISED

All dimensions are approximate. Cl. = Centerline

 <p>ENTECH ENGINEERING, INC. 505 Elkton Drive Colorado Springs, CO 80907 (719) 531-5599 • (719) 531-5238 (fax)</p>	<p>FIELD DENSITY RESULTS</p>	<p><i>Mark H. Hauschild, P.E.</i></p>
--	------------------------------	---------------------------------------