



**ENTECH**  
 ENGINEERING, INC.  
 505 Elkton Drive  
 Colorado Springs, CO 80907  
 (719) 531-5599 • (719) 531-5238 (fax)

Client: **FLRD #2**  
 Project: **Forest Lakes Residential Development, Filing 5**  
 Entech Job # **192273**

**CONCRETE TEST**

<b>EO</b>			<b>Test #: 16</b>		
Date: 8/14/2020	# of Specimens: 4	Specified Strength (psi): 4500	Time of Test: 10:15 AM	Hours Field Cured: 24	Lab Receive Date: 8/15/2020

<b>Specimen Type</b>	<b>Test Type</b>	<b>Type of Cure</b>
<b>Cylinders 4x8</b>	<b>Field</b>	<b>Tank</b>

Contractor: <b>PPC Construction</b>	Supplier: <b>Pete Lien</b>	Mix Design Number: <b>90DJ50</b>
-------------------------------------	----------------------------	----------------------------------

Truck Number: <b>311</b>	Ticket Number: <b>974419</b>	Batch Time: <b>9:27 AM</b>
--------------------------	------------------------------	----------------------------

Location:  
 Trickle channel, 5' northeast and 3' northwest of southwest corner of pond, southwest side of Pond C.

Slump (in.): <b>3.0</b>	Air (%): <b>7.2</b>	Unit Weight (PCF): <b>138.9</b>	Concrete Temp (°F): <b>83</b>	Air Temp (°F): <b>92</b>
-------------------------	---------------------	---------------------------------	-------------------------------	--------------------------

<i>7-Day Strength</i>	<i>28-Day Strength</i>	<i>-Day Strength</i>	<i>56-Day Strength</i>	<i>-Day Strength</i>
3800				
Average: <b>3800</b>	Average:	Average:	Average:	Average:
Break Date: <b>8/21/2020</b>	Break Date: <b>9/11/2020</b>	Break Date:	Break Date:	Break Date:

Remarks:  
**7 Day Results**

Specifications: 4500 PSI, 4" Max Slump, 5-8% Air	Break Sequence: 1@7, 2@28, 1@hold
-----------------------------------------------------	--------------------------------------

Summary Comments:  
**PPC Construction, Pete Lien**

Reviewed By: *[Signature]*