



**ENTECH**  
 ENGINEERING, INC.  
 505 Elktion Drive  
 Colorado Springs, CO 80907  
 (719) 531-5599 • (719) 531-5238 (fax)

Client: **FLRD #5**  
 Project: **Forest Lakes Residential Development, Filing 5**  
 Entech Job # **192273**

**CONCRETE TEST**

<b>GR</b>			Test #: <b>46</b>		
Date: <b>4/13/2021</b>	# of Specimens: <b>4</b>	Specified Strength (psi): <b>4500</b>	Time of Test: <b>7:57 AM</b>	Hours Field Cured: <b>24</b>	Lab Receive Date: <b>4/13/2021</b>
<b>Specimen Type</b>		<b>Test Type</b>		<b>Type of Cure</b>	
<b>Cylinders 4x8</b>		<b>Field</b>		<b>Tank</b>	
Contractor: <b>Trax Construction</b>		Supplier: <b>Transit Mix</b>		Mix Design Number: <b>T34562110</b>	
Truck Number: <b>29</b>		Ticket Number: <b>86477609</b>		Batch Time: <b>7:43 AM</b>	

Location:  
**Sidewalk (39.059928, -104.897858)**

Slump (in.): <b>2.0</b>	Air (%): <b>5.0</b>	Unit Weight (PCF): <b>142.9</b>	Concrete Temp (°F): <b>67</b>	Air Temp (°F): <b>32</b>
-------------------------	---------------------	---------------------------------	-------------------------------	--------------------------

7-Day Strength	28-Day Strength	-Day Strength	56-Day Strength	-Day Strength
4610	5170			
	5640			
	5660			
Average: <b>4610</b>	Average: <b>5490</b>	Average:	Average:	Average:
Break Date: <b>4/20/2021</b>	Break Date: <b>5/11/2021</b>	Break Date:	Break Date:	Break Date:

Remarks:  
**28 Day Results**

Specifications: **4500 PSI, 5-8% Air, 4" Max Slump**  
 Break Sequence: **1@7, 3@28**

Summary Comments:  
**Trax Construction, Transit Mix**

Reviewed By: *RSJ*

