



**ENTECH**  
 ENGINEERING, INC.  
 505 Elkton Drive  
 Colorado Springs, CO 80907  
 (719) 531-5599 • (719) 531-5238 (fax)

Client: **FLRD #6**  
 Project: **Forest Lakes Residential Development, Filing 6**  
 Entech Job # **201326**

**CONCRETE TEST**

<b>J. Brunk</b>			Test #: <b>14</b>		
Date: <b>3/3/2022</b>	# of Specimens: <b>4</b>	Specified Strength (psi): <b>4000</b>	Time of Test: <b>11:20 AM</b>	Hours Field Cured: <b>24</b>	Lab Receive Date: <b>3/4/2022</b>
<b>Specimen Type</b>		<b>Test Type</b>		<b>Type of Cure</b>	
<b>Cylinders 4x8</b>		<b>Field</b>		<b>Lab</b>	
Contractor: <b>Trax Construction</b>		Supplier: <b>Transit Mix</b>		Mix Design Number: <b>74082110</b>	
Truck Number: <b>40</b>		Ticket Number: <b>86588094</b>		Batch Time: <b>10:47 AM</b>	

Location:  
**Median; GPS Coordinates: (39.06141° N, 104.90521° W)**

Slump (in.): <b>3.0</b>	Air (%): <b>6.0</b>	Unit Weight (PCF): <b>138.0</b>	Concrete Temp (°F): <b>70</b>	Air Temp (°F): <b>63</b>
-------------------------	---------------------	---------------------------------	-------------------------------	--------------------------

<i>7-Day Strength</i>	<i>28-Day Strength</i>	<i>-Day Strength</i>	<i>56-Day Strength</i>	<i>-Day Strength</i>
4190				
Average: <b>4190</b>	Average:	Average:	Average:	Average:
Break Date: <b>3/10/2022</b>	Break Date: <b>3/31/2022</b>	Break Date:	Break Date:	Break Date:

Remarks:  
**7 Day Results**

Specifications: **4000 PSI, 4" Max Slump, 5-8% Air**      Break Sequence: **1@7, 3@28**

Summary Comments:  
**Trax Construction, Transit Mix**

Reviewed By: *[Signature]*