

Client: Elliott Van Stelle
Structures, Inc.
4 Inverness Court East, Suite 250
Englewood, CO 80112

Forest Lakes Bridges

Report Date: Sep 20, 2021

Work Order No.: 21-8536.ConcreteCylinderPickup.0008; ver: 1

Work Order Date: Sep 18, 2021

Reviewed by: Josiah Johnson

Concrete Sample Retrieval

As required, previously cast concrete specimens were collected by a representative of GROUND, transported to the laboratory, and prepared for testing. Test results will be forwarded upon completion.

Collected by: Brian Rivera

On-Site Notifications

Name	Company
Elliott Van Stelle	Structures, Inc.

Results apply only to the specific items and locations referenced and at the time of testing, observations or special inspections. This report should not be reproduced, except in full, without the written permission of GROUND Engineering Consultants, Inc.


41 Inverness Drive East, Englewood, Colorado

www.groundeng.com

303-289-1989

Englewood | Commerce City | Loveland | Granby | Gypsum | Colorado Springs

Page 1 of 1



Client: Elliott Van Stelle
Structures, Inc.
4 Inverness Court East, Suite 250
Englewood, CO 80112

Forest Lakes Bridges

Report Date: Mar 30, 2022

Work Order No.: 21-8536.ConcreteCylinderPickup.0025; ver: 1

Work Order Date: Mar 25, 2022

Reviewed by: Josiah Johnson

Concrete Sample Retrieval

As required, previously cast concrete specimens were collected by a representative of GROUND, transported to the laboratory, and prepared for testing. Test results will be forwarded upon completion.

Collected by: Justin Brookhart

Results apply only to the specific items and locations referenced and at the time of testing, observations or special inspections. This report should not be reproduced, except in full, without the written permission of GROUND Engineering Consultants, Inc.

41 Inverness Drive East, Englewood, Colorado

www.groundeng.com

303-289-1989

Englewood | Commerce City | Loveland | Granby | Gypsum | Colorado Springs

Page 1 of 1