



J&K Geological Services
18291 Smokey Pine Rd
Peyton, Colorado 80831
(719) 499-5431

April 15, 2022

Home Run Restorations
5090 Wileys Road
Peyton, CO. 80831

RE: Wyoming Estates
J&K JOB: 220401

Gentlemen,

Attached with this letter is the density test results obtained on 04/03 and 04/07/22 at the above referenced site. Based upon our understanding of the El Paso County new road specifications, the testing program satisfies the regulations. The material consisted of an imported Class 6 Base Coarse.

We trust this provides the information you require at this time. If you have any questions, please contact our office at your convenience.

Respectfully submitted,

J&K GEOLOGIC SERVICES, LLC

James F. Frohbieter
Professional Geologist

**THIS DOCUMENT WAS
PREPARED UNDER MY
DIRECT SUPERVISION:**

Guenther Polok, P.E.

JFF/ksf

CLIENT: Home Run Restoration Date: 04/3-7/2022

ADDRESS: Wyoming Estates (Teleo Court) Technician: JF

Test No.	% Compaction	% Required	% Moisture	Proctor Value	ASTM Test Designation
1	92.2	90	4.9	140.1 @ 5.2%	D-1557
2	93.5	90	4.3	140.1 @ 5.2%	D-1557
3	94.0	90	4.7	140.1 @ 5.2%	D-1557
4	93.3	90	9.8	120.3 @ 11.0%	D-1557
5					
6					
7					
8					
9					
10					

TEST LOCATIONS:

1	Center of Cul de Sac @ base coarse grade.
2	225ft. West of Curtis Road on Teleo Court Centerline, @ base coarse grade.
3	75ft. West of Curtis Road on Teleo Court Centerline, @ base coarse grade.
4	25ft. West of Curtis Road on Teleo Court Centerline, @ base coarse grade.
5	
6	
7	
8	
9	
10	

Notes: Test locations and elevations were provided by client. Test results indicate density at locations and elevations shown above. J&K GEOLOGIC SERVICES, LLC does not warrant or guarantee the performance of the trench.
 *Indicates failing test result



DENSITY TEST RESULTS

J&K GEOLOGIC SERVICES, LLC