

March 30, 2022

Home Run Restorations 5090 Wileys Road Peyton, CO. 80831

**RE: Wyoming Estates** 

Ellicott CO

J&K JOB: 220317

To whom it may concern;

This letter is provided to inform you that at your request, personnel of J&K Geological Services LLC made a site visit to the address referenced above on 03/29/2022. The purpose of the site visit was to perform temperature testing on the existing road subgrade of Teleo Court to verify the roadway is frost free.

An Ames Instruments 12:1 Infrared Laser Thermometer was utilized to perform the temperature testing. A total of six temperature measurements were taken at three different locations in the section of Teleo Court that is to be paved. One measurement was taken at the ground surface and a second measurement was taken in a hand drilled hole 14 inches below the ground surface.

The temperature measurement results are as follows:

Test #1 taken over the western culvert in Teleo Court, Ground surface temp. 56.0 degrees F, @ depth53.7degrees F.

Test #2- taken in center of cul de sac in Teleo Court, Ground surface temp. 58.7 degrees F, @ depth 53.9degrees F.

Test #3 taken 50 feet West of the Traffic pad in Teleo Court, Ground surface temp. 55.2 degrees F, @ depth 54.7degrees F.

We trust this report provides you with the information you required. Should questions arise or further information is needed, please contact J&K Geological Services at your convenience.

Respectfully submitted,

J&K GEOLOGIC SERVICES, LLC

James F. Frohbieter,

Professional Geologist/Owner J&K Geological Services LLC