



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 92 **Sample #:** 8931 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 80, east pedestrian ramp on Tapeats Dr. **Lat/Long:** 38.9936943 / -104.5784709

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
92	1365 20828786	5.00	Slump: 4 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	80	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
92 / 29510	7	08/12/2026	3470	Type 3

Average Strength (psi): 7 Day - 3470 psi

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 92 **Sample #:** 8931 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 80, east pedestrian ramp on Tapeats Dr. **Lat/Long:** 38.9936943 / -104.5784709

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
92	1365 20828786	5.00	Slump: 4 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	80	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
92 / 29510	7	08/12/2026	3470	Type 3
92 / 29511	28	09/02/2026	4650	Type 5
92 / 29512	28	09/02/2026	4790	Type 3
92 / 29513	28	09/02/2026	4560	Type 2

Average Strength (psi): 7 Day - 3470 psi, 28 Day - 4670 psi

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 93 **Sample #:** 8933 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 64 + 40, north pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.9937938 / -104.5771624

Notes: County Inspector requested this truck be tested since the first truck failed Air.

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
93	1374 20828854	5.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.6 Spec.: 5 - 8	136.8	86	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
93 / 29518	7	08/12/2026	3440	Type 3

Average Strength (psi): 7 Day - 3440 psi

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 93 **Sample #:** 8933 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 64 + 40, north pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.9937938 / -104.5771624

Notes: County Inspector requested this truck be tested since the first truck failed Air.

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
93	1374 20828854	5.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.6 Spec.: 5 - 8	136.8	86	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
93 / 29518	7	08/12/2026	3440	Type 3
93 / 29519	28	09/02/2026	4420	Type 2
93 / 29520	28	09/02/2026	4530	Type 2
93 / 29521	28	09/02/2026	4340	Type 5

Average Strength (psi): 7 Day - 3440 psi, 28 Day - 4430 psi

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 94 **Sample #:** 8942 **Placement Date:** 08/06/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 32 + 30, east pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9937855 / -104.577164

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
94	1379 20829017	5.00	Slump: 5 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
94 / 29617	7	08/13/2026	3180	Type 2

Average Strength (psi): 7 Day - 3180 psi

08/14/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 94 **Sample #:** 8942 **Placement Date:** 08/06/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 32 + 30, east pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9937855 / -104.577164

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
94	1379 20829017	5.00	Slump: 5 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
94 / 29617	7	08/13/2026	3180	Type 2
94 / 29618	28	09/03/2026	4190	Type 3

Average Strength (psi): 7 Day - 3180 psi, 28 Day - 4190 psi

56 Day Breaks will be provided when available.

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 95 **Sample #:** 8965 **Placement Date:** 08/07/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 81
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 31 + 55, west pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9936068 / -104.5774218

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
95	1362 20829328	5.00	Slump: 5 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.8 Spec.: 5 - 8	135.2	83	81

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
95 / 29666	7	08/14/2026	3130	Type 3

Average Strength (psi): 7 Day - 3130 psi

08/14/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 95 **Sample #:** 8965 **Placement Date:** 08/07/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 81
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 31 + 55, west pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9936068 / -104.5774218

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
95	1362 20829328	5.00	Slump: 5 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.8 Spec.: 5 - 8	135.2	83	81

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
95 / 29666	7	08/14/2026	3130	Type 3
95 / 29667	28	09/04/2026	3780	Type 2

Average Strength (psi): 7 Day - 3130 psi, 28 Day - 3780 psi

56 Day Breaks will be provided when available.

09/04/2026

Reviewed by: Austin Nossokoff

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	Raul Directed To Replace
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	Raul Directed To Replace
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0	0
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	4620	4480	0	0
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	0	0	0	0
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	0	0	0	Raul Directed To Replace
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0	0
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0	0
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	County may accept since 1 close and 1 over
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0	Raul Directed To Replace
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	3780	0	0	0	0	0	0
Sidewalk	86	7/27/26	5	5.5	6.6	138.8	3630	4430	0	0	0	0	0	0
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	4180	0	0	0	0	0	0
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	0	0	0	0	0	0	0
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	0	0	0	0	0	0	0
Sidewalk	92	8/5/26	5	4.75	7.2	138	3470	0	0	0	0	0	0	0
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	0	0	0	0	0	0	0
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	0	0	0	0	0	0	0
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	0	0	0	0	0	0	0

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	Raul Directed To Replace
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	Raul Directed To Replace
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0	0
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	4620	4480	0	0
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	4510	4860	0	0
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	0	0	0	Raul Directed To Replace
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0	0
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0	0
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	County may accept since 1 close and 1 over
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0	Raul Directed To Replace
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	3780	0	0	0	0	0	0
Sidewalk	86	7/27/26	5	5.5	6.6	138.8	3630	4430	0	0	0	0	0	0
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	4180	0	0	0	0	0	0
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	0	0	0	0	0	0	0
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	0	0	0	0	0	0	0
Sidewalk	92	8/5/26	5	4.75	7.2	138	3470	0	0	0	0	0	0	0
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	0	0	0	0	0	0	0
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	0	0	0	0	0	0	0
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	0	0	0	0	0	0	0

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		Ok
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		OK
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	Needs Replaced
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		OK
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		OK
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		OK
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		OK
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	Needs Replaced
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		OK
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0	Needs Replaced
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	4620	4480	0	OK
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	4510	4860	0	OK
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	4350	0	0	Needs Replaced
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0	Core
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0	Core
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	Core
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0	Needs Replaced
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	3780	0	0	0	0	0	Needs Replaced
Sidewalk	86	7/27/26	5	5.5	6.6	138.8	3630	4430	0	0	0	0	0	Core
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	4180	0	0	0	0	0	Needs Replaced
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	4240	0	0	0	0	0	Core
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	4300	0	0	0	0	0	Core
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	4420	4530	4340	0	0	0	As County If Core Needed?
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	4190	0	0	0	0	0	Needs Replaced
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	3780	0	0	0	0	0	Needs Replaced

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0 0	
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	0	0	0 0	
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	0	0	0 0	
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	0	0	0 0	
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0 0	
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0 0	
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	County may accept since so close
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0 0	
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	0	0	0	0	0	0 0	
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	0	0	0	0	0	0 0	
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	0	0	0	0	0	0 0	
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	0	0	0	0	0	0 0	
Sidewalk	92	8/5/26	5	4.75	7.2	138	3470	0	0	0	0	0	0 0	
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	0	0	0	0	0	0 0	
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	0	0	0	0	0	0 0	
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	0	0	0	0	0	0 0	



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 1 **Sample #:** 4290 **Placement Date:** 06/05/2025 **Technician:** Michael Crytser **Weather Conditions:** Rain **Air Temp (°F):** 59
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** At Inlet box 13. **Lat/Long:** 38.9932333 / -104.5727586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
1	1198 20727662	10.00	Slump: 4 Spec: 3 - 5	Result: 7.8 Spec.: 5 - 8	136.0	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
1 / 14630	7	06/12/2025	3110	Type 3
1 / 14631	28	07/03/2025	4060	Type 3
1 / 14632	56	07/31/2025	4220	Type 2
1 / 14633	90	09/03/2025	4800	Type 2

Average Strength (psi): 7 Day - 3110 psi, 28 Day - 4060 psi, 56 Day - 4220 psi, 90 Day - 4800 psi

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 1 **Sample #:** 4290 **Placement Date:** 06/05/2025 **Technician:** Michael Crytser **Weather Conditions:** Rain **Air Temp (°F):** 59
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** At Inlet box 13. **Lat/Long:** 38.9932333 / -104.5727586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
1	1198 20727662	10.00	Slump: 4 Spec: 3 - 5	Result: 7.8 Spec.: 5 - 8	136.0	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
1 / 14630	7	06/12/2025	3110	Type 3
1 / 14631	28	07/03/2025	4060	Type 3

Average Strength (psi): 7 Day - 3110 psi, 28 Day - 4060 psi

56 Day Breaks will be provided when available.

07/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 1 **Sample #:** 4290 **Placement Date:** 06/05/2025 **Technician:** Michael Crytser **Weather Conditions:** Rain **Air Temp (°F):** 59
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** At Inlet box 13. **Lat/Long:** 38.9932333 / -104.5727586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
1	1198 20727662	10.00	Slump: 4 Spec: 3 - 5	Result: 7.8 Spec.: 5 - 8	136.0	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
1 / 14630	7	06/12/2025	3110	Type 3
1 / 14631	28	07/03/2025	4060	Type 3
1 / 14632	56	07/31/2025	4220	Type 2

Average Strength (psi): 7 Day - 3110 psi, 28 Day - 4060 psi, 56 Day - 4220 psi

08/12/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 2 **Sample #:** 4300 **Placement Date:** 06/09/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 60
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** Cap of Inlet Box 13. **Lat/Long:** 38.9933771 / -104.5724576

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
2	1378 20727953	3.00	Slump: 3 Spec: 3 - 5	Result: 8 Spec.: 5 - 8	136.8	75	60

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
2 / 14634	7	06/16/2025	3450	Type 2
2 / 14635	28	07/07/2025	4140	Type 5
2 / 14636	56	08/04/2025	4970	Type 2
2 / 14637	56	08/04/2025	4900	Type 3

Average Strength (psi): 7 Day - 3450 psi, 28 Day - 4140 psi, 56 Day - 4930 psi

08/12/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 92 **Sample #:** 8931 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 80, east pedestrian ramp on Tapeats Dr. **Lat/Long:** 38.9936943 / -104.5784709

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
92	1365 20828786	5.00	Slump: 4 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	80	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
92 / 29510	7	08/12/2026	3470	Type 3

Average Strength (psi): 7 Day - 3470 psi

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 92 **Sample #:** 8931 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 80, east pedestrian ramp on Tapeats Dr. **Lat/Long:** 38.9936943 / -104.5784709

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
92	1365 20828786	5.00	Slump: 4 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	80	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
92 / 29510	7	08/12/2026	3470	Type 3
92 / 29511	28	09/02/2026	4650	Type 5
92 / 29512	28	09/02/2026	4790	Type 3
92 / 29513	28	09/02/2026	4560	Type 2

Average Strength (psi): 7 Day - 3470 psi, 28 Day - 4670 psi

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 93 **Sample #:** 8933 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 64 + 40, north pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.9937938 / -104.5771624

Notes: County Inspector requested this truck be tested since the first truck failed Air.

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
93	1374 20828854	5.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.6 Spec.: 5 - 8	136.8	86	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
93 / 29518	7	08/12/2026	3440	Type 3

Average Strength (psi): 7 Day - 3440 psi

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 93 **Sample #:** 8933 **Placement Date:** 08/05/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 64 + 40, north pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.9937938 / -104.5771624

Notes: County Inspector requested this truck be tested since the first truck failed Air.

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
93	1374 20828854	5.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.6 Spec.: 5 - 8	136.8	86	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
93 / 29518	7	08/12/2026	3440	Type 3
93 / 29519	28	09/02/2026	4420	Type 2
93 / 29520	28	09/02/2026	4530	Type 2
93 / 29521	28	09/02/2026	4340	Type 5

Average Strength (psi): 7 Day - 3440 psi, 28 Day - 4430 psi

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 94 **Sample #:** 8942 **Placement Date:** 08/06/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 32 + 30, east pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9937855 / -104.577164

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
94	1379 20829017	5.00	Slump: 5 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
94 / 29617	7	08/13/2026	3180	Type 2

Average Strength (psi): 7 Day - 3180 psi

08/14/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 94 **Sample #:** 8942 **Placement Date:** 08/06/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 32 + 30, east pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9937855 / -104.577164

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
94	1379 20829017	5.00	Slump: 5 3/4 Spec: 2 1/2 - 6 1/2	Result: 7.2 Spec.: 5 - 8	138.0	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
94 / 29617	7	08/13/2026	3180	Type 2
94 / 29618	28	09/03/2026	4190	Type 3

Average Strength (psi): 7 Day - 3180 psi, 28 Day - 4190 psi

56 Day Breaks will be provided when available.

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 95 **Sample #:** 8965 **Placement Date:** 08/07/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 81
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 31 + 55, west pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9936068 / -104.5774218

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
95	1362 20829328	5.00	Slump: 5 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.8 Spec.: 5 - 8	135.2	83	81

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
95 / 29666	7	08/14/2026	3130	Type 3

Average Strength (psi): 7 Day - 3130 psi

08/14/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 95 **Sample #:** 8965 **Placement Date:** 08/07/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 81
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 31 + 55, west pedestrian ramp on Galeros Dr. **Lat/Long:** 38.9936068 / -104.5774218

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
95	1362 20829328	5.00	Slump: 5 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.8 Spec.: 5 - 8	135.2	83	81

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
95 / 29666	7	08/14/2026	3130	Type 3
95 / 29667	28	09/04/2026	3780	Type 2

Average Strength (psi): 7 Day - 3130 psi, 28 Day - 3780 psi

56 Day Breaks will be provided when available.

09/04/2026

Reviewed by: Austin Nossokoff

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	Raul Directed To Replace
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	Raul Directed To Replace
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0	0
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	4620	4480	0	0
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	0	0	0	0
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	0	0	0	Raul Directed To Replace
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0	0
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0	0
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	County may accept since 1 close and 1 over
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0	Raul Directed To Replace
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	3780	0	0	0	0	0	0
Sidewalk	86	7/27/26	5	5.5	6.6	138.8	3630	4430	0	0	0	0	0	0
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	4180	0	0	0	0	0	0
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	0	0	0	0	0	0	0
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	0	0	0	0	0	0	0
Sidewalk	92	8/5/26	5	4.75	7.2	138	3470	0	0	0	0	0	0	0
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	0	0	0	0	0	0	0
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	0	0	0	0	0	0	0
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	0	0	0	0	0	0	0

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	Raul Directed To Replace
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	Raul Directed To Replace
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0	0
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	4620	4480	0	0
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	4510	4860	0	0
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	0	0	0	Raul Directed To Replace
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0	0
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0	0
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	County may accept since 1 close and 1 over
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0	Raul Directed To Replace
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	3780	0	0	0	0	0	0
Sidewalk	86	7/27/26	5	5.5	6.6	138.8	3630	4430	0	0	0	0	0	0
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	4180	0	0	0	0	0	0
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	0	0	0	0	0	0	0
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	0	0	0	0	0	0	0
Sidewalk	92	8/5/26	5	4.75	7.2	138	3470	0	0	0	0	0	0	0
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	0	0	0	0	0	0	0
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	0	0	0	0	0	0	0
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	0	0	0	0	0	0	0

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		Ok
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		OK
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	Needs Replaced
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		OK
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		OK
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		OK
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		OK
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	Needs Replaced
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		OK
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0	Needs Replaced
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	4620	4480	0	OK
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	4510	4860	0	OK
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	4350	0	0	Needs Replaced
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0	Core
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0	Core
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	Core
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0	Needs Replaced
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	3780	0	0	0	0	0	Needs Replaced
Sidewalk	86	7/27/26	5	5.5	6.6	138.8	3630	4430	0	0	0	0	0	Core
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	4180	0	0	0	0	0	Needs Replaced
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	4240	0	0	0	0	0	Core
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	4300	0	0	0	0	0	Core
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	4420	4530	4340	0	0	0	As County If Core Needed?
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	4190	0	0	0	0	0	Needs Replaced
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	3780	0	0	0	0	0	Needs Replaced

Item	Set #	Date	CU. YDS	Slump (in)	Air Content %	Weight	7 Day	28 Day	28 Day	28 Day	56 Day	56 Day	90 Day	Notes
C&G	3	8/7/25	10	1.5	8	134.4	3560	4240	-	-	4810	4990		
C&G	10	9/9/25	7	3.5	8	132	3080	4310	-	-	4720	4450		
C&G	13	9/10/25	10	5	7	133.3	2460	3550	-	-	4300		4390	
C&G	15	9/22/25	6	2.5	6.5	137.2	3400	4420			5290	5180		
Crosspan	16	9/26/25	8	3.5	8	134.4	2910	4360			5140	5030		
Sidewalk	31	11/14/25	10	7	6.8	138.4	3160	4060			4870	4630		
Sidewalk	40	12/9/25	10	4	7.8	134.3	3380	4320			5440	5530		
C&G	53	4/21/26	10	7	8	135.9	2890	3590			4100		4560	
Sidewalk	57	5/15/26	5	4.5	7.6	140	3520	4480	4430		4990			County accepted this concrete 07/15/2026
Sidewalk	64	6/23/26	10	2.25	8	137.2	3630	4120			4680	4790		
Sidewalk	69	6/30/26	7.5	4.75	7.2	138.8	3290	4100	0	0	0	0	0 0	
Sidewalk	70	7/1/26	7.5	4	6.8	137.6	3460	4360	0	0	0	0	0 0	
Sidewalk	71	7/2/26	7.5	4.25	6.6	136.8	3490	4290	0	0	0	0	0 0	
Sidewalk	73	7/8/26	7.5	5.25	7.8	136.4	3090	3620	0	0	0	0	0 0	
Sidewalk	76	7/13/26	10	4.25	7.8	136.4	3510	4320	0	0	0	0	0 0	
Sidewalk	78	7/14/26	5	5.5	7.6	138.8	3380	4260	0	0	0	0	0 0	
C&G	81	7/17/26	7.5	4	5.2	141.2	3460	4710	4390	0	0	0	0	County may accept since so close
Sidewalk	83	7/21/26	5	4.25	7.2	138.4	2880	3960	0	0	0	0	0 0	
Sidewalk	85	7/24/26	6	5.75	7.6	136.4	2890	0	0	0	0	0	0 0	
Sidewalk	88	7/29/26	5	4.5	7.4	138.4	3370	0	0	0	0	0	0 0	
Sidewalk	90	8/3/26	5	4.5	7.6	137.6	3260	0	0	0	0	0	0 0	
Sidewalk	91	8/4/26	7	4.25	7.8	136.4	3400	0	0	0	0	0	0 0	
Sidewalk	92	8/5/26	5	4.75	7.2	138	3470	0	0	0	0	0	0 0	
Sidewalk	93	8/5/26	5	4.25	7.6	136.8	3440	0	0	0	0	0	0 0	
Sidewalk	94	8/6/26	5	5.75	7.2	138	3180	0	0	0	0	0	0 0	
Sidewalk	95	8/7/26	5	5.5	7.8	135.2	3130	0	0	0	0	0	0 0	



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 1 **Sample #:** 4290 **Placement Date:** 06/05/2025 **Technician:** Michael Crytser **Weather Conditions:** Rain **Air Temp (°F):** 59
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** At Inlet box 13. **Lat/Long:** 38.9932333 / -104.5727586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
1	1198 20727662	10.00	Slump: 4 Spec: 3 - 5	Result: 7.8 Spec.: 5 - 8	136.0	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
1 / 14630	7	06/12/2025	3110	Type 3
1 / 14631	28	07/03/2025	4060	Type 3
1 / 14632	56	07/31/2025	4220	Type 2
1 / 14633	90	09/03/2025	4800	Type 2

Average Strength (psi): 7 Day - 3110 psi, 28 Day - 4060 psi, 56 Day - 4220 psi, 90 Day - 4800 psi

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 1 **Sample #:** 4290 **Placement Date:** 06/05/2025 **Technician:** Michael Crytser **Weather Conditions:** Rain **Air Temp (°F):** 59
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** At Inlet box 13. **Lat/Long:** 38.9932333 / -104.5727586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
1	1198 20727662	10.00	Slump: 4 Spec: 3 - 5	Result: 7.8 Spec.: 5 - 8	136.0	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
1 / 14630	7	06/12/2025	3110	Type 3
1 / 14631	28	07/03/2025	4060	Type 3

Average Strength (psi): 7 Day - 3110 psi, 28 Day - 4060 psi

56 Day Breaks will be provided when available.

07/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 1 **Sample #:** 4290 **Placement Date:** 06/05/2025 **Technician:** Michael Crytser **Weather Conditions:** Rain **Air Temp (°F):** 59
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** At Inlet box 13. **Lat/Long:** 38.9932333 / -104.5727586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
1	1198 20727662	10.00	Slump: 4 Spec: 3 - 5	Result: 7.8 Spec.: 5 - 8	136.0	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
1 / 14630	7	06/12/2025	3110	Type 3
1 / 14631	28	07/03/2025	4060	Type 3
1 / 14632	56	07/31/2025	4220	Type 2

Average Strength (psi): 7 Day - 3110 psi, 28 Day - 4060 psi, 56 Day - 4220 psi

08/12/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 2 **Sample #:** 4300 **Placement Date:** 06/09/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 60
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** Cap of Inlet Box 13. **Lat/Long:** 38.9933771 / -104.5724576

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
2	1378 20727953	3.00	Slump: 3 Spec: 3 - 5	Result: 8 Spec.: 5 - 8	136.8	75	60

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
2 / 14634	7	06/16/2025	3450	Type 2
2 / 14635	28	07/07/2025	4140	Type 5
2 / 14636	56	08/04/2025	4970	Type 2
2 / 14637	56	08/04/2025	4900	Type 3

Average Strength (psi): 7 Day - 3450 psi, 28 Day - 4140 psi, 56 Day - 4930 psi

08/12/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 2 **Sample #:** 4300 **Placement Date:** 06/09/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 60
Contractor: Vista Concrete **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Inlet Box **Location Details:** Cap of Inlet Box 13. **Lat/Long:** 38.9933771 / -104.5724576

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
2	1378 20727953	3.00	Slump: 3 Spec: 3 - 5	Result: 8 Spec.: 5 - 8	136.8	75	60

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
2 / 14634	7	06/16/2025	3450	Type 2
2 / 14635	28	07/07/2025	4140	Type 5

Average Strength (psi): 7 Day - 3450 psi, 28 Day - 4140 psi

56 Day Breaks will be provided when available.

07/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 3 **Sample #:** 4817 **Placement Date:** 08/07/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 69

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Northeast corner of Crystal Falls and House Rock at marker Co/36 **Lat/Long:** 38.9931552 / -104.5753017

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
3	1372 20745518	10.00	Slump: 1 1/2 Spec: - 2	Result: 8 Spec.: 5 - 8	134.4	88	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
3 / 16164	7	08/14/2025	3560	Type 2
3 / 16165	28	09/04/2025	4240	Type 2

Average Strength (psi): 7 Day - 3560 psi, 28 Day - 4240 psi

56 Day Breaks will be provided when available.

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 3 **Sample #:** 4817 **Placement Date:** 08/07/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 69

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Northeast corner of Crystal Falls and House Rock at marker Co/36 **Lat/Long:** 38.9931552 / -104.5753017

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
3	1372 20745518	10.00	Slump: 1 1/2 Spec: - 2	Result: 8 Spec.: 5 - 8	134.4	88	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
3 / 16164	7	08/14/2025	3560	Type 2
3 / 16165	28	09/04/2025	4240	Type 2
3 / 16166	56	10/02/2025	4810	Type 3
3 / 16167	56	10/02/2025	4990	Type 3

Average Strength (psi): 7 Day - 3560 psi, 28 Day - 4240 psi, 56 Day - 4900 psi

10/10/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 4 **Sample #:** 4828 **Placement Date:** 08/07/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 90
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** East on crystal falls between lots 213 and 214 **Lat/Long:** 38.99361 / -104.5742084

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
4	1376 20745707	10.00	Slump: 1 1/2 Spec: - 2	Result: 6.8 Spec.: 5 - 8	137.2	90	90

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
4 / 16168	7	08/14/2025	4340	Type 2
4 / 16169	28	09/04/2025	5180	Type 3
4 / 16170	28	09/04/2025	4980	Type 5
4 / 16171	28	09/04/2025	5420	Type 2

Average Strength (psi): 7 Day - 4340 psi, 28 Day - 5190 psi

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 5 **Sample #:** 4832 **Placement Date:** 08/08/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** South end of lot 166 **Lat/Long:** 38.99234 / -104.57904

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
5	1368 20745979	10.00	Slump: 1 Spec: - 2	Result: 7.5 Spec.: 5 - 8	136.8	85	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
5 / 16172	7	08/15/2025	4060	Type 2
5 / 16173	28	09/05/2025	5640	Type 2
5 / 16174	28	09/05/2025	4760	Type 2
5 / 16175	28	09/05/2025	5120	Type 2

Average Strength (psi): 7 Day - 4060 psi, 28 Day - 5170 psi

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 6 **Sample #:** 4917 **Placement Date:** 08/15/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 63
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** West end of lot 113 heading East **Lat/Long:** 38.9942872 / -104.5745251

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
6	1368 20748005	10.00	Slump: 1 1/4 Spec: - 2	Result: 7 Spec.: 5 - 8	136.4	75	63

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
6 / 16348	7	08/22/2025	4240	Type 2

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 6 **Sample #:** 4917 **Placement Date:** 08/15/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 63
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** West end of lot 113 heading East **Lat/Long:** 38.9942872 / -104.5745251

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
6	1368 20748005	10.00	Slump: 1 1/4 Spec: - 2	Result: 7 Spec.: 5 - 8	136.4	75	63

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
6 / 16348	7	08/22/2025	4240	Type 2
6 / 16349	28	09/12/2025	5180	Type 3
6 / 16350	28	09/12/2025	4950	Type 2
6 / 16351	28	09/12/2025	5080	Type 2

Average Strength (psi): 7 Day - 4240 psi, 28 Day - 5070 psi

09/17/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 7 **Sample #:** 4927 **Placement Date:** 08/15/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 86
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** East end of lot 175 heading west **Lat/Long:** 38.9943667 / -104.574825

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
7	1376 20748202	10.00	Slump: 1/2 Spec: - 2	Result: 5.6 Spec.: 5 - 8	140.0	80	86

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
7 / 16308	7	08/22/2025	3790	Type 3

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 7 **Sample #:** 4927 **Placement Date:** 08/15/2025 **Technician:** Michael Crytser **Weather Conditions:** Sunny **Air Temp (°F):** 86
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** East end of lot 175 heading west **Lat/Long:** 38.9943667 / -104.574825

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
7	1376 20748202	10.00	Slump: 1/2 Spec: - 2	Result: 5.6 Spec.: 5 - 8	140.0	80	86

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
7 / 16308	7	08/22/2025	3790	Type 3
7 / 16309	28	09/12/2025	5230	Type 2
7 / 16310	28	09/12/2025	5420	Type 2
7 / 16311	28	09/12/2025	5120	Type 3

Average Strength (psi): 7 Day - 3790 psi, 28 Day - 5250 psi

09/17/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 8 **Sample #:** 4983 **Placement Date:** 08/21/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 63
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb & gutter at Lot 129

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
8	1376 20749675	10.00	Slump: 1 Spec: - 2	Result: 6 Spec.: 5 - 8	139.2	90	63

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
8 / 16637	7	08/28/2025	4380	Type 2

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 8 **Sample #:** 4983 **Placement Date:** 08/21/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 63
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb & gutter at Lot 129

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
8	1376 20749675	10.00	Slump: 1 Spec: - 2	Result: 6 Spec.: 5 - 8	139.2	90	63

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
8 / 16637	7	08/28/2025	4380	Type 2
8 / 16638	28	09/18/2025	6180	Type 3
8 / 16639	28	09/18/2025	5950	Type 2
8 / 16640	28	09/18/2025	6050	Type 2

Average Strength (psi): 7 Day - 4390 psi, 28 Day - 6060 psi

09/22/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 9 **Sample #:** 4991 **Placement Date:** 08/21/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 82
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb & gutter at lot 238

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
9	B1000 20749907	10.00	Slump: 1 Spec: - 2	Result: 5 Spec.: 5 - 8	140.7	82	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
9 / 16609	7	08/28/2025	4100	Type 2

09/08/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 9 **Sample #:** 4991 **Placement Date:** 08/21/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 82
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb & gutter at lot 238

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
9	B1000 20749907	10.00	Slump: 1 Spec: - 2	Result: 5 Spec.: 5 - 8	140.7	82	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
9 / 16609	7	08/28/2025	4100	Type 2
9 / 16610	28	09/18/2025	5250	Type 3
9 / 16611	28	09/18/2025	5350	Type 5
9 / 16612	28	09/18/2025	5260	Type 3

Average Strength (psi): 7 Day - 4100 psi, 28 Day - 5290 psi

09/22/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 10 **Sample #:** 5139 **Placement Date:** 09/09/2025 **Technician:** Matt Spring **Weather Conditions:** Sunny **Air Temp (°F):** 65
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Southeast corner of Sunrise Ridge Dr. and House Rock Dr. **Lat/Long:** 38.990135 / -104.5846333

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
10	1386 20754383	7.00	Slump: 3 1/2 Spec: 2 - 6	Result: 8 Spec.: 5 - 8	132.0	83	65

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
10 / 17088	7	09/16/2025	3080	Type 3

09/22/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 10 **Sample #:** 5139 **Placement Date:** 09/09/2025 **Technician:** Matt Spring **Weather Conditions:** Sunny **Air Temp (°F):** 65
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Southeast corner of Sunrise Ridge Dr. and House Rock Dr. **Lat/Long:** 38.990135 / -104.5846333

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
10	1386 20754383	7.00	Slump: 3 1/2 Spec: 2 - 6	Result: 8 Spec.: 5 - 8	132.0	83	65

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
10 / 17088	7	09/16/2025	3080	Type 3
10 / 17089	28	10/07/2025	4310	Type 2

Average Strength (psi): 7 Day - 3080 psi, 28 Day - 4310 psi

56 Day Breaks will be provided when available.

10/23/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 10 **Sample #:** 5139 **Placement Date:** 09/09/2025 **Technician:** Spring, Matt **Weather Conditions:** Sunny **Air Temp (°F):** 65
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Southeast corner of Sunrise Ridge Dr. and House Rock Dr. **Lat/Long:** 38.990135 / -104.5846333

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
10	1386 20754383	7.00	Slump: 3 1/2 Spec: 2 - 6	Result: 8 Spec.: 5 - 8	132.0	83	65

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
10 / 17088	7	09/16/2025	3080	Type 3
10 / 17089	28	10/07/2025	4310	Type 2
10 / 17090	56	11/04/2025	4720	Type 5
10 / 17091	56	11/04/2025	4550	Type 2

Average Strength (psi): 7 Day - 3080 psi, 28 Day - 4310 psi, 56 Day - 4640 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 11 **Sample #:** 5162 **Placement Date:** 09/10/2025 **Technician:** Matt Spring **Weather Conditions:** Sunny **Air Temp (°F):** 59

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Southeast corner of Crystal Falls drive and House Rock drive **Lat/Long:** 38.9931717 / -104.5757051

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
11	1384 20754832	10.00	Slump: 3 1/2 Spec: 2 - 6	Result: 7 Spec.: 5 - 8	135.6	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
11 / 17048	7	09/17/2025	3520	Type 3
11 / 17049	28	10/08/2025	4950	Type 2
11 / 17050	28	10/08/2025	4940	Type 2
11 / 17051	28	10/08/2025	4940	Type 5

Average Strength (psi): 7 Day - 3520 psi, 28 Day - 4940 psi

10/23/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 11 **Sample #:** 5162 **Placement Date:** 09/10/2025 **Technician:** Matt Spring **Weather Conditions:** Sunny **Air Temp (°F):** 59
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Southeast corner of Crystal Falls drive and House Rock drive **Lat/Long:** 38.9931717 / -104.5757051

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
11	1384 20754832	10.00	Slump: 3 1/2 Spec: 2 - 6	Result: 7 Spec.: 5 - 8	135.6	75	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
11 / 17048	7	09/17/2025	3520	Type 3

09/22/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 12 **Sample #:** 5183 **Placement Date:** 09/11/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Cloudy **Air Temp (°F):** 76
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb & gutter applied by machine at lot 85 **Lat/Long:** 38.9901943 / -104.5846579

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
12	1368 20755409	10.00	Slump: 1/2 Spec: - 2	Result: 6 Spec.: 5 - 8	137.8	71	76

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
12 / 17185	7	09/18/2025	3570	Type 3
12 / 17186	28	10/09/2025	4730	Type 2
12 / 17187	28	10/09/2025	4790	Type 3
12 / 17188	28	10/09/2025	4990	Type 2

Average Strength (psi): 7 Day - 3570 psi, 28 Day - 4830 psi

10/23/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 12 **Sample #:** 5183 **Placement Date:** 09/11/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Cloudy **Air Temp (°F):** 76
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb & gutter applied by machine at lot 85 **Lat/Long:** 38.9901943 / -104.5846579

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
12	1368 20755409	10.00	Slump: 1/2 Spec: - 2	Result: 6 Spec.: 5 - 8	137.8	71	76

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
12 / 17185	7	09/18/2025	3570	Type 3

09/22/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 13 **Sample #:** 5185 **Placement Date:** 09/10/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter

Location Details: Handset curb & gutter Northwest corner intersection south of Lot 85

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
13	1372 20755460	10.00	Slump: 5 Spec: 3 - 5	Result: 7 Spec.: 5 - 8	133.3	71	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
13 / 17189	7	09/17/2025	2460	Type 2
13 / 17158	28	10/08/2025	3550	Type 2

Average Strength (psi): 7 Day - 2460 psi, 28 Day - 3550 psi

56 Day Breaks will be provided when available.

10/23/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 13 **Sample #:** 5185 **Placement Date:** 09/10/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter

Location Details: Handset curb & gutter Northwest corner intersection south of Lot 85

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
13	1372 20755460	10.00	Slump: 5 Spec: 3 - 5	Result: 7 Spec.: 5 - 8	133.3	71	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
13 / 17189	7	09/17/2025	2460	Type 2

09/22/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 13 **Sample #:** 5185 **Placement Date:** 09/10/2025 **Technician:** Barnhart, Jayce **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter

Location Details: Handset curb & gutter Northwest corner intersection south of Lot 85

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
13	1372 20755460	10.00	Slump: 5 Spec: 3 - 5	Result: 7 Spec.: 5 - 8	133.3	71	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
13 / 17189	7	09/17/2025	2460	Type 2
13 / 17158	28	10/08/2025	3550	Type 2
13 / 17159	56	11/05/2025	4300	Type 2

Average Strength (psi): 7 Day - 2460 psi, 28 Day - 3550 psi, 56 Day - 4300 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 13 **Sample #:** 5185 **Placement Date:** 09/10/2025 **Technician:** Barnhart, Jayce **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Handset curb & gutter Northwest corner intersection south of Lot 85

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
13	1372 20755460	10.00	Slump: 5 Spec: 3 - 5	Result: 7 Spec.: 5 - 8	133.3	71	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
13 / 17189	7	09/17/2025	2460	Type 2
13 / 17158	28	10/08/2025	3550	Type 2
13 / 17159	56	11/05/2025	4300	Type 2
13 / 17160	90	12/09/2025	4390	Type 5

Average Strength (psi): 7 Day - 2460 psi, 28 Day - 3550 psi, 56 Day - 4300 psi, 90 Day - 4390 psi

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 14 **Sample #:** 5353 **Placement Date:** 09/24/2025 **Technician:** Kirby Hooker **Weather Conditions:** Cloudy **Air Temp (°F):** 56
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** 2 curb sections in front of storm inlets on Sunrise Ridge Dr. **Lat/Long:** 38.9937956 / -104.5761635

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
14	1376 20758795	6.00	Slump: 3 1/2 Spec: 2 - 6	Result: 7 Spec.: 5 - 8	136.4	79	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
14 / 17600	7	10/01/2025	3340	Type 3

10/03/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 14 **Sample #:** 5353 **Placement Date:** 09/24/2025 **Technician:** Kirby Hooker **Weather Conditions:** Cloudy **Air Temp (°F):** 56
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** 2 curb sections in front of storm inlets on Sunrise Ridge Dr. **Lat/Long:** 38.9937956 / -104.5761635

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
14	1376 20758795	6.00	Slump: 3 1/2 Spec: 2 - 6	Result: 7 Spec.: 5 - 8	136.4	79	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
14 / 17600	7	10/01/2025	3340	Type 3
14 / 17601	28	10/22/2025	4840	Type 3
14 / 17602	28	10/22/2025	5110	Type 2
14 / 17603	28	10/22/2025	4670	Type 2

Average Strength (psi): 7 Day - 3350 psi, 28 Day - 4870 psi

10/30/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 15 **Sample #:** 5369 **Placement Date:** 09/25/2025 **Technician:** Ben Westhues **Weather Conditions:** Sunny **Air Temp (°F):** 70

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** At the intersection of Sunrise Ridge Dr. and Shelter Creek Dr. In the Northwest corner of intersection. **Lat/Long:** 38.9957037 / -104.5722882

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
15	1373 20759025	6.00	Slump: 2 1/2 Spec: 2 - 4	Result: 6.5 Spec.: 5 - 8	137.2	73	70

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
15 / 17705	7	10/02/2025	3400	Type 3

10/10/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 15 **Sample #:** 5369 **Placement Date:** 09/25/2025 **Technician:** Ben Westhues **Weather Conditions:** Sunny **Air Temp (°F):** 70

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** At the intersection of Sunrise Ridge Dr. and Shelter Creek Dr. In the Northwest corner of intersection. **Lat/Long:** 38.9957037 / -104.5722882

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
15	1373 20759025	6.00	Slump: 2 1/2 Spec: 2 - 4	Result: 6.5 Spec.: 5 - 8	137.2	73	70

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
15 / 17705	7	10/02/2025	3400	Type 3
15 / 17706	28	10/23/2025	4420	Type 2

Average Strength (psi): 7 Day - 3400 psi, 28 Day - 4420 psi

56 Day Breaks will be provided when available.

10/30/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 15 **Sample #:** 5369 **Placement Date:** 09/25/2025 **Technician:** Westhues, Ben **Weather Conditions:** Sunny **Air Temp (°F):** 70

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** At the intersection of Sunrise Ridge Dr. and Shelter Creek Dr. In the Northwest corner of intersection. **Lat/Long:** 38.9957037 / -104.5722882

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
15	1373 20759025	6.00	Slump: 2 1/2 Spec: 2 - 4	Result: 6.5 Spec.: 5 - 8	137.2	73	70

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
15 / 17705	7	10/02/2025	3400	Type 3
15 / 17706	28	10/23/2025	4420	Type 2
15 / 17707	56	11/20/2025	5290	Type 3
15 / 17708	56	11/20/2025	5180	Type 3

Average Strength (psi): 7 Day - 3400 psi, 28 Day - 4420 psi, 56 Day - 5230 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 16 **Sample #:** 5391 **Placement Date:** 09/26/2025 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Crosspan **Location Details:** Shelter Creek Dr. and Crystal Falls Dr. **Lat/Long:** 38.993151 / -104.5755313

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
16	1387 20759395	8.00	Slump: 3 1/2 Spec: 3 - 6	Result: 8 Spec.: 5 - 8	134.4	78	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
16 / 17637	7	10/03/2025	2910	Type 5

10/10/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 16 **Sample #:** 5391 **Placement Date:** 09/26/2025 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Crosspan **Location Details:** Shelter Creek Dr. and Crystal Falls Dr. **Lat/Long:** 38.993151 / -104.5755313

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
16	1387 20759395	8.00	Slump: 3 1/2 Spec: 3 - 6	Result: 8 Spec.: 5 - 8	134.4	78	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
16 / 17637	7	10/03/2025	2910	Type 5
16 / 17638	28	10/24/2025	4360	Type 3

Average Strength (psi): 7 Day - 2910 psi, 28 Day - 4360 psi

56 Day Breaks will be provided when available.

10/30/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 16 **Sample #:** 5391 **Placement Date:** 09/26/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Crosspan **Location Details:** Shelter Creek Dr. and Crystal Falls Dr. **Lat/Long:** 38.993151 / -104.5755313

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
16	1387 20759395	8.00	Slump: 3 1/2 Spec: 3 - 6	Result: 8 Spec.: 5 - 8	134.4	78	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
16 / 17637	7	10/03/2025	2910	Type 5
16 / 17638	28	10/24/2025	4360	Type 3
16 / 17639	56	11/21/2025	5140	Type 3
16 / 17640	56	11/21/2025	5030	Type 3

Average Strength (psi): 7 Day - 2910 psi, 28 Day - 4360 psi, 56 Day - 5080 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 17 **Sample #:** 5416 **Placement Date:** 09/29/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 69

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Directly across the street from Lot 194 on Crystal Falls Drive.

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
17	1364 20759943	8.00	Slump: 4 1/2 Spec: 3 - 5	Result: 7 Spec.: 5 - 8	139.3	74	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
17 / 17801	7	10/06/2025	3690	Type 2

10/23/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 17 **Sample #:** 5416 **Placement Date:** 09/29/2025 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 69

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Directly across the street from Lot 194 on Crystal Falls Drive.

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
17	1364 20759943	8.00	Slump: 4 1/2 Spec: 3 - 5	Result: 7 Spec.: 5 - 8	139.3	74	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
17 / 17801	7	10/06/2025	3690	Type 2
17 / 17802	28	10/27/2025	4590	Type 2
17 / 17803	28	10/27/2025	4700	Type 2
17 / 17804	28	10/27/2025	4550	Type 2

Average Strength (psi): 7 Day - 3690 psi, 28 Day - 4610 psi

10/30/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 18 **Sample #:** 5442 **Placement Date:** 10/01/2025 **Technician:** Kirby Hooker **Weather Conditions:** Sunny **Air Temp (°F):** 68

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** At the northeast corner of Shelter Creek Drive and Rex Road. **Lat/Long:** 38.9925893 / -104.5723245

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
18	1372 20760680	7.00	Slump: 5 1/2 Spec: 3 - 5	Result: 6.8 Spec.: 5 - 8	136.0	82	68

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
18 / 17891	7	10/08/2025	3430	Type 5

Average Strength (psi): 7 Day - 3430 psi

10/23/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 18 **Sample #:** 5442 **Placement Date:** 10/01/2025 **Technician:** Hooker, Kirby **Weather Conditions:** Sunny **Air Temp (°F):** 68

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** At the northeast corner of Shelter Creek Drive and Rex Road. **Lat/Long:** 38.9925893 / -104.5723245

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
18	1372 20760680	7.00	Slump: 5 1/2 Spec: 3 - 5	Result: 6.8 Spec.: 5 - 8	136.0	82	68

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
18 / 17891	7	10/08/2025	3430	Type 5
18 / 17892	28	10/29/2025	4790	Type 2
18 / 17893	28	10/29/2025	4480	Type 5
18 / 17894	56	11/26/2025	5420	Type 5

Average Strength (psi): 7 Day - 3430 psi, 28 Day - 4630 psi, 56 Day - 5420 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 19 **Sample #:** 5718 **Placement Date:** 10/22/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 41
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 64 + 75, North sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9937047 / -104.576746

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
19	1373 20767035	10.00	Slump: 1 Spec: 1 - 3	Result: 5.2 Spec.: 5 - 8	142.0	70	41

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
19 / 18785	7	10/29/2025	4760	Type 3
19 / 18786	28	11/19/2025	7000	Type 5
19 / 18787	28	11/19/2025	6800	Type 3
19 / 18788	28	11/19/2025	7060	Type 2

Average Strength (psi): 7 Day - 4760 psi, 28 Day - 6950 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 20 **Sample #:** 5735 **Placement Date:** 10/22/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 63
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 75 + 40, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9948352 / -104.5732321

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
20	1373 20767278	10.00	Slump: 1 1/2 Spec: 1 - 4	Result: 6.6 Spec.: 5 - 8	139.2	78	63

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
20 / 18793	7	10/29/2025	4490	Type 6
20 / 18794	28	11/19/2025	6270	Type 3
20 / 18795	28	11/19/2025	5730	Type 2
20 / 18796	28	11/19/2025	5540	Type 5

Average Strength (psi): 7 Day - 4500 psi, 28 Day - 5850 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 21 **Sample #:** 5738 **Placement Date:** 10/23/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 43
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 78 + 50, South sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9947055 / -104.5724975

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
21	1385 20767447	10.00	Slump: 1 Spec: 1 - 4	Result: 6.1 Spec.: 5 - 8	140.4	71	43

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
21 / 18801	7	10/30/2025	5260	Type 5
21 / 18802	28	11/20/2025	6060	Type 2
21 / 18803	28	11/20/2025	5880	Type 5
21 / 18804	28	11/20/2025	5890	Type 3

Average Strength (psi): 7 Day - 5260 psi, 28 Day - 5950 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 22 **Sample #:** 5779 **Placement Date:** 10/27/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 46
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 13+50 along Crystal Falls Drive. **Lat/Long:** 38.9934518 / -104.5745761

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
22	1385 20768333	10.00	Slump: 1 1/2 Spec: 1/2 - 2 1/2	Result: 6.6 Spec.: 5 - 8	139.2	62	46

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
22 / 18926	7	11/03/2025	5290	Type 2
22 / 18927	28	11/24/2025	6250	Type 2
22 / 18928	28	11/24/2025	5770	Type 5
22 / 18929	28	11/24/2025	5980	Type 3

Average Strength (psi): 7 Day - 5290 psi, 28 Day - 6000 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 23 **Sample #:** 5825 **Placement Date:** 10/29/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 48
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 10+50 along Cardenas Drive. **Lat/Long:** 38.9941882 / -104.575412

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
23	1373 20769305	10.00	Slump: 4 Spec: 4 - 6	Result: 6.8 Spec.: 5 - 8	138.8	70	48

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
23 / 19060	7	11/05/2025	4550	Type 2
23 / 19061	28	11/26/2025	6280	Type 5
23 / 19062	28	11/26/2025	6180	Type 2
23 / 19063	28	11/26/2025	6090	Type 2

Average Strength (psi): 7 Day - 4550 psi, 28 Day - 6180 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 24 **Sample #:** 5860 **Placement Date:** 10/31/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Cloudy **Air Temp (°F):** 39
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 71+50 along Sunrise Ridge Drive. **Lat/Long:** 38.9941277 / -104.5752741

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
24	1376 20769868	10.00	Slump: 5 1/2 Spec: 4 - 6	Result: 5.6 Spec.: 5 - 8	142.4	61	39

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
24 / 19112	7	11/07/2025	6120	Type 2

Average Strength (psi): 7 Day - 6120 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 24 **Sample #:** 5860 **Placement Date:** 10/31/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Cloudy **Air Temp (°F):** 39
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 71+50 along Sunrise Ridge Drive. **Lat/Long:** 38.9941277 / -104.5752741

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
24	1376 20769868	10.00	Slump: 5 1/2 Spec: 4 - 6	Result: 5.6 Spec.: 5 - 8	142.4	61	39

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
24 / 19112	7	11/07/2025	6120	Type 2
24 / 19113	28	11/28/2025	7390	Type 2
24 / 19114	28	11/28/2025	7870	Type 2
24 / 19115	28	11/28/2025	7160	Type 2

Average Strength (psi): 7 Day - 6120 psi, 28 Day - 7470 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 25 **Sample #:** 5894 **Placement Date:** 11/04/2025 **Technician:** Crytser, Michael **Weather Conditions:** Sunny **Air Temp (°F):** 57
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Between the lot line of Lot 218 and Lot 219. **Lat/Long:** 38.9932765 / -104.5753689

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
25	1382 20770663	10.00	Slump: 1 Spec: 1/2 - 2 1/2	Result: 7 Spec.: 5 - 8	138.8	75	57

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
25 / 19264	7	11/11/2025	4160	Type 2

Average Strength (psi): 7 Day - 4160 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 25 **Sample #:** 5894 **Placement Date:** 11/04/2025 **Technician:** Crytser, Michael **Weather Conditions:** Sunny **Air Temp (°F):** 57
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Between the lot line of Lot 218 and Lot 219. **Lat/Long:** 38.9932765 / -104.5753689

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
25	1382 20770663	10.00	Slump: 1 Spec: 1/2 - 2 1/2	Result: 7 Spec.: 5 - 8	138.8	75	57

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
25 / 19264	7	11/11/2025	4160	Type 2
25 / 19265	28	12/02/2025	5670	Type 2
25 / 19266	28	12/02/2025	5930	Type 3
25 / 19267	28	12/02/2025	5620	Type 2

Average Strength (psi): 7 Day - 4160 psi, 28 Day - 5740 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 26 **Sample #:** 5902 **Placement Date:** 11/04/2025 **Technician:** Crytser, Michael **Weather Conditions:** Sunny **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At the lot line between Lot 232 and Lot 233. **Lat/Long:** 38.9926852 / -104.5739346

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
26	1385 20770862	10.00	Slump: 1 1/4 Spec: 1/2 - 2 1/2	Result: 6.8 Spec.: 5 - 8	138.8	75	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
26 / 19292	7	11/11/2025	3980	Type 3

Average Strength (psi): 7 Day - 3980 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 26 **Sample #:** 5902 **Placement Date:** 11/04/2025 **Technician:** Crytser, Michael **Weather Conditions:** Sunny **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At the lot line between Lot 232 and Lot 233. **Lat/Long:** 38.9926852 / -104.5739346

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
26	1385 20770862	10.00	Slump: 1 1/4 Spec: 1/2 - 2 1/2	Result: 6.8 Spec.: 5 - 8	138.8	75	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
26 / 19292	7	11/11/2025	3980	Type 3
26 / 19293	28	12/02/2025	5460	Type 3
26 / 19294	28	12/02/2025	5230	Type 2
26 / 19295	28	12/02/2025	5540	Type 3

Average Strength (psi): 7 Day - 3980 psi, 28 Day - 5410 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 27 **Sample #:** 5916 **Placement Date:** 11/05/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 49
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 23+30 along House Rock Drive. **Lat/Long:** 38.9931419 / -104.5729141

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
27	1364 20771055	10.00	Slump: 1 1/2 Spec: 1/2 - 2 1/2	Result: 7.8 Spec.: 5 - 8	136.0	73	49

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
27 / 19328	7	11/12/2025	4140	Type 2

Average Strength (psi): 7 Day - 4140 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 27 **Sample #:** 5916 **Placement Date:** 11/05/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 49
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 23+30 along House Rock Drive. **Lat/Long:** 38.9931419 / -104.5729141

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
27	1364 20771055	10.00	Slump: 1 1/2 Spec: 1/2 - 2 1/2	Result: 7.8 Spec.: 5 - 8	136.0	73	49

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
27 / 19328	7	11/12/2025	4140	Type 2
27 / 19329	28	12/03/2025	5040	Type 3
27 / 19330	28	12/03/2025	5070	Type 2
27 / 19331	28	12/03/2025	5000	Type 3

Average Strength (psi): 7 Day - 4140 psi, 28 Day - 5030 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 28 **Sample #:** 5923 **Placement Date:** 11/05/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 56
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 22+10 along House Rock Drive. **Lat/Long:** 38.9929124 / -104.5732437

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
28	1384 20771229	10.00	Slump: 1 Spec: 1/2 - 2 1/2	Result: 6.2 Spec.: 5 - 8	141.2	71	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
28 / 19344	7	11/12/2025	4460	Type 3

Average Strength (psi): 7 Day - 4460 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 28 **Sample #:** 5923 **Placement Date:** 11/05/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 56
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 22+10 along House Rock Drive. **Lat/Long:** 38.9929124 / -104.5732437

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
28	1384 20771229	10.00	Slump: 1 Spec: 1/2 - 2 1/2	Result: 6.2 Spec.: 5 - 8	141.2	71	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
28 / 19344	7	11/12/2025	4460	Type 3
28 / 19345	28	12/03/2025	6400	Type 2
28 / 19346	28	12/03/2025	6140	Type 3
28 / 19347	28	12/03/2025	6010	Type 5

Average Strength (psi): 7 Day - 4460 psi, 28 Day - 6180 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 29 **Sample #:** 5981 **Placement Date:** 11/10/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 54
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 16+10 along House Rock Drive. **Lat/Long:** 38.9922759 / -104.5752339

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
29	1387 o 20772358	10.00	Slump: 1 1/2 Spec: 1/2 - 2 1/2	Result: 7.3 Spec.: 5 - 8	138.4	71	54

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
29 / 19523	7	11/17/2025	4510	Type 3

Average Strength (psi): 7 Day - 4510 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 29 **Sample #:** 5981 **Placement Date:** 11/10/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 54
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 16+10 along House Rock Drive. **Lat/Long:** 38.9922759 / -104.5752339

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
29	1387 o 20772358	10.00	Slump: 1 1/2 Spec: 1/2 - 2 1/2	Result: 7.3 Spec.: 5 - 8	138.4	71	54

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
29 / 19523	7	11/17/2025	4510	Type 3
29 / 19524	28	12/08/2025	4880	Type 5
29 / 19525	28	12/08/2025	5390	Type 2
29 / 19526	28	12/08/2025	5290	Type 3

Average Strength (psi): 7 Day - 4510 psi, 28 Day - 5190 psi

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 31 **Sample #:** 6077 **Placement Date:** 11/14/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 27+00 Along Shelter Creek Drive. **Lat/Long:** 38.992989 / -104.5724344

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
31	1385 207773982	10.00	Slump: 7 Spec: 4 - 6	Result: 6.8 Spec.: 5 - 8	138.4	69	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
31 / 19635	7	11/21/2025	3160	Type 3

Average Strength (psi): 7 Day - 3170 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 31 **Sample #:** 6077 **Placement Date:** 11/14/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 27+00 Along Shelter Creek Drive. **Lat/Long:** 38.992989 / -104.5724344

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
31	1385 207773982	10.00	Slump: 7 Spec: 4 - 6	Result: 6.8 Spec.: 5 - 8	138.4	69	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
31 / 19635	7	11/21/2025	3160	Type 3
31 / 19636	28	12/12/2025	4060	Type 2

Average Strength (psi): 7 Day - 3170 psi, 28 Day - 4060 psi

56 Day Breaks will be provided when available.

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 31 **Sample #:** 6077 **Placement Date:** 11/14/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 27+00 Along Shelter Creek Drive. **Lat/Long:** 38.992989 / -104.5724344

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
31	1385 207773982	10.00	Slump: 7 Spec: 4 - 6	Result: 6.8 Spec.: 5 - 8	138.4	69	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
31 / 19635	7	11/21/2025	3160	Type 3
31 / 19636	28	12/12/2025	4060	Type 2
31 / 19637	56	01/09/2026	4870	Type 2
31 / 19638	56	01/09/2026	4630	Type 2

Average Strength (psi): 7 Day - 3170 psi, 28 Day - 4060 psi, 56 Day - 4750 psi

01/19/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 32 **Sample #:** 6088 **Placement Date:** 11/17/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 46
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 11+40 along House Rock Drive. **Lat/Long:** 38.9937347 / -104.5758971

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
32	1372 20774294	10.00	Slump: 5 1/2 Spec: 4 - 6	Result: 5.5 Spec.: 5 - 8	139.6	65	46

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
32 / 19879	7	11/24/2025	3910	Type 3

Average Strength (psi): 7 Day - 3910 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 32 **Sample #:** 6088 **Placement Date:** 11/17/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 46
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 11+40 along House Rock Drive. **Lat/Long:** 38.9937347 / -104.5758971

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
32	1372 20774294	10.00	Slump: 5 1/2 Spec: 4 - 6	Result: 5.5 Spec.: 5 - 8	139.6	65	46

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
32 / 19879	7	11/24/2025	3910	Type 3
32 / 19880	28	12/15/2025	5440	Type 2
32 / 19881	28	12/15/2025	4840	Type 2
32 / 19882	28	12/15/2025	5080	Type 2

Average Strength (psi): 7 Day - 3910 psi, 28 Day - 5120 psi

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 33 **Sample #:** 6109 **Placement Date:** 11/18/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 40
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 33+45 Along Shelter Creek Drive. **Lat/Long:** 38.9946687 / -104.5721914

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
33	1359 20774658	10.00	Slump: 4 1/2 Spec: 4 - 6	Result: 6.4 Spec.: 5 - 8	139.6	61	40

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
33 / 19930	7	11/25/2025	3570	Type 2

Average Strength (psi): 7 Day - 3570 psi

11/28/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 33 **Sample #:** 6109 **Placement Date:** 11/18/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 40
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 33+45 Along Shelter Creek Drive. **Lat/Long:** 38.9946687 / -104.5721914

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
33	1359 20774658	10.00	Slump: 4 1/2 Spec: 4 - 6	Result: 6.4 Spec.: 5 - 8	139.6	61	40

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
33 / 19930	7	11/25/2025	3570	Type 2
33 / 19931	28	12/16/2025	4550	Type 2
33 / 19932	28	12/16/2025	4550	Type 5
33 / 19933	28	12/16/2025	4680	Type 3

Average Strength (psi): 7 Day - 3570 psi, 28 Day - 4590 psi

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 34 **Sample #:** 6128 **Placement Date:** 11/19/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 47
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 26 + 05 along Shelter Creek Drive. **Lat/Long:** 38.9932254 / -104.572552

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
34	1477 20775039	10.00	Slump: 6 Spec: 4 - 6	Result: 6.2 Spec.: 5 - 8	140.0	66	47

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
34 / 19951	7	11/26/2025	3650	Type 2

Average Strength (psi): 7 Day - 3650 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 34 **Sample #:** 6128 **Placement Date:** 11/19/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 47
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 26 + 05 along Shelter Creek Drive. **Lat/Long:** 38.9932254 / -104.572552

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
34	1477 20775039	10.00	Slump: 6 Spec: 4 - 6	Result: 6.2 Spec.: 5 - 8	140.0	66	47

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
34 / 19951	7	11/26/2025	3650	Type 2
34 / 19952	28	12/17/2025	4760	Type 5
34 / 19953	28	12/17/2025	5200	Type 5
34 / 19954	28	12/17/2025	5140	Type 2

Average Strength (psi): 7 Day - 3650 psi, 28 Day - 5030 psi

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 35 **Sample #:** 6149 **Placement Date:** 11/20/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Cloudy **Air Temp (°F):** 43
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 34 + 10 along Shelter Creek Drive. **Lat/Long:** 38.9948708 / -104.5721103

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
35	1384 20775494	10.00	Slump: 4 1/2 Spec: 4 - 6	Result: 5.2 Spec.: 5 - 8	142.0	66	43

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
35 / 20082	7	11/27/2025	4300	Type 2

Average Strength (psi): 8 Day - 4300 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 35 **Sample #:** 6149 **Placement Date:** 11/20/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Cloudy **Air Temp (°F):** 43
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 34 + 10 along Shelter Creek Drive. **Lat/Long:** 38.9948708 / -104.5721103

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
35	1384 20775494	10.00	Slump: 4 1/2 Spec: 4 - 6	Result: 5.2 Spec.: 5 - 8	142.0	66	43

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
35 / 20082	7	11/27/2025	4300	Type 2
35 / 20083	28	12/18/2025	5720	Type 3
35 / 20084	28	12/18/2025	5480	Type 3
35 / 20085	28	12/18/2025	5830	Type 3

Average Strength (psi): 7 Day - 4300 psi, 28 Day - 5680 psi

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 36 **Sample #:** 6187 **Placement Date:** 11/24/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 42
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 19 + 00 along House Rock Drive. **Lat/Long:** 38.9925554 / -104.5742601

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
36	1366 20776172	10.00	Slump: 4 1/4 Spec: 4 - 6	Result: 5.5 Spec.: 5 - 8	140.4	61	42

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
36 / 20124	7	12/01/2025	4070	Type 3

Average Strength (psi): 7 Day - 4070 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 36 **Sample #:** 6187 **Placement Date:** 11/24/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Sunny **Air Temp (°F):** 42
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 19 + 00 along House Rock Drive. **Lat/Long:** 38.9925554 / -104.5742601

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
36	1366 20776172	10.00	Slump: 4 1/4 Spec: 4 - 6	Result: 5.5 Spec.: 5 - 8	140.4	61	42

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
36 / 20124	7	12/01/2025	4070	Type 3
36 / 20125	28	12/22/2025	5380	Type 2
36 / 20126	28	12/22/2025	5130	Type 2
36 / 20127	28	12/22/2025	5500	Type 3

Average Strength (psi): 7 Day - 4070 psi, 28 Day - 5340 psi

01/05/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 37 **Sample #:** 6198 **Placement Date:** 11/25/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Cloudy **Air Temp (°F):** 32
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 13+15 along Crystal Falls Drive. **Lat/Long:** 38.9933894 / -104.5745418

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
37	1197 20776492	10.00	Slump: 3 1/2 Spec: 4 - 6	Result: 6.4 Spec.: 5 - 8	139.2	66	32

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
37 / 20160	7	12/02/2025	3670	Type 3

Average Strength (psi): 7 Day - 3670 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 37 **Sample #:** 6198 **Placement Date:** 11/25/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Cloudy **Air Temp (°F):** 32
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 13+15 along Crystal Falls Drive. **Lat/Long:** 38.9933894 / -104.5745418

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
37	1197 20776492	10.00	Slump: 3 1/2 Spec: 4 - 6	Result: 6.4 Spec.: 5 - 8	139.2	66	32

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
37 / 20160	7	12/02/2025	3670	Type 3
37 / 20161	28	12/23/2025	5200	Type 5
37 / 20162	28	12/23/2025	5210	Type 2
37 / 20163	28	12/23/2025	5160	Type 5

Average Strength (psi): 7 Day - 3670 psi, 28 Day - 5190 psi

01/05/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 38 **Sample #:** 6222 **Placement Date:** 11/26/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 42
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 67+70 along Sunrise Ridge Drive. **Lat/Long:** 38.9939586 / -104.5760706

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
38	B1000 20776906	10.00	Slump: 4 1/4 Spec: 4 - 6	Result: 5.8 Spec.: 5 - 8	138.8	67	42

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
38 / 20209	7	12/03/2025	3660	Type 3

Average Strength (psi): 7 Day - 3660 psi

12/15/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 38 **Sample #:** 6222 **Placement Date:** 11/26/2025 **Technician:** Fannin, Rodney **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 42
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** At Station 67+70 along Sunrise Ridge Drive. **Lat/Long:** 38.9939586 / -104.5760706

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
38	B1000 20776906	10.00	Slump: 4 1/4 Spec: 4 - 6	Result: 5.8 Spec.: 5 - 8	138.8	67	42

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
38 / 20209	7	12/03/2025	3660	Type 3
38 / 20210	28	12/24/2025	5920	Type 3
38 / 20211	28	12/24/2025	5330	Type 5
38 / 20212	28	12/24/2025	4960	Type 3

Average Strength (psi): 7 Day - 3660 psi, 28 Day - 5400 psi

01/05/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 39 **Sample #:** 6244 **Placement Date:** 12/02/2025 **Technician:** Anderson, Paul **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 48
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Sidewalk in Southeast corner of intersection of Crystal Fls Dr. and House Rock Dr. **Lat/Long:** 38.9931088 / -104.5754306

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
39	1373 20777395	10.00	Slump: 3 Spec: 3 - 7	Result: 5 Spec.: 5 - 8	141.2	78	48

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
39 / 20292	7	12/09/2025	4560	Type 2

Average Strength (psi): 7 Day - 4560 psi

12/21/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 39 **Sample #:** 6244 **Placement Date:** 12/02/2025 **Technician:** Paul, Anderson **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 48
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Sidewalk in Southeast corner of intersection of Crystal Fls Dr. and House Rock Dr. **Lat/Long:** 38.9931088 / -104.5754306

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
39	1373 20777395	10.00	Slump: 3 Spec: 3 - 7	Result: 5 Spec.: 5 - 8	141.2	78	48

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
39 / 20292	7	12/09/2025	4560	Type 2
39 / 20293	28	12/30/2025	6160	Type 2
39 / 20294	28	12/30/2025	6400	Type 3
39 / 20295	28	12/30/2025	6140	Type 3

Average Strength (psi): 7 Day - 4560 psi, 28 Day - 6230 psi

01/19/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 40 **Sample #:** 6285 **Placement Date:** 12/09/2025 **Technician:** Rutrough, Ryan **Weather Conditions:** Cloudy **Air Temp (°F):** 47
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Sidewalk-East Side of Galaros Dr STA 5+35

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
40	1362 20778187	10.00	Slump: 4 Spec: 4 - 8	Result: 7.8 Spec.: 5 - 8	134.3	68	47

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
40 / 20419	7	12/16/2025	3380	Type 5

Average Strength (psi): 7 Day - 3380 psi

12/31/2025

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 40 **Sample #:** 6285 **Placement Date:** 12/09/2025 **Technician:** Ryan, Rutrough **Weather Conditions:** Cloudy **Air Temp (°F):** 47
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Sidewalk-East Side of Galaros Dr STA 5+35

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
40	1362 20778187	10.00	Slump: 4 Spec: 4 - 8	Result: 7.8 Spec.: 5 - 8	134.3	68	47

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
40 / 20419	7	12/16/2025	3380	Type 5
40 / 20420	28	01/06/2026	4320	Type 3

Average Strength (psi): 7 Day - 3380 psi, 28 Day - 4320 psi

56 Day Breaks will be provided when available.

01/19/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 40 **Sample #:** 6285 **Placement Date:** 12/09/2025 **Technician:** Ryan Rutrough **Weather Conditions:** Cloudy **Air Temp (°F):** 47
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Sidewalk-East Side of Galaros Dr STA 5+35

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
40	1362 20778187	10.00	Slump: 4 Spec: 4 - 8	Result: 7.8 Spec.: 5 - 8	134.3	68	47

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
40 / 20419	7	12/16/2025	3380	Type 5
40 / 20420	28	01/06/2026	4320	Type 3
40 / 20421	56	02/03/2026	5440	Type 3
40 / 20422	56	02/03/2026	5530	Type 3

Average Strength (psi): 7 Day - 3380 psi, 28 Day - 4320 psi, 56 Day - 5490 psi

02/18/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 41 **Sample #:** 7612 **Placement Date:** 04/10/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 45
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** At Station 65+35 along Sunrise Ridge Drive. **Lat/Long:** 38.9936372 / -104.5767702

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
41	2106 R14050056	10.00	Slump: 1 1/4 Spec: 1/2 - 2 1/2	Result: 6.8 Spec.: 5 - 8	142.0	77	45

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
41 / 25262	7	04/17/2026	5260	Type 3

Average Strength (psi): 7 Day - 5260 psi

04/29/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 41 **Sample #:** 7612 **Placement Date:** 04/10/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 45
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** At Station 65+35 along Sunrise Ridge Drive. **Lat/Long:** 38.9936372 / -104.5767702

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
41	2106 R14050056	10.00	Slump: 1 1/4 Spec: 1/2 - 2 1/2	Result: 6.8 Spec.: 5 - 8	142.0	77	45

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
41 / 25262	7	04/17/2026	5260	Type 3
41 / 25263	28	05/08/2026	5630	Type 3
41 / 25264	28	05/08/2026	6250	Type 2
41 / 25265	28	05/08/2026	6420	Type 3

Average Strength (psi): 7 Day - 5260 psi, 28 Day - 6100 psi

05/18/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 42 **Sample #:** 7622 **Placement Date:** 04/10/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 50
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** At Station 53+25 along Sunrise Ridge Drive. **Lat/Long:** 38.9941233 / -104.5810021

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
42	2033 R14050075	10.00	Slump: 2 Spec: 1/2 - 2 1/2	Result: 6.2 Spec.: 5 - 8	142.8	65	50

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
42 / 25260	7	04/17/2026	5080	Type 3

Average Strength (psi): 7 Day - 5080 psi

04/29/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 42 **Sample #:** 7622 **Placement Date:** 04/10/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 50
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** At Station 53+25 along Sunrise Ridge Drive. **Lat/Long:** 38.9941233 / -104.5810021

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
42	2033 R14050075	10.00	Slump: 2 Spec: 1/2 - 2 1/2	Result: 6.2 Spec.: 5 - 8	142.8	65	50

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
42 / 25260	7	04/17/2026	5080	Type 3
42 / 25261	28	05/08/2026	5550	Type 6
42 / 25267	28	05/08/2026	5970	Type 3
42 / 25268	28	05/08/2026	6120	Type 3

Average Strength (psi): 7 Day - 5080 psi, 28 Day - 5880 psi

05/18/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 43 **Sample #:** 7646 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 46
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45070-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on STA 51+75, for the south curb on Sunrise Ridge Dr. **Lat/Long:** 38.994143 / -104.5816083

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
43	2106 R14050207	10.00	Slump: 4 1/4 Spec: 3 - 6	Result: 7.5 Spec.: 5 - 8	141.2	60	46

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
43 / 25342	7	04/21/2026	4380	Type 2

Average Strength (psi): 7 Day - 4380 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 43 **Sample #:** 7646 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 46

Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45070-4 **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on STA 51+75, for the south curb on Sunrise Ridge Dr. **Lat/Long:** 38.994143 / -104.5816083

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
43	2106 R14050207	10.00	Slump: 4 1/4 Spec: 3 - 6	Result: 7.5 Spec.: 5 - 8	141.2	60	46

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
43 / 25342	7	04/21/2026	4380	Type 2
43 / 25343	28	05/12/2026	5500	Type 5
43 / 25344	28	05/12/2026	5460	Type 5
43 / 25345	28	05/12/2026	5380	Type 2

Average Strength (psi): 7 Day - 4380 psi, 28 Day - 5450 psi

05/18/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 44 **Sample #:** 7648 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 47
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the West side of Galeros Dr., located at STA 27+35 **Lat/Long:** 38.9924448 / -104.577534

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
44	4026 R14050209	10.00	Slump: 1 3/4 Spec: - 3	Result: 5.2 Spec.: 5 - 8	143.6	60	47

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
44 / 25347	7	04/21/2026	4540	Type 3

Average Strength (psi): 7 Day - 4540 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 44 **Sample #:** 7648 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 47
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the West side of Galeros Dr., located at STA 27+35 **Lat/Long:** 38.9924448 / -104.577534

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
44	4026 R14050209	10.00	Slump: 1 3/4 Spec: - 3	Result: 5.2 Spec.: 5 - 8	143.6	60	47

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
44 / 25347	7	04/21/2026	4540	Type 3
44 / 25348	28	05/12/2026	5470	Type 5
44 / 25349	28	05/12/2026	5480	Type 2
44 / 25350	28	05/12/2026	6010	Type 3

Average Strength (psi): 7 Day - 4540 psi, 28 Day - 5660 psi

05/18/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 45 **Sample #:** 7659 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 54
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the East side of Galeros Dr., located at STA 28+40 **Lat/Long:** 38.9927654 / -104.5773529

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
45	2034 R14050223	10.00	Slump: 1 3/4 Spec: - 3	Result: 5.1 Spec.: 5 - 8	151.6	64	54

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
45 / 25368	7	04/21/2026	4350	Type 3

Average Strength (psi): 7 Day - 4350 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 45 **Sample #:** 7659 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 54

Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the East side of Galeros Dr., located at STA 28+40 **Lat/Long:** 38.9927654 / -104.5773529

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
45	2034 R14050223	10.00	Slump: 1 3/4 Spec: - 3	Result: 5.1 Spec.: 5 - 8	151.6	64	54

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
45 / 25368	7	04/21/2026	4350	Type 3
45 / 25369	28	05/12/2026	5200	Type 3
45 / 25370	28	05/12/2026	5140	Type 3
45 / 25371	28	05/12/2026	5270	Type 2

Average Strength (psi): 7 Day - 4350 psi, 28 Day - 5200 psi

05/18/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 46 **Sample #:** 7662 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 56
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the North side of Horn Hill Dr., located at STA 17+35 **Lat/Long:** 38.9926791 / -104.5808164

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
46	4029 T14050243	10.00	Slump: 2 1/4 Spec: - 3	Result: 5.5 Spec.: 5 - 8	143.6	66	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
46 / 25380	7	04/21/2026	4400	Type 2

Average Strength (psi): 7 Day - 4400 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 46 **Sample #:** 7662 **Placement Date:** 04/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 56
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the North side of Horn Hill Dr., located at STA 17+35 **Lat/Long:** 38.9926791 / -104.5808164

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
46	4029 T14050243	10.00	Slump: 2 1/4 Spec: - 3	Result: 5.5 Spec.: 5 - 8	143.6	66	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
46 / 25380	7	04/21/2026	4400	Type 2
46 / 25381	28	05/12/2026	5050	Type 2
46 / 25382	28	05/12/2026	5550	Type 3
46 / 25383	28	05/12/2026	5550	Type 3

Average Strength (psi): 7 Day - 4400 psi, 28 Day - 5380 psi

05/18/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 49 **Sample #:** 7695 **Placement Date:** 04/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 56

Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Curb and Gutter at STA 14+50, on the East curb of Bright Angel Dr. **Lat/Long:** 38.9936976 / -104.5793338

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
49	1766 14050300	10.00	Slump: 1 1/2 Spec: - 3	Result: 7 Spec.: 5 - 8	145.6	61	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
49 / 25537	7	04/23/2026	4570	Type 2

Average Strength (psi): 7 Day - 4570 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 49 **Sample #:** 7695 **Placement Date:** 04/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 56

Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Curb and Gutter at STA 14+50, on the East curb of Bright Angel Dr. **Lat/Long:** 38.9936976 / -104.5793338

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
49	1766 14050300	10.00	Slump: 1 1/2 Spec: - 3	Result: 7 Spec.: 5 - 8	145.6	61	56

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
49 / 25537	7	04/23/2026	4570	Type 2
49 / 25538	28	05/14/2026	5100	Type 3
49 / 25539	28	05/14/2026	5360	Type 3
49 / 25540	28	05/14/2026	5560	Type 2

Average Strength (psi): 7 Day - 4570 psi, 28 Day - 5340 psi

05/22/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 50 **Sample #:** 7703 **Placement Date:** 04/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 59
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45878-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the East side of Bright Angel Dr., at STA 14+78 **Lat/Long:** 38.9937737 / -104.5793786

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
50	4109 R14050312	8.00	Slump: 2 3/4 Spec: 3 - 6	Result: 5.8 Spec.: 5 - 8	143.2	62	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
50 / 25547	7	04/23/2026	5060	Type 3

Average Strength (psi): 7 Day - 5060 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 50 **Sample #:** 7703 **Placement Date:** 04/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 59

Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45878-4 **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the East side of Bright Angel Dr., at STA 14+78 **Lat/Long:** 38.9937737 / -104.5793786

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
50	4109 R14050312	8.00	Slump: 2 3/4 Spec: 3 - 6	Result: 5.8 Spec.: 5 - 8	143.2	62	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
50 / 25547	7	04/23/2026	5060	Type 3
50 / 25548	28	05/14/2026	5800	Type 3
50 / 25549	28	05/14/2026	5990	Type 2
50 / 25550	28	05/14/2026	6390	Type 2

Average Strength (psi): 7 Day - 5060 psi, 28 Day - 6060 psi

05/22/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 51 **Sample #:** 7709 **Placement Date:** 04/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 64
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the West side of Temple Butte Dr., located at STA 14+00 **Lat/Long:** 38.993704 / -104.5804881

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
51	17005 R14050322	10.00	Slump: 2 Spec: - 3	Result: 6.5 Spec.: 5 - 8	141.2	66	64

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
51 / 25493	7	04/23/2026	4130	Type 3

Average Strength (psi): 7 Day - 4130 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 51 **Sample #:** 7709 **Placement Date:** 04/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 64
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45879-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the West side of Temple Butte Dr., located at STA 14+00 **Lat/Long:** 38.993704 / -104.5804881

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
51	17005 R14050322	10.00	Slump: 2 Spec: - 3	Result: 6.5 Spec.: 5 - 8	141.2	66	64

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
51 / 25493	7	04/23/2026	4130	Type 3
51 / 25494	28	05/14/2026	4840	Type 3
51 / 25495	28	05/14/2026	4900	Type 6
51 / 25496	28	05/14/2026	4920	Type 5

Average Strength (psi): 7 Day - 4130 psi, 28 Day - 4890 psi

05/22/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 52 **Sample #:** 7720 **Placement Date:** 04/20/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 59
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45878-4 **Specified Strength (psi):** 4500
Placement Location: Crosspan **Location Details:** North Crosspan for Sunrise Ridge Dr. and Tapeats Dr. **Lat/Long:** 38.9924652 / -104.5786224

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
52	4025 R14050402	10.00	Slump: 5 1/2 Spec: 4 - 6	Result: 6.6 Spec.: 5 - 8	140.8	67	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
52 / 25601	7	04/27/2026	4520	Type 5

Average Strength (psi): 7 Day - 4520 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 52 **Sample #:** 7720 **Placement Date:** 04/20/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 59
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45878-4 **Specified Strength (psi):** 4500
Placement Location: Crosspan **Location Details:** North Crosspan for Sunrise Ridge Dr. and Tapeats Dr. **Lat/Long:** 38.9924652 / -104.5786224

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
52	4025 R14050402	10.00	Slump: 5 1/2 Spec: 4 - 6	Result: 6.6 Spec.: 5 - 8	140.8	67	59

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
52 / 25601	7	04/27/2026	4520	Type 5
52 / 25602	28	05/18/2026	5440	Type 3
52 / 25603	28	05/18/2026	5760	Type 3
52 / 25604	28	05/18/2026	5590	Type 2

Average Strength (psi): 7 Day - 4520 psi, 28 Day - 5600 psi

05/22/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 53 **Sample #:** 7746 **Placement Date:** 04/21/2026 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter inlet tie ins at Lot 24 **Lat/Long:** 38.9923742 / -104.5774221

Notes: High slump passes County QC and Brett

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
53	1366 20805609	10.00	Slump: 7 Spec: 4 - 6	Result: 8 Spec.: 5 - 8	135.9	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
53 / 25670	7	04/28/2026	2890	Type 3
53 / 25671	28	05/19/2026	3590	Type 3
53 / 25672	56	06/16/2026	4100	Type 2

Average Strength (psi): 7 Day - 2890 psi, 28 Day - 3590 psi, 56 Day - 4100 psi

06/26/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 53 **Sample #:** 7746 **Placement Date:** 04/21/2026 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter inlet tie ins at Lot 24 **Lat/Long:** 38.9923742 / -104.5774221

Notes: High slump passes County QC and Brett

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
53	1366 20805609	10.00	Slump: 7 Spec: 4 - 6	Result: 8 Spec.: 5 - 8	135.9	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
53 / 25670	7	04/28/2026	2890	Type 3
53 / 25671	28	05/19/2026	3590	Type 3
53 / 25672	56	06/16/2026	4100	Type 2
53 / 25673	90	07/20/2026	4560	Type 3

Average Strength (psi): 7 Day - 2890 psi, 28 Day - 3590 psi, 56 Day - 4100 psi, 90 Day - 4560 psi

07/21/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 53 **Sample #:** 7746 **Placement Date:** 04/21/2026 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter inlet tie ins at Lot 24 **Lat/Long:** 38.9923742 / -104.5774221

Notes: High slump passes County QC and Brett

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
53	1366 20805609	10.00	Slump: 7 Spec: 4 - 6	Result: 8 Spec.: 5 - 8	135.9	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
53 / 25670	7	04/28/2026	2890	Type 3

Average Strength (psi): 7 Day - 2890 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 53 **Sample #:** 7746 **Placement Date:** 04/21/2026 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter inlet tie ins at Lot 24 **Lat/Long:** 38.9923742 / -104.5774221

Notes: High slump passes County QC and Brett

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
53	1366 20805609	10.00	Slump: 7 Spec: 4 - 6	Result: 8 Spec.: 5 - 8	135.9	74	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
53 / 25670	7	04/28/2026	2890	Type 3
53 / 25671	28	05/19/2026	3590	Type 3

Average Strength (psi): 7 Day - 2890 psi, 28 Day - 3590 psi

56 Day Breaks will be provided when available.

06/04/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 54 **Sample #:** 7767 **Placement Date:** 04/22/2026 **Technician:** Matt Spring **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 67

Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45878-4 **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the Southwest corner of Sunrise Ridge Dr. and Tapeats Dr. **Lat/Long:** 38.993822 / -104.5785988

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
54	4015 R14050477	10.00	Slump: 4 Spec: 3 - 6	Result: 5.4 Spec.: 5 - 8	143.6	70	67

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
54 / 25757	7	04/30/2026	5010	Type 2

Average Strength (psi): 7 Day - 5010 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 54 **Sample #:** 7767 **Placement Date:** 04/22/2026 **Technician:** Matt Spring **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 67

Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** ZCDOT45878-4 **Specified Strength (psi):** 4500

Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the Southwest corner of Sunrise Ridge Dr. and Tapeats Dr. **Lat/Long:** 38.993822 / -104.5785988

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
54	4015 R14050477	10.00	Slump: 4 Spec: 3 - 6	Result: 5.4 Spec.: 5 - 8	143.6	70	67

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
54 / 25757	7	04/30/2026	5010	Type 2
54 / 25790	28	05/20/2026	6120	Type 3
54 / 25791	28	05/20/2026	6200	Type 6
54 / 25792	28	05/20/2026	6000	Type 2

Average Strength (psi): 7 Day - 5010 psi, 28 Day - 6110 psi

06/04/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 55 **Sample #:** 7799 **Placement Date:** 04/24/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 53
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** CDOT45878-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the West side of Galeros Dr., located at STA 32+35 **Lat/Long:** 38.99388 / -104.577316

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
55	4030 R14050569	7.00	Slump: 5 3/4 Spec: 3 - 6	Result: 5.8 Spec.: 5 - 8	143.2	63	53

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
55 / 25916	7	05/01/2026	5220	Type 3

Average Strength (psi): 7 Day - 5220 psi

05/08/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 55 **Sample #:** 7799 **Placement Date:** 04/24/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 53
Contractor: Bannister Construction **Supplier:** SRM **Mix Design:** CDOT45878-4 **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** Curb and Gutter on the West side of Galeros Dr., located at STA 32+35 **Lat/Long:** 38.99388 / -104.577316

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
55	4030 R14050569	7.00	Slump: 5 3/4 Spec: 3 - 6	Result: 5.8 Spec.: 5 - 8	143.2	63	53

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
55 / 25916	7	05/01/2026	5220	Type 3
55 / 25917	28	05/22/2026	6580	Type 3
55 / 25918	28	05/22/2026	5740	Type 2
55 / 25919	28	05/22/2026	5640	Type 6

Average Strength (psi): 7 Day - 5220 psi, 28 Day - 5990 psi

06/04/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 56 **Sample #:** 7926 **Placement Date:** 05/11/2026 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 62

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Sidewalk **Location Details:** From the northwest corner of House Rock Drive and Sunrise Ridge Drive. **Lat/Long:** 38.9938739 / -104.576223

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
56	1359 20809391	5.00	Slump: 3 Spec: 3 - 5	Result: 5.5 Spec.: 5 - 8	142.0	69	62

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
56 / 26413	7	05/18/2026	4030	Type 3

Average Strength (psi): 7 Day - 4030 psi

05/22/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 56 **Sample #:** 7926 **Placement Date:** 05/11/2026 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 62

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Sidewalk **Location Details:** From the northwest corner of House Rock Drive and Sunrise Ridge Drive. **Lat/Long:** 38.9938739 / -104.576223

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
56	1359 20809391	5.00	Slump: 3 Spec: 3 - 5	Result: 5.5 Spec.: 5 - 8	142.0	69	62

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
56 / 26413	7	05/18/2026	4030	Type 3
56 / 26414	28	06/08/2026	5350	Type 3
56 / 26415	28	06/08/2026	5220	Type 2
56 / 26416	28	06/08/2026	5120	Type 2

Average Strength (psi): 7 Day - 4030 psi, 28 Day - 5230 psi

06/09/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 56 **Sample #:** 7926 **Placement Date:** 05/11/2026 **Technician:** Jayce Barnhart **Weather Conditions:** Sunny **Air Temp (°F):** 62

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Sidewalk **Location Details:** From the northwest corner of House Rock Drive and Sunrise Ridge Drive. **Lat/Long:** 38.9938739 / -104.576223

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
56	1359 20809391	5.00	Slump: 3 Spec: 3 - 5	Result: 5.5 Spec.: 5 - 8	142.0	69	62

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
56 / 26413	7	05/18/2026	4030	Type 3
56 / 26414	28	06/08/2026	5350	Type 3
56 / 26415	28	06/08/2026	5220	Type 2
56 / 26416	28	06/08/2026	5120	Type 2

Average Strength (psi): 7 Day - 4030 psi, 28 Day - 5230 psi

08/20/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 57 **Sample #:** 8007 **Placement Date:** 05/15/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 77
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 27 + 25, the east Pedestrian ramp on Shelter Creek Dr. **Lat/Long:** 38.9929736 / -104.5726002

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
57	1372 20811122	5.00	Slump: 4 1/2 Spec: 2 - 5	Result: 7.6 Spec.: 5 - 8	140.0	79	77

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
57 / 26623	7	05/22/2026	3520	Type 3

Average Strength (psi): 7 Day - 3520 psi

06/04/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 57 **Sample #:** 8007 **Placement Date:** 05/15/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 77
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 27 + 25, the east Pedestrian ramp on Shelter Creek Dr. **Lat/Long:** 38.9929736 / -104.5726002

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
57	1372 20811122	5.00	Slump: 4 1/2 Spec: 2 - 5	Result: 7.6 Spec.: 5 - 8	140.0	79	77

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
57 / 26623	7	05/22/2026	3520	Type 3
57 / 26624	28	06/12/2026	4480	Type 5
57 / 26625	28	06/12/2026	4430	Type 3

Average Strength (psi): 7 Day - 3520 psi, 28 Day - 4450 psi

56 Day Breaks will be provided when available.

06/12/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 57 **Sample #:** 8007 **Placement Date:** 05/15/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 77
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 27 + 25, the east Pedestrian ramp on Shelter Creek Dr. **Lat/Long:** 38.9929736 / -104.5726002

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
57	1372 20811122	5.00	Slump: 4 1/2 Spec: 2 - 5	Result: 7.6 Spec.: 5 - 8	140.0	79	77

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
57 / 26623	7	05/22/2026	3520	Type 3
57 / 26624	28	06/12/2026	4480	Type 5
57 / 26625	28	06/12/2026	4430	Type 3
57 / 26626	56	07/10/2026	4990	Type 2

Average Strength (psi): 7 Day - 3520 psi, 28 Day - 4450 psi, 56 Day - 5000 psi

07/10/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 58 **Sample #:** 8039 **Placement Date:** 05/19/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 37
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 50+35, North sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9942657 / -104.5819442

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
58	1364 20811479	10.00	Slump: 5 1/2 Spec: 2 - 5	Result: 5.8 Spec.: 5 - 8	140.4	69	37

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
58 / 26705	7	05/26/2026	4010	Type 5
58 / 26706	28	06/16/2026	4990	Type 3
58 / 26707	28	06/16/2026	4770	Type 5
58 / 26708	28	06/16/2026	5360	Type 3

Average Strength (psi): 7 Day - 4010 psi, 28 Day - 5040 psi

06/19/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 58 **Sample #:** 8039 **Placement Date:** 05/19/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 37
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 50 + 35, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9942657 / -104.5819442

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
58	1364 20811479	10.00	Slump: 5 1/2 Spec: 2 - 5	Result: 5.8 Spec.: 5 - 8	140.4	69	37

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
58 / 26705	7	05/26/2026	4010	Type 5

Average Strength (psi): 7 Day - 4010 psi

06/04/2026

Reviewed by: Dylan Gassmann, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 59 **Sample #:** 8297 **Placement Date:** 06/12/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 55
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 65 + 20, south sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9936137 / -104.5768466

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
59	1386 20817319	10.00	Slump: 1 3/4 Spec: 1 - 3	Result: 5.5 Spec.: 5 - 8	142.4	74	55

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
59 / 27610	7	06/19/2026	4170	Type 3

Average Strength (psi): 7 Day - 4170 psi

06/30/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 59 **Sample #:** 8297 **Placement Date:** 06/12/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 55
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 65 + 20, south sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9936137 / -104.5768466

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
59	1386 20817319	10.00	Slump: 1 3/4 Spec: 1 - 3	Result: 5.5 Spec.: 5 - 8	142.4	74	55

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
59 / 27610	7	06/19/2026	4170	Type 3
59 / 27611	28	07/10/2026	5310	Type 3
59 / 27612	28	07/10/2026	5260	Type 3
59 / 27613	28	07/10/2026	4570	Type 2

Average Strength (psi): 7 Day - 4170 psi, 28 Day - 5040 psi

07/10/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 60 **Sample #:** 8332 **Placement Date:** 06/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 62
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 26 + 25, south sidewalk on Horn Hill Dr. **Lat/Long:** 38.9923616 / -104.5778445

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
60	1374 20818007	10.00	Slump: 2 Spec: 1 - 4	Result: 5.4 Spec.: 5 - 8	142.4	73	62

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
60 / 27676	7	06/23/2026	4200	Type 3

Average Strength (psi): 7 Day - 4200 psi

06/30/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 60 **Sample #:** 8332 **Placement Date:** 06/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 62
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 26 + 25, south sidewalk on Horn Hill Dr. **Lat/Long:** 38.9923616 / -104.5778445

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
60	1374 20818007	10.00	Slump: 2 Spec: 1 - 4	Result: 5.4 Spec.: 5 - 8	142.4	73	62

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
60 / 27676	7	06/23/2026	4200	Type 3
60 / 27677	28	07/14/2026	5230	Type 3
60 / 27678	28	07/14/2026	5370	Type 2
60 / 27679	28	07/14/2026	5310	Type 2

Average Strength (psi): 7 Day - 4200 psi, 28 Day - 5300 psi

07/16/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 61 **Sample #:** 8342 **Placement Date:** 06/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny / Partly Cloudy **Air Temp (°F):** 79
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 50, west sidewalk on Redwall Dr. **Lat/Long:** 38.9929206 / -104.5817379

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
61	1379 20818160	10.00	Slump: 1 Spec: 1 - 3	Result: 5.6 Spec.: 5 - 8	143.2	79	79

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
61 / 27712	7	06/23/2026	4230	Type 3

Average Strength (psi): 7 Day - 4230 psi

06/30/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 61 **Sample #:** 8342 **Placement Date:** 06/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny / Partly Cloudy **Air Temp (°F):** 79
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 50, west sidewalk on Redwall Dr. **Lat/Long:** 38.9929206 / -104.5817379

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
61	1379 20818160	10.00	Slump: 1 Spec: 1 - 3	Result: 5.6 Spec.: 5 - 8	143.2	79	79

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
61 / 27712	7	06/23/2026	4230	Type 3
61 / 27713	29	07/14/2026	5710	Type 3
61 / 27714	29	07/14/2026	5380	Type 3
61 / 27715	29	07/14/2026	5180	Type 5

Average Strength (psi): 7 Day - 4230 psi, 29 Day - 5430 psi

07/16/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 62 **Sample #:** 8370 **Placement Date:** 06/18/2026 **Technician:** Kai Ordahl **Weather Conditions:** Sunny / Partly Cloudy **Air Temp (°F):** 54

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4000

Placement Location: Sidewalk **Location Details:** Sidewalk on westbound Sunrise Rdige Drive. Approx sta 57+00 on Sunrise Ridge Drive. **Lat/Long:** 38.9940763 / -104.5798681

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
62	1378 20818655	10.00	Slump: 1 1/4 Spec: - 4	Result: 6.2 Spec.: 5 - 8	140.0	80	54

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
62 / 27828	7	06/25/2026	4250	Type 2

Average Strength (psi): 7 Day - 4250 psi

06/30/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 62 **Sample #:** 8370 **Placement Date:** 06/18/2026 **Technician:** Kai Ordahl **Weather Conditions:** Sunny / Partly Cloudy **Air Temp (°F):** 54

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4000

Placement Location: Sidewalk **Location Details:** Sidewalk on westbound Sunrise Rdge Drive. Approx sta 57+00 on Sunrise Ridge Drive. **Lat/Long:** 38.9940763 / -104.5798681

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
62	1378 20818655	10.00	Slump: 1 1/4 Spec: - 4	Result: 6.2 Spec.: 5 - 8	140.0	80	54

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
62 / 27828	7	06/25/2026	4250	Type 2
62 / 27829	28	07/16/2026	5180	Type 2
62 / 27830	28	07/16/2026	5330	Type 5
62 / 27831	28	07/16/2026	5260	Type 3

Average Strength (psi): 7 Day - 4250 psi, 28 Day - 5260 psi

07/18/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 63 **Sample #:** 8385 **Placement Date:** 06/18/2026 **Technician:** Kai Ordahl **Weather Conditions:** Sunny / Partly Cloudy **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4000
Placement Location: Sidewalk **Location Details:** Sidewalk on Tapeats Drive at Station 14+00 **Lat/Long:** 38.9936496 / -104.5783494

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
63	1387 20818887	10.00	Slump: 2 1/4 Spec: - 4	Result: 5.9 Spec.: 5 - 8	140.0	80	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
63 / 27782	7	06/25/2026	4090	Type 2

Average Strength (psi): 7 Day - 4090 psi

06/30/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 63 **Sample #:** 8385 **Placement Date:** 06/18/2026 **Technician:** Kai Ordahl **Weather Conditions:** Sunny / Partly Cloudy **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4000
Placement Location: Sidewalk **Location Details:** Sidewalk on Tapeats Drive at Station 14+00 **Lat/Long:** 38.9936496 / -104.5783494

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
63	1387 20818887	10.00	Slump: 2 1/4 Spec: - 4	Result: 5.9 Spec.: 5 - 8	140.0	80	69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
63 / 27782	7	06/25/2026	4090	Type 2
63 / 27783	28	07/16/2026	5080	Type 3
63 / 27784	28	07/16/2026	5050	Type 2
63 / 27785	28	07/16/2026	5130	Type 2

Average Strength (psi): 7 Day - 4090 psi, 28 Day - 5090 psi

07/18/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 64 **Sample #:** 8433 **Placement Date:** 06/23/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 76
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 28+00, West sidewalk on Galeros Dr. **Lat/Long:** 38.9926199 / -104.5774147

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
64	1297 20819597	10.00	Slump: 2 1/4 Spec: 1 - 3	Result: 8 Spec.: 5 - 8	137.2	79	76

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
64 / 28018	7	06/30/2026	3630	Type 2

Average Strength (psi): 7 Day - 3630 psi

07/01/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 64 **Sample #:** 8433 **Placement Date:** 06/23/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 76
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 28+00, West sidewalk on Galeros Dr. **Lat/Long:** 38.9926199 / -104.5774147

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
64	1297 20819597	10.00	Slump: 2 1/4 Spec: 1 - 3	Result: 8 Spec.: 5 - 8	137.2	79	76

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
64 / 28018	7	06/30/2026	3630	Type 2
64 / 28019	28	07/21/2026	4120	Type 3

Average Strength (psi): 7 Day - 3630 psi, 28 Day - 4120 psi

56 Day Breaks will be provided when available.

07/22/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 64 **Sample #:** 8433 **Placement Date:** 06/23/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 76
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 28+00, West sidewalk on Galeros Dr. **Lat/Long:** 38.9926199 / -104.5774147

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
64	1297 20819597	10.00	Slump: 2 1/4 Spec: 1 - 3	Result: 8 Spec.: 5 - 8	137.2	79	76

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
64 / 28018	7	06/30/2026	3630	Type 2
64 / 28019	28	07/21/2026	4120	Type 3
64 / 28020	56	08/18/2026	4680	Type 3
64 / 28021	56	08/18/2026	4790	Type 3

Average Strength (psi): 7 Day - 3630 psi, 28 Day - 4120 psi, 56 Day - 4740 psi

08/19/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 65 **Sample #:** 8440 **Placement Date:** 06/23/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 76
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 11+15, East sidewalk on Bright Angel Dr. **Lat/Long:** 38.992809 / -104.5795097

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
65	1187 20819704	10.00	Slump: 1 3/4 Spec: 1 - 3	Result: 5.3 Spec.: 5 - 8	142.8	81	76

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
65 / 28022	7	06/30/2026	4440	Type 3

Average Strength (psi): 7 Day - 4440 psi

07/01/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 65 **Sample #:** 8440 **Placement Date:** 06/23/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 76
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 11+15, East sidewalk on Bright Angel Dr. **Lat/Long:** 38.992809 / -104.5795097

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
65	1187 20819704	10.00	Slump: 1 3/4 Spec: 1 - 3	Result: 5.3 Spec.: 5 - 8	142.8	81	76

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
65 / 28022	7	06/30/2026	4440	Type 3
65 / 28023	28	07/21/2026	5790	Type 3
65 / 28024	28	07/21/2026	4680	Type 5
65 / 28025	28	07/21/2026	5250	Type 6

Average Strength (psi): 7 Day - 4440 psi, 28 Day - 5240 psi

07/22/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 66 **Sample #:** 8466 **Placement Date:** 06/25/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 60
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 60 + 00, south sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9937821 / -104.5787586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
66	1384 20820183	10.00	Slump: 1 1/4 Spec: 1 - 3 1/2	Result: 5.8 Spec.: 5 - 8	140.0	79	60

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
66 / 28136	7	07/02/2026	3940	Type 2

Average Strength (psi): 7 Day - 3940 psi

07/07/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 66 **Sample #:** 8466 **Placement Date:** 06/25/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 60
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 60 + 00, south sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9937821 / -104.5787586

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
66	1384 20820183	10.00	Slump: 1 1/4 Spec: 1 - 3 1/2	Result: 5.8 Spec.: 5 - 8	140.0	79	60

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
66 / 28136	7	07/02/2026	3940	Type 2
66 / 28137	28	07/23/2026	4860	Type 2
66 / 28138	28	07/23/2026	4700	Type 2
66 / 28139	28	07/23/2026	4790	Type 2

Average Strength (psi): 7 Day - 3940 psi, 28 Day - 4780 psi

07/27/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 67 **Sample #:** 8471 **Placement Date:** 06/25/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy / Rain **Air Temp (°F):** 64
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 57 + 00, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9938663 / -104.5797147

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
67	1384 208202	110.00	Slump: 1 Spec: 1 - 3	Result: 5.4 Spec.: 5 - 8	142.0	81	64

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
67 / 28152	7	07/02/2026	4010	Type 2

Average Strength (psi): 7 Day - 4010 psi

07/07/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 67 **Sample #:** 8471 **Placement Date:** 06/25/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy / Rain **Air Temp (°F):** 64
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 57 + 00, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9938663 / -104.5797147

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
67	1384 208202	110.00	Slump: 1 Spec: 1 - 3	Result: 5.4 Spec.: 5 - 8	142.0	81	64

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
67 / 28152	7	07/02/2026	4010	Type 2
67 / 28153	28	07/23/2026	5570	Type 3
67 / 28154	28	07/23/2026	4850	Type 2
67 / 28155	28	07/23/2026	5640	Type 2

Average Strength (psi): 7 Day - 4010 psi, 28 Day - 5350 psi

07/23/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 68 **Sample #:** 8491 **Placement Date:** 06/29/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 73
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 00, west sidewalk on Bright Angel Dr. **Lat/Long:** 38.9936161 / -104.5795029

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
68	1383 20820722	10.00	Slump: 1 1/4 Spec: 1 - 3 1/2	Result: 5.6 Spec.: 5 - 8	141.6	79	73

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
68 / 28245	7	07/06/2026	4150	Type 2

Average Strength (psi): 7 Day - 4150 psi

07/07/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 68 **Sample #:** 8491 **Placement Date:** 06/29/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 73
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 00, west sidewalk on Bright Angel Dr. **Lat/Long:** 38.9936161 / -104.5795029

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
68	1383 20820722	10.00	Slump: 1 1/4 Spec: 1 - 3 1/2	Result: 5.6 Spec.: 5 - 8	141.6	79	73

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
68 / 28245	7	07/06/2026	4150	Type 2
68 / 28246	28	07/27/2026	5200	Type 3
68 / 28247	28	07/27/2026	5460	Type 3
68 / 28248	28	07/27/2026	5350	Type 5

Average Strength (psi): 7 Day - 4150 psi, 28 Day - 5340 psi

07/27/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 69 **Sample #:** 8512 **Placement Date:** 06/30/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 65 + 40, south sidewalk of Sunrise Ridge Dr. **Lat/Long:** 38.9936017 / -104.5767215

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
69	1379 208210076	7.50	Slump: 4 3/4 Spec: 3 - 7	Result: 7.2 Spec.: 5 - 8	138.8		69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
69 / 28283	7	07/07/2026	3290	Type 3

Average Strength (psi): 7 Day - 3290 psi

07/07/2026

Reviewed by: Austin Nossokoff, PE



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 69 **Sample #:** 8512 **Placement Date:** 06/30/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 69
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 65 + 40, south sidewalk of Sunrise Ridge Dr. **Lat/Long:** 38.9936017 / -104.5767215

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
69	1379 208210076	7.50	Slump: 4 3/4 Spec: 3 - 7	Result: 7.2 Spec.: 5 - 8	138.8		69

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
69 / 28283	7	07/07/2026	3290	Type 3
69 / 28284	28	07/28/2026	4100	Type 2

Average Strength (psi): 7 Day - 3290 psi, 28 Day - 4100 psi

56 Day Breaks will be provided when available.

07/30/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 70 **Sample #:** 8535 **Placement Date:** 07/01/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 73
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 51 + 25, south sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.994076 / -104.5816651

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
70	1379 20831467	7.50	Slump: 4 Spec: 3 - 7	Result: 6.8 Spec.: 5 - 8	137.6	77	73

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
70 / 28400	7	07/08/2026	3460	Type 3
70 / 28401	28	07/29/2026	4360	Type 3

Average Strength (psi): 7 Day - 3460 psi, 28 Day - 4360 psi

56 Day Breaks will be provided when available.

07/30/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 70 **Sample #:** 8535 **Placement Date:** 07/01/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 73
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 51 + 25, south sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.994076 / -104.5816651

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
70	1379 20831467	7.50	Slump: 4 Spec: 3 - 7	Result: 6.8 Spec.: 5 - 8	137.6	77	73

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
70 / 28400	7	07/08/2026	3460	Type 3
70 / 28401	28	07/29/2026	4360	Type 3
70 / 28402	56	08/26/2026	4620	Type 2
70 / 28403	56	08/26/2026	4480	Type 2

Average Strength (psi): 7 Day - 3460 psi, 28 Day - 4360 psi, 56 Day - 4550 psi

56 Day Breaks will be provided when available.

08/26/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 71 **Sample #:** 8558 **Placement Date:** 07/02/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 00, east sidewalk on Redwall Dr. **Lat/Long:** 38.9929942 / -104.5815927

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
71	1378 20821855	7.50	Slump: 4 1/4 Spec: 2 - 6	Result: 6.6 Spec.: 5 - 8	136.8	76	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
71 / 28338	7	07/09/2026	3490	Type 2

Average Strength (psi): 7 Day - 3490 psi

07/10/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 71 **Sample #:** 8558 **Placement Date:** 07/02/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 00, east sidewalk on Redwall Dr. **Lat/Long:** 38.9929942 / -104.5815927

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
71	1378 20821855	7.50	Slump: 4 1/4 Spec: 2 - 6	Result: 6.6 Spec.: 5 - 8	136.8	76	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
71 / 28338	7	07/09/2026	3490	Type 2
71 / 28339	28	07/30/2026	4290	Type 3

Average Strength (psi): 7 Day - 3490 psi, 28 Day - 4290 psi

56 Day Breaks will be provided when available.

08/01/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 71 **Sample #:** 8558 **Placement Date:** 07/02/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 66
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 00, east sidewalk on Redwall Dr. **Lat/Long:** 38.9929942 / -104.5815927

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
71	1378 20821855	7.50	Slump: 4 1/4 Spec: 2 - 6	Result: 6.6 Spec.: 5 - 8	136.8	76	66

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
71 / 28338	7	07/09/2026	3490	Type 2
71 / 28339	28	07/30/2026	4290	Type 3
71 / 28340	56	08/27/2026	4510	Type 2
71 / 28341	56	08/27/2026	4860	Type 2

Average Strength (psi): 7 Day - 3490 psi, 28 Day - 4290 psi, 56 Day - 4690 psi

08/30/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 72 **Sample #:** 8589 **Placement Date:** 07/07/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 79
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** Sidewalk on the North side of Sunrise Ridge Dr, located at STA 65 + 35 **Lat/Long:** 38.993719 / -104.5767805

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
72	1383 20822447	7.50	Slump: 4 1/2 Spec: 2 - 6	Result: 7 Spec.: 5 - 8	138.0	79	79

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
72 / 28573	7	07/14/2026	2930	Type 2

Average Strength (psi): 7 Day - 2930 psi

07/16/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 72 **Sample #:** 8589 **Placement Date:** 07/07/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 79

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Sidewalk **Location Details:** Sidewalk on the North side of Sunrise Ridge Dr, located at STA 65 + 35 **Lat/Long:** 38.993719 / -104.5767805

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
72	1383 20822447	7.50	Slump: 4 1/2 Spec: 2 - 6	Result: 7 Spec.: 5 - 8	138.0	79	79

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
72 / 28573	7	07/14/2026	2930	Type 2
72 / 28574	28	08/04/2026	4520	Type 3
72 / 28575	28	08/04/2026	4650	Type 3
72 / 28576	28	08/04/2026	4610	Type 2

Average Strength (psi): 7 Day - 2930 psi, 28 Day - 4590 psi

08/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 73 **Sample #:** 8610 **Placement Date:** 07/08/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 82

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Sidewalk **Location Details:** Sidewalk on the South side of Horn Hill Dr., located at STA 24 + 60 **Lat/Long:** 38.9923289 / -104.578342

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
73	1379 20822783	7.50	Slump: 5 1/4 Spec: 2 - 6	Result: 7.8 Spec.: 5 - 8	136.4	78	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
73 / 28522	7	07/15/2026	3090	Type 2

Average Strength (psi): 7 Day - 3090 psi

07/16/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 73 **Sample #:** 8610 **Placement Date:** 07/08/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 82

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Sidewalk **Location Details:** Sidewalk on the South side of Horn Hill Dr., located at STA 24 + 60 **Lat/Long:** 38.9923289 / -104.578342

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
73	1379 20822783	7.50	Slump: 5 1/4 Spec: 2 - 6	Result: 7.8 Spec.: 5 - 8	136.4	78	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
73 / 28522	7	07/15/2026	3090	Type 2
73 / 28523	28	08/05/2026	3620	Type 3

Average Strength (psi): 7 Day - 3090 psi, 28 Day - 3620 psi

56 Day Breaks will be provided when available.

08/06/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 73 **Sample #:** 8610 **Placement Date:** 07/08/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 82

Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500

Placement Location: Sidewalk **Location Details:** Sidewalk on the South side of Horn Hill Dr., located at STA 24 + 60 **Lat/Long:** 38.9923289 / -104.578342

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
73	1379 20822783	7.50	Slump: 5 1/4 Spec: 2 - 6	Result: 7.8 Spec.: 5 - 8	136.4	78	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
73 / 28522	7	07/15/2026	3090	Type 2
73 / 28523	28	08/05/2026	3620	Type 3
73 / 28524	56	09/02/2026	4350	Type 3

Average Strength (psi): 7 Day - 3090 psi, 28 Day - 3620 psi, 56 Day - 4350 psi

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 74 **Sample #:** 8625 **Placement Date:** 07/09/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 21 + 50, north sidewalk on Horn Hill Dr. **Lat/Long:** 38.9925397 / -104.5793908

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
74	1386 20823101	7.50	Slump: 2 1/2 Spec: 2 - 6	Result: 5.5 Spec.: 5 - 8	140.4	79	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
74 / 28675	7	07/16/2026	4020	Type 3

Average Strength (psi): 7 Day - 4020 psi

07/18/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 74 **Sample #:** 8625 **Placement Date:** 07/09/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 21 + 50, north sidewalk on Horn Hill Dr. **Lat/Long:** 38.9925397 / -104.5793908

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
74	1386 20823101	7.50	Slump: 2 1/2 Spec: 2 - 6	Result: 5.5 Spec.: 5 - 8	140.4	79	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
74 / 28675	7	07/16/2026	4020	Type 3
74 / 28676	28	08/06/2026	5340	Type 3
74 / 28677	28	08/06/2026	4810	Type 2
74 / 28678	28	08/06/2026	5090	Type 2

Average Strength (psi): 7 Day - 4020 psi, 28 Day - 5080 psi

08/06/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 75 **Sample #:** 8630 **Placement Date:** 07/09/2026 **Technician:** Rodney Fannin **Weather Conditions:** Rain **Air Temp (°F):** 82
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 11 + 15, east sidewalk on Bright Angel Dr. **Lat/Long:** 38.9928011 / -104.5794341

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
75	1378 20823150	7.50	Slump: 4 Spec: 2 - 6	Result: 5.5 Spec.: 5 - 8	140.0	81	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
75 / 28679	7	07/16/2026	3760	Type 3

Average Strength (psi): 7 Day - 3760 psi

07/18/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 75 **Sample #:** 8630 **Placement Date:** 07/09/2026 **Technician:** Rodney Fannin **Weather Conditions:** Rain **Air Temp (°F):** 82
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 11 + 15, east sidewalk on Bright Angel Dr. **Lat/Long:** 38.9928011 / -104.5794341

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
75	1378 20823150	7.50	Slump: 4 Spec: 2 - 6	Result: 5.5 Spec.: 5 - 8	140.0	81	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
75 / 28679	7	07/16/2026	3760	Type 3
75 / 28680	28	08/06/2026	4750	Type 2
75 / 28681	28	08/06/2026	4860	Type 3
75 / 28682	28	08/06/2026	4890	Type 3

Average Strength (psi): 7 Day - 3760 psi, 28 Day - 4840 psi

08/06/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 76 **Sample #:** 8661 **Placement Date:** 07/13/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy / Windy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 10 + 40, east sidewalk on Tapeats Dr. **Lat/Long:** 38.9925258 / -104.578458

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
76	1364 20823722	10.00	Slump: 4 1/4 Spec: 2 - 6	Result: 7.8 Spec.: 5 - 8	136.4	83	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
76 / 28752	7	07/20/2026	3510	Type 3

Average Strength (psi): 7 Day - 3510 psi

07/21/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 76 **Sample #:** 8661 **Placement Date:** 07/13/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy / Windy **Air Temp (°F):** 80
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 10 + 40, east sidewalk on Tapeats Dr. **Lat/Long:** 38.9925258 / -104.578458

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
76	1364 20823722	10.00	Slump: 4 1/4 Spec: 2 - 6	Result: 7.8 Spec.: 5 - 8	136.4	83	80

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
76 / 28752	7	07/20/2026	3510	Type 3
76 / 28729	28	08/10/2026	4320	Type 2

Average Strength (psi): 7 Day - 3510 psi, 28 Day - 4320 psi

08/10/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 77 **Sample #:** 8679 **Placement Date:** 07/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 24 + 25, north pedestrian ramp on Horn Hill Dr. **Lat/Long:** 38.9924508 / -104.5784436

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
77	1382 20823972	10.00	Slump: 6 Spec: 4 - 6	Result: 7.6 Spec.: 5 - 8	138.8	84	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
77 / 28813	7	07/21/2026	4070	Type 2

Average Strength (psi): 7 Day - 4070 psi

07/22/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 77 **Sample #:** 8679 **Placement Date:** 07/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 24 + 25, north pedestrian ramp on Horn Hill Dr. **Lat/Long:** 38.9924508 / -104.5784436

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
77	1382 20823972	10.00	Slump: 6 Spec: 4 - 6	Result: 7.6 Spec.: 5 - 8	138.8	84	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
77 / 28813	7	07/21/2026	4070	Type 2
77 / 28814	28	08/11/2026	4620	Type 3
77 / 28815	28	08/11/2026	4540	Type 2
77 / 28816	28	08/11/2026	4620	Type 2

Average Strength (psi): 7 Day - 4070 psi, 28 Day - 4590 psi

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 78 **Sample #:** 8680 **Placement Date:** 07/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy / Windy **Air Temp (°F):** 82
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 21 + 50, south sidewalk on Horn Hill Dr. **Lat/Long:** 38.9924223 / -104.5793936

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
78	1382 20824012	5.00	Slump: 5 1/2 Spec: 2 - 6	Result: 7.6 Spec.: 5 - 8	138.8	79	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
78 / 28817	7	07/21/2026	3380	Type 5

Average Strength (psi): 7 Day - 3380 psi

07/22/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 78 **Sample #:** 8680 **Placement Date:** 07/14/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy / Windy **Air Temp (°F):** 82
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 21 + 50, south sidewalk on Horn Hill Dr. **Lat/Long:** 38.9924223 / -104.5793936

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
78	1382 20824012	5.00	Slump: 5 1/2 Spec: 2 - 6	Result: 7.6 Spec.: 5 - 8	138.8	79	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
78 / 28817	7	07/21/2026	3380	Type 5
78 / 28818	28	08/11/2026	4260	Type 2

Average Strength (psi): 7 Day - 3380 psi, 28 Day - 4260 psi

56 Day Breaks will be provided when available.

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 79 **Sample #:** 8694 **Placement Date:** 07/15/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 71
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 21 + 10, south sidewalk on Horn Hill Dr. **Lat/Long:** 38.9924777 / -104.5795784

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
79	1368 20824216	7.50	Slump: 4 1/4 Spec: 2 - 6	Result: 5.8 Spec.: 5 - 8	140.8	81	71

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
79 / 28843	7	07/22/2026	3830	Type 3

Average Strength (psi): 7 Day - 3830 psi

07/22/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 79 **Sample #:** 8694 **Placement Date:** 07/15/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 71
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 21 + 10, south sidewalk on Horn Hill Dr. **Lat/Long:** 38.9924777 / -104.5795784

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
79	1368 20824216	7.50	Slump: 4 1/4 Spec: 2 - 6	Result: 5.8 Spec.: 5 - 8	140.8	81	71

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
79 / 28843	7	07/22/2026	3830	Type 3
79 / 28844	28	08/12/2026	4820	Type 3
79 / 28845	28	08/12/2026	4730	Type 3
79 / 28846	28	08/12/2026	4650	Type 2

Average Strength (psi): 7 Day - 3830 psi, 28 Day - 4730 psi

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 80 **Sample #:** 8714 **Placement Date:** 07/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 74
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 54 + 00, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9941045 / -104.5806859

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
80	1379 20824542		Slump: 4 1/4 Spec: 2 - 6	Result: 5.4 Spec.: 5 - 8	141.2	86	74

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
80 / 28970	7	07/23/2026	3740	Type 5

Average Strength (psi): 7 Day - 3740 psi

07/23/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 80 **Sample #:** 8714 **Placement Date:** 07/16/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 74
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 54 + 00, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9941045 / -104.5806859

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
80	1379 20824542		Slump: 4 1/4 Spec: 2 - 6	Result: 5.4 Spec.: 5 - 8	141.2	86	74

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
80 / 28970	7	07/23/2026	3740	Type 5
80 / 28971	28	08/13/2026	5010	Type 2
80 / 28972	28	08/13/2026	4950	Type 3
80 / 28973	28	08/13/2026	4860	Type 3

Average Strength (psi): 7 Day - 3740 psi, 28 Day - 4940 psi

08/14/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 81 **Sample #:** 8736 **Placement Date:** 07/17/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** STA 78 + 00, south Curb/Gutter on Sunrise Ridge Dr. **Lat/Long:** 38.9947844 / -104.5726498

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
81	1376 20824916	7.50	Slump: 4 Spec: 2 - 6	Result: 5.2 Spec.: 5 - 8	141.2	81	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
81 / 28986	7	07/24/2026	3460	Type 3

Average Strength (psi): 7 Day - 3460 psi

07/27/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 81 **Sample #:** 8736 **Placement Date:** 07/17/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 78
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Curb & Gutter **Location Details:** STA 78 + 00, south Curb/Gutter on Sunrise Ridge Dr. **Lat/Long:** 38.9947844 / -104.5726498

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
81	1376 20824916	7.50	Slump: 4 Spec: 2 - 6	Result: 5.2 Spec.: 5 - 8	141.2	81	78

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
81 / 28986	7	07/24/2026	3460	Type 3
81 / 28987	28	08/14/2026	4710	Type 2
81 / 28988	28	08/14/2026	4390	Type 2

Average Strength (psi): 7 Day - 3460 psi, 28 Day - 4550 psi

56 Day Breaks will be provided when available.

08/14/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 82 **Sample #:** 8748 **Placement Date:** 07/20/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 86
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 45 + 00, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9941234 / -104.5804009

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
82	1380 20825262	7.50	Slump: 4 1/2 Spec: 2 - 6	Result: 5.8 Spec.: 5 - 8	140.4	82	86

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
82 / 28993	7	07/27/2026	4010	Type 2

Average Strength (psi): 7 Day - 4010 psi

07/27/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 82 **Sample #:** 8748 **Placement Date:** 07/20/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 86
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 45 + 00, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9941234 / -104.5804009

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
82	1380 20825262	7.50	Slump: 4 1/2 Spec: 2 - 6	Result: 5.8 Spec.: 5 - 8	140.4	82	86

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
82 / 28993	7	07/27/2026	4010	Type 2
82 / 28994	28	08/17/2026	5220	Type 2
82 / 28995	28	08/17/2026	5150	Type 2
82 / 28996	28	08/17/2026	5140	Type 2

Average Strength (psi): 7 Day - 4010 psi, 28 Day - 5170 psi

08/17/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 83 **Sample #:** 8763 **Placement Date:** 07/21/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny / Windy **Air Temp (°F):** 73
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 57 + 60, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9939955 / -104.5795118

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
83	1373 20825541	5.00	Slump: 4 1/4 Spec: 2 - 6	Result: 7.2 Spec.: 5 - 8	138.4	86	73

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
83 / 29029	7	07/28/2026	2880	Type 2

Average Strength (psi): 7 Day - 2880 psi

07/30/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 83 **Sample #:** 8763 **Placement Date:** 07/21/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny / Windy **Air Temp (°F):** 73
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 57 + 60, north sidewalk on Sunrise Ridge Dr. **Lat/Long:** 38.9939955 / -104.5795118

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
83	1373 20825541	5.00	Slump: 4 1/4 Spec: 2 - 6	Result: 7.2 Spec.: 5 - 8	138.4	86	73

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
83 / 29029	7	07/28/2026	2880	Type 2
83 / 29030	28	08/18/2026	3960	Type 2

Average Strength (psi): 7 Day - 2880 psi, 28 Day - 3960 psi

56 Day Breaks will be provided when available.

08/19/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 84 **Sample #:** 8789 **Placement Date:** 07/23/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 72
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 21 +25, north pedestrian ramp on Horn Hill Dr. **Lat/Long:** 38.9926152 / -104.5795186

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
84	1368 20826195	5.00	Slump: 4 1/4 Spec: 2 - 6	Result: 6.6 Spec.: 5 - 8	139.2	86	72

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
84 / 29147	7	07/30/2026	3660	Type 6

Average Strength (psi): 7 Day - 3660 psi

08/01/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 85 **Sample #:** 8799 **Placement Date:** 07/24/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 81
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 51 + 60, south pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.994153 / -104.581641

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
85	1362 20826419	6.00	Slump: 5 3/4 Spec: 2 - 6	Result: 7.6 Spec.: 5 - 8	136.4	84	81

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
85 / 29191	7	07/31/2026	2890	Type 2

Average Strength (psi): 7 Day - 2890 psi

08/01/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 85 **Sample #:** 8799 **Placement Date:** 07/24/2026 **Technician:** Rodney Fannin **Weather Conditions:** Sunny **Air Temp (°F):** 81
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 51 + 60, south pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.994153 / -104.581641

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
85	1362 20826419	6.00	Slump: 5 3/4 Spec: 2 - 6	Result: 7.6 Spec.: 5 - 8	136.4	84	81

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
85 / 29191	7	07/31/2026	2890	Type 2
85 / 29192	28	08/21/2026	3780	Type 3

Average Strength (psi): 7 Day - 2890 psi, 28 Day - 3780 psi

56 Day Breaks will be provided when available.

08/26/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 86 **Sample #:** 8816 **Placement Date:** 07/27/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy / Windy **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 10 + 30, east pedestrian ramp on Redwall Dr. **Lat/Long:** 38.9940399 / -104.5814244

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
86	1359 20826756	5.00	Slump: 5 1/2 Spec: 2 - 6	Result: 6.6 Spec.: 5 - 8	138.8	83	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
86 / 29221	7	08/03/2026	3630	Type 2

Average Strength (psi): 7 Day - 3630 psi

08/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 86 **Sample #:** 8816 **Placement Date:** 07/27/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy / Windy **Air Temp (°F):** 75
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 10 + 30, east pedestrian ramp on Redwall Dr. **Lat/Long:** 38.9940399 / -104.5814244

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
86	1359 20826756	5.00	Slump: 5 1/2 Spec: 2 - 6	Result: 6.6 Spec.: 5 - 8	138.8	83	75

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
86 / 29221	7	08/03/2026	3630	Type 2
86 / 29222	28	08/24/2026	4430	Type 3

Average Strength (psi): 7 Day - 3630 psi, 28 Day - 4440 psi

56 Day Breaks will be provided when available.

08/26/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 87 **Sample #:** 8826 **Placement Date:** 07/28/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 77
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 60 + 75, north pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.9938992 / -104.5782792

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
87	1373 20827031	5.00	Slump: 3 3/4 Spec: 2 - 6	Result: 7.2 Spec.: 5 - 8	138.4	86	77

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
87 / 29201	7	08/04/2026	3730	Type 2

Average Strength (psi): 7 Day - 3730 psi

08/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 87 **Sample #:** 8826 **Placement Date:** 07/28/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 77
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C2C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 60 + 75, north pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.9938992 / -104.5782792

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
87	1373 20827031	5.00	Slump: 3 3/4 Spec: 2 - 6	Result: 7.2 Spec.: 5 - 8	138.4	86	77

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
87 / 29201	7	08/04/2026	3730	Type 2
87 / 29202	28	08/25/2026	4770	Type 5
87 / 29203	28	08/25/2026	4750	Type 2
87 / 29204	28	08/25/2026	4650	Type 2

Average Strength (psi): 7 Day - 3730 psi, 28 Day - 4720 psi

08/26/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 88 **Sample #:** 8846 **Placement Date:** 07/29/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 79
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 80, east pedestrian ramp on Bright Angel Dr. **Lat/Long:** 38.9938178 / -104.5794967

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
88	1376 20827315	5.00	Slump: 4 1/2 Spec: 2 - 6	Result: 7.4 Spec.: 5 - 8	138.4	82	79

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
88 / 29259	7	08/05/2026	3370	Type 2

Average Strength (psi): 7 Day - 3370 psi

08/06/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 88 **Sample #:** 8846 **Placement Date:** 07/29/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 79
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 14 + 80, east pedestrian ramp on Bright Angel Dr. **Lat/Long:** 38.9938178 / -104.5794967

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
88	1376 20827315	5.00	Slump: 4 1/2 Spec: 2 - 6	Result: 7.4 Spec.: 5 - 8	138.4	82	79

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
88 / 29259	7	08/05/2026	3370	Type 2
88 / 29260	28	08/26/2026	4180	Type 2

Average Strength (psi): 7 Day - 3370 psi, 28 Day - 4180 psi

56 Day Breaks will be provided when available.

08/26/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 89 **Sample #:** 8864 **Placement Date:** 07/30/2026 **Technician:** Rodney Fannin **Weather Conditions:** Partly Cloudy **Air Temp (°F):** 82
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 58 + 25, south pedestrian ramp on Sunrise Ridge Dr. **Lat/Long:** 38.9938416 / -104.579267

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
89	1383 20827597	5.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.8 Spec.: 5 - 8	136.8	84	82

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
89 / 29369	7	08/06/2026	3790	Type 3

Average Strength (psi): 7 Day - 3790 psi

08/06/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 90 **Sample #:** 8888 **Placement Date:** 08/03/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 87
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 10 + 60, west pedestrian ramp on Temple Butte Dr. **Lat/Long:** 38.9927403 / -104.5807024

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
90	1387 20828200	5.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.6 Spec.: 5 - 8	137.6	89	87

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
90 / 29430	7	08/10/2026	3260	Type 3

Average Strength (psi): 7 Day - 3260 psi

08/10/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 90 **Sample #:** 8888 **Placement Date:** 08/03/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy **Air Temp (°F):** 87
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 10 + 60, west pedestrian ramp on Temple Butte Dr. **Lat/Long:** 38.9927403 / -104.5807024

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
90	1387 20828200	5.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.6 Spec.: 5 - 8	137.6	89	87

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
90 / 29430	7	08/10/2026	3260	Type 3
90 / 29431	28	08/31/2026	4240	Type 3

Average Strength (psi): 7 Day - 3260 psi, 28 Day - 4240 psi

56 Day Breaks will be provided when available.

09/04/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 91 **Sample #:** 8902 **Placement Date:** 08/04/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy / Windy **Air Temp (°F):** 64
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 18 + 25, south pedestrian ramp on Horn Hill Dr. **Lat/Long:** 38.9925734 / -104.5804754

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
91	1383 20828435	7.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.8 Spec.: 5 - 8	136.4	76	64

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
91 / 29493	7	08/11/2026	3400	Type 3

Average Strength (psi): 7 Day - 3400 psi

08/12/2026

Reviewed by: Austin Nossokoff



Entech Engineering
505 Elkton Dr.
Colorado Springs, CO 80907
Phone: 719-531-5599

Concrete Test

Client:

Tech Contractors
3575 Kenyon Street, Suite 200
San Diego, CA 92110

Project:

250235
Meridian Ranch - Rolling Hills Ranch North F1
Rolling Hills Ranch North F1
Peyton, CO

Set #: 91 **Sample #:** 8902 **Placement Date:** 08/04/2026 **Technician:** Rodney Fannin **Weather Conditions:** Cloudy / Windy **Air Temp (°F):** 64
Contractor: Bannister Construction **Supplier:** Burnco **Mix Design:** 45E5C1C4C **Specified Strength (psi):** 4500
Placement Location: Sidewalk **Location Details:** STA 18 + 25, south pedestrian ramp on Horn Hill Dr. **Lat/Long:** 38.9925734 / -104.5804754

PLACEMENT DATA

Set #	Truck # Ticket #	Load Vol (yd³)	Slump (in)	Air Content (%)	Unit Weight (lb/ft³)	Concrete Temp (°F)	Air Temp (°F)
91	1383 20828435	7.00	Slump: 4 1/2 Spec: 2 1/2 - 6 1/2	Result: 7.8 Spec.: 5 - 8	136.4	76	64

STRENGTH DATA

Set / Test	Age (days)	Test Date	Strength (psi)	Fracture Pattern
91 / 29493	7	08/11/2026	3400	Type 3
91 / 29494	28	09/01/2026	4300	Type 5

Average Strength (psi): 7 Day - 3400 psi, 28 Day - 4300 psi

56 Day Breaks will be provided when available.

09/04/2026

Reviewed by: Austin Nossokoff